

#### **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

INV No. AC2003567

INV Date 29/04/2020

Reference CC3/CTI19010165/Jea3n2

Code CT

# PROFESSIONAL SERVICE FEE

Vehicle No. SG 5808S

Insured Veh. XD 9274L

Claim No. SNM19D202411C02/4

Policy No. DMCVSN1903281900

Accident Date 27/05/2019

Inspection Date 07/06/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile						
CHIN	CHINA TAIPING INSURANCE (S) PTE LTD Ref: CC3/CTI19010165/Jea3n2						
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 29-04-2020 Code: CTI					
1.	1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	XD 9274L	Veh. Inspected	SG 5808S			
	Policy No.	DMCVSN1903281900	Coverage (\$)	0.00			
	Claim No.	SNM19D202411C02/4	Excess (\$)	0.00			
	Assign From		Assign Date	07/06/2019			
2.		Vehicle Partic	culars & Condition				
	Make & Model	MAN A95	c.c	10518			
	Engine No.	HIDDEN	Year of Reg.	2017			
	Chassis No.	WMAA95ZZ3G7003455	Colour	GREEN			
	Odometer	153966	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.		Condition	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm			
	L/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm			
	R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	7/7 mm			
	L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	7/7 mm			
4.	1	•	on of Damages				
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	BODY.				
	DAMAGES SEE D	ETAILS.					
5.		General	Information				
	Accident Date	27/05/2019	Inspection Date	07/06/2019			
	Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD						
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705						
5a.			emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	9 Working Days				



### **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5808S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE PANEL R8	DENTED	537.50	537.50
1	WHEELARCH TRIM	DENTED	250.00	250.00
1	SIDE GLASS R11	BROKEN	425.00	425.00
1	SIDE GLASS R12	BROKEN	641.00	641.00
1	WINDOW CAPPING L2780	DENTED	550.00	550.00
1	WINDOW CAPPING 995MM	DENTED	486.00	486.00
1	TYRE RIM	DENTED	2,560.06	2,560.06
1	TYRE	TORN	1,325.00	1,325.00
	LESS 10% DISCOUNT		-	-677.46
			6,774.56	6,097.10
	SPECIAL NETT ITEMS			
1	STICKER SG LOVE (SN)	NECESSARY	200.00	200.00
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
12	SEALANT SIKAFLEX @\$37.00 (SN)	NECESSARY	444.00	444.00
1	PRIMER (SIKA 206 G+P) (SN)	NECESSARY	80.00	80.00
			804.00	804.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		4,770.00	3,710.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		728.00	616.00
			5,498.00	4,326.00
	GRAND TOTAL		13,076.56	11,227.10

RECOMMENDED COST OF REPAIRS		11,227.10

Report Ref No. CC3/CTI19010165/Jea3n2

A A

**ONG HWEE JIE** 

**Automotive Assessor** 

Amonto

HO LEONG CHUAN

**Automotive Assessor**