

MTM Performance Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11/6/2019

To: MSIG Insurance Insurance (S) Pte Ltd

Re: Quotation for Repairs to SJN6525X

Item	Description	Qty	Amount (S\$)
1	Rear Bumper	1	455.60 <i>de</i>
2	Rear Boot	1	785.30 <i>bt</i>
3	Rear Boot Center Garnish	1	183.00 <i>de</i>
4	Rear Boot Hinge	2	240.60 <i>Ry bt</i>
5	Retainer (Bumper)	2	114.20 <i>de</i>
6	Rear Panel	1	86.7 <i>bt</i>
7	Re-enforcement Bar	1	92.30 <i>X</i>
8	Exhaust	1	550.00 <i>Ry</i> <i>SN 100</i>
9	Rear Light <i>e 278.64</i>	2	557.28 <i>cray</i>
10	Reflector <i>e 91.60</i>	2	183.20 <i>cut</i>
11	Rear Boot Rubber	1	240.00 <i>mi</i>
12	Rear Sensor	1	<i>SN</i> 220.00 <i>2000w</i>
13	Rear Boot Lock	1	150.00 <i>bt</i>
14	Rear Boot Lock Hinge	1	52.00 <i>bt</i>
15	Rear Boot Carpet	1	320.00 <i>X de</i>
16	Install Reverse Sensor	1	80.00 <i>30</i>
17	To remove inner trim, garnish for check & repair	1	250.00 <i>60.</i>
18	Spray tyre compartment / floor panel	1	800.00 <i>Ry</i>
19	Spray Paint	1	1,400.00 <i>800</i>
20	Anti rust	1	120.00 <i>40.</i>
21	Labour to install	1	800.00 <i>700.</i>

Total

8,171.40

9200.76
L Rear end panel garnish de *Taufik 97495749*

360 - Spare tyre sponge - de

WP
12/6/19 12pm

Resurvey after repair
@ 6 days

taufik@khamb.com

4708-614

25/0 3531.71

SN 200

Lubon. 1930

5461.71

48 Toh Guan Road East, #01-115/116 Enterprise Hub, Singapore 608586

Tel: 92210404 email: fujimotorsports@hotmail.com

4584400