




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQI19010170/Jgb3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 10-10-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLX 5330X	Veh. Inspected	SHF 121H
	Policy No.	DMPPHQ19-001610	Coverage (\$)	0.00
	Claim No.	DM19HO01645/WY	Excess (\$)	0.00
	Assign From		Assign Date	07/06/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTDKN36U405768623	Colour	MAROON
	Odometer	308476	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	FALKEN	6 mm
	L/H Front Tyre	195/65 R15	FALKEN	6 mm
	R/H Rear Tyre	195/65 R15	FALKEN	6 mm
	L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/06/2019	Inspection Date	07/06/2019
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	