

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5593L**AAD1906-036**

Not Notarized
1/15/14 @ 3400h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHC 5593L

VF1ABL15AUC279387

RENAULT

LATITUDE

5.6.19

QBE

30/9/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>DiT</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08 X
1	HEADLAMP RH	\$	<i>Cur</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>N</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>DiT</i> 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84
1	TOW COVER FRT	\$	<i>SL</i> 28.61
1	FRONT BRACE PANEL	\$	<i>N</i> 177.22
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75 } X
1	FRAME FULL SUPPORT PANEL	\$	<i>N</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79
1	BONNET	\$	<i>N</i> 1,941.63
1	BONNET INSULATOR	\$	<i>SL</i> 405.73
1	BONNET STRUT LH	\$	<i>SL</i> 88.61
1	BONNET STRUT RH	\$	<i>SL</i> 88.61
1	BONNET HINGE LH	\$	<i>N</i> 348.31
1	BONNET HINGE RH	\$	<i>N</i> 348.31
1	BONNET LOCK	\$	<i>N</i> 305.48

Trans-cab Auto Services Pte Ltd**AAD1906-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5593L

1	BONNET CABLE	\$	119.19
1	BONNET CABLE COVER	\$	161.03
1	BONNET SEAL OUTER	\$	92.36
1	BONNET SEAL INNER	\$	157.28
1	DOOR PANEL FRT RH	\$	2,844.66
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	DOOR MIRROR GLASS RH	\$	148.20
1	DOOR MIRROR BACK COVER RH	\$	218.46
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	ROCKER PANEL CENTER RH	\$	990.25
1	LOWER ARM RH L70Y	\$	685.76
1	KNUCKLE ARM RH L70Y	\$	846.98
1	ABSORBER FRT RH L70Y	\$	360.54
1	DRIVESHAFT RH	\$	1,747.45
1	STABILIZER BAR FRT	\$	604.65
1	WIPER RESERVOIR MOTOR	\$	270.06
1	WIPER RESERVOIR	\$	348.25
1	WIPER RESERVOIR NECK	\$	136.11
1	DOOR HARNESS WIRE RH	\$	2,670.00
TOTAL		\$	30,803.94
10%		\$	3,080.39
		\$	27,723.55

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00
1	FRONT DOOR STICKER 'Classic'	\$	80.00
1	BUMPER CLIP FRT	\$	66.00
1	BUMPER BRACKET CLIP FRT RH	\$	12.00
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50
1	BUMPER GRILLE LOWER CLIP	\$	69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
1	WHEELARCH CLIP FRT RH	\$	30.50
1	FRONT RIGHT TYRE	\$	300.00
1	FRONT RIGHT TYRE RIM	\$	380.00

Trans-cab Auto Services Pte Ltd**AAD1906-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5593L

1SET	Front licence plate with holder	\$	Sn	80.00	} X
1SET	RADIATOR GRILLE SCREW	\$	nn	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	
1	WINDSCREEN SEALANT	\$	nn	253.80	
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	
2	BONNET STRUT L70Y	\$	nn	88.61	
2	BONNET CABLE CLIP L70Y	\$	nn	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
TOTAL		\$		1,882.88	

TOTAL PARTS	\$	29,606.42
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	↪ 380.00	X
To check steering geometry and computer wheel alignment	\$	↪ 220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	↪ 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	↪ 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1906-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5593L

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>4</i> 380.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>5</i> 170.00	<i>X</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>5</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>2d</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	<i>X</i>

TOTAL \$ 15,940.00**Over All Total \$ 45,546.42****LUMP SUM (REPAIR DAY)****~~20~~DAYS***2day,*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: