



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperv.com.sg

Repair Estimates

SME 7536 U

Parts	(a) Cost / List Price Items	\$	6,049.12
	Plus/Less 25%	\$	1,512.28
	Total of Cost / List	\$	4,536.84
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	4,536.84
Labour		\$	3,090.00
Total		\$	7,626.84

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	SME 7536 U	Submit By :	SERENCE
Make & Model :	TOYOTA PRIUS	Year Manufacture :	2018
Chassis No. :	ZVW508086295	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	1	\$497.50		
2	Rear bumper clip	10	\$40.00		
3	Rear bumper side retainer LH	1	\$112.70		
4	Rear bumper side retainer RH	1	\$112.70		
5	Rear bumper reinforcement	1	\$398.90		
6	Rear bumper lower garnish centre	1	\$582.60		
7	Rear bumper lower garnish LH	1	\$149.70		
8	Rear bumper tow cover	1	\$31.70		
9	Rear bumper under cover	1	\$355.20		
10	Rear bumper under cover LH	1	\$187.60		
11	Rear bumper under cover clip	4	\$14.00		
12	Tail lamp LH - UPPER	1	\$498.75		
13	Tail lamp LH - LOWER	1	\$511.60		
14	Tail door	1	\$1,122.50		
15	Tail door emblem	1	\$61.70		
16	Wording "PRIUS"	1	\$51.90		
17	Wording "HYBRID"	1	\$55.47		
18	Tail door hinge LH	1	\$87.60		
19	Tail door hinge RH	1	\$87.60		
20	Tail door plate garnish	1	\$782.50		
21	Tail door inner trim	1	\$278.90		
22	Tail door inner trim clip	10	\$28.00		
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SME 7536 U** Submit By : **SERENCE**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, TAIL DOOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, TAIL DOOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	
3	To tuff coat.	\$100.00	
4	TO Check wiring	\$50.00	
5	To transfer boot mechanism to new boot	\$120.00	
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	
7	To remove & refit reverse sensor	\$150.00	
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.