

AXA

Kp



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLM 9108 D

Finalised

Parts (a) Cost / List Price Items

\$ 2834.70 11,325.45

Plus/Less 25%

\$ 707.70 2,831.36

Total of Cost / List

\$ 2126.10 8,494.09

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

\$ 295.00

Total Parts Cost

\$ 8,789.09

Labour

\$ 1130.00 3,380.00

Total

\$ 3756.10 12,169.09

The above total will be subjected to 7% G.S.T.

Not Authorized

Penny B4 paint

* End Panel & Rear Bumper Reinforcement

- after take out rear bumper,

remember take End Panel & Rear Bumper Reinforcement

- if change Tail end Panel, Photo.

After Replace, remember take new end Panel photo

- if change Rear Bumper Reinforcement,

remember take before & after photo.

Name of Surveyor

Kenneth

Company

CICK

Survey conducted on

10/6/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-6 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess

:\$

(e) Signature of surveyor

Le

Date:

10/6/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLM 9108 D

TOYOTA PRIUS
JTDKB3FUX03555552

Submit By :
Year Manufacture :
Engine No. :
Cost / List

SERENCE

2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Sn 1	\$200.00	S.N	X
2	Rear bumper	Bu 1	\$497.50		✓
3	Rear bumper clip	un 10	\$40.00		✓
4	Rear bumper side retainer LH	Di 1	\$112.70		✓
5	Rear bumper side retainer RH	Sn 1	\$112.70		X
6	Rear bumper reinforcement	Rf 1	\$398.90		✓
7	Rear bumper lower garnish centre	Di 1	\$582.60		✓
8	Rear bumper lower garnish LH	mg 1	\$149.70		X
9	Rear bumper lower garnish RH	Sn 1	\$149.70		X
10	Rear bumper tow cover	Sn 1	\$31.70		X
11	Rear bumper under cover	Cm 1	\$355.20		X
12	Rear bumper under cover LH	Sn 1	\$187.60		X
13	Rear bumper under cover RH	Sn 1	\$187.60		X
14	Rear bumper under cover clip	un 4	\$14.00		X
15	Tail door	R 1	\$1,122.50		X
16	Tail door lock	R 1	\$487.70		X
17	Tail door emblem	un 1	\$61.70		X
18	Wording "PRIUS"	un 1	\$51.90		X
19	Wording "HYBRID"	un 1	\$55.47		X
20	Tail door hinge LH	R 1	\$87.60		X
21	Tail door hinge RH	R 1	\$87.60		X
22	Tail door plate garnish	Plac 1	\$782.50		X
23	Tail door inner trim	Sn 1	\$278.90		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

213660

Spare Parts

Vehicle No. :

SLM 9108 D

Make & Model :

TOYOTA PRIUS

Chassis No. :

JTDKB3FUX03555552

Submit By :

SERENCE

Year Manufacture :

2017

Engine No. :

0

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door inner trim clip <i>nn</i>	10	\$28.00		X
25	Tail end panel <i>R</i>	1	\$596.60		X
26	Tail end panel garnish <i>cm</i>	1	\$151.60		✓
27	Tail end panel garnish clip <i>mc</i>	10	\$35.00		✓
28	Boot weatherstrip <i>sn</i>	1	\$353.10		X
29	Spare tyre well panel <i>R</i>	1	\$793.15		X
30	Spare tyre board <i>sn</i>	1	\$566.79		✓
31	Spare tyre compartment sponge LH <i>sn</i>	1	\$297.67		✓
32	Spare tyre compartment sponge RH <i>sn</i>	1	\$297.67		✓
33	Spare tyre compartment centre <i>sn</i>	1	\$251.70		X
34	Tail lamp LH - UPPER <i>sn</i>	1	\$498.75		X
35	Tail lamp RH - UPPER <i>sn</i> GRT	1	\$498.75		X
36	Tail lamp LH - LOWER <i>cm</i>	1	\$511.60		✓
37	Tail lamp RH - LOWER <i>sn</i>	1	\$511.60		X
38	Taildoor glass sealant <i>nn</i>	1	\$50.00	S.N	X
39	Rear windscreen moulding <i>nn</i>	1	\$97.70		X
40	Rear windscreen sealant <i>nn</i>	1	\$50.00	S.N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

697.20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLM 9108 D Submit By : SERENCE
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, TAILROOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	400 600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, TAILROOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	680
3	To tuff coat. <i>nn</i>	\$150.00	X
4	TO Check wiring	\$50.00	20
5	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	50
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X
9	To remove & refit Taildoor glass to assit work load <i>nn</i>	\$120.00	X
10	To remove & refit rear windscreen. <i>nn</i>	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.