

ASSIGNMENT

Adrian Munn

nr: _____ Date: _____
 mated Cost: _____
 / TF / WS / TP RES / OD RES / EVA / INV / MV
 Inspect Vehicle No: _____
 Workshop m/s: _____
 ured _____
 ily No. 1700726631-01
 ills No. 296494044950
 m Insured: _____ Excess: 0f 0/6/19
 Client's Record) _____
 ke of Veh: _____

N/S	O/S

Power Condition) _____
 mark: The veh had commenced its
 repair at the time of inspection.
 al. or Market Value: 92K
 AC Accident Rpt: _____ Consistent? : Yes or No
 IA / IPR Seen: _____ Consistent? : Yes or No
 st. Repairs: 04/8/5 days Res: Yes or No
 um Sum: _____ % 3 Val: Yes or No
 A / REV / REP. / 24 HRS
 ate: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SLR 2876P- Yr Regn: 2017, August
 Type: McCar M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi A3 Sedan cc 999
 Colour: White A/C: Insured / Std / NI / NA
 Sp.Reading: 23699. T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZ8V1J1001586
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modl: Nil / SRim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: 205/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 10/06/19
 Survey held at: Premium
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Front n/s.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 07 AUG
 SLR 2876 R-
 18/6/19 @ 11.18am Informed Sheila ex- 50k by email.
 10/7/19 @ 10.34am ColPinned with Carvine Portal Ag 4817.84, 4 days. (Red 10763.16, 68%)
 mv :
 PV :
 Nett :
 RECEIVED 10 JUL 2019

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1) 16/7 2019	2)	IN	Basic & Add.	200
3)	4)	OUT	S + RS, SI	1
5)	6)		Photos	
Prel. Report:			Others	
Final Report:			TOTAL	211

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 10 July 2019 10:34 AM
To: Carrine Leong; SUR
Cc: 'Chang Chee Sing'; jiajee.yap@premiumauto.com.sg;
nora.khai@premiumautomobiles.com.sg
Subject: RE: FINAL REVISION - SLR2876P - OD AIG - SURVEYED 10 JUN 2019

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$4,819.84 before excess \$0/- & GST and 4 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Tuesday, 9 July 2019 3:53 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Chang Chee Sing' <claims@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg;
nora.khai@premiumautomobiles.com.sg
Subject: RE: FINAL REVISION - SLR2876P - OD AIG - SURVEYED 10 JUN 2019

Hi Adrian and Shiau Chan,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.

Revised estimate was mailed to you on 18 Jun 2019.

Kindly assist to finalize the repair cost on urgent basis, customer is chasing.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 289902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 18 June 2019 11:18 AM
To: Claims
Cc: SUR
Subject: RE: SLR 2876 P - OD CLAIMS

Dear Sheila,

Please be informed that the excess of above vehicle is \$0.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 18 June 2019 10:10 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLR 2876 P - OD CLAIMS

Dear Shiau Chan,

I have emailed the forms yesterday. Kindly update if you have Received it.

Best Regards,
Sheila M Ismail
Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sq/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8723H
Vehicle Details	
Vehicle No.:	SLR2876P
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CHZ392973
Chassis No.:	WAUZZZ8V1J1001586
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,469.00
Original Registration Date:	08 Aug 2017
First Registration Date:	08 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$16,257.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Aug 2027
PARF Rebate Amount:	\$12,192.00
Intended COE Rebate Details	
COE Expiry Date:	07 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$34,919.00
Total Rebate Amount:	\$47,111.00

The information contained herein is correct as at 10 Jun 2019

OK

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : RANDEEP SINGH KOONAR
Period of Insurance : 08 Aug 2018 To 07 Aug 2019
Engine No. : CHZ392973
Chassis No. : WAUZZZ8V1J1001586

Vehicle No. : SLR2876P
Policy No. : 1700026631-01
Endorsement No. :
Issued Date : 11 Jul 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

RANDEEP SINGH KOONAR - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408098 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6335 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125210

PREMIUM LEASING - VL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

050412

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Write/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and important information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e. refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8728723H

Name
RANDEEP SINGH KOONAR

Race
SIKH
Date of Birth
14-09-1987
Country of Birth
SINGAPORE

Sex
M



REPUBLIC OF SINGAPORE - DRIVERS LICENSE

License Number: **S8728723H**

Name
RANDEEP SINGH KOONAR

Birth Date **14 Sep 1987**
Issue Date **21 Nov 2013**

002247431E



4822512

S8728723H

APT BLK 520B TAMPINES CENTRAL 6 #01-53
SINGAPORE 522520

NPIC No: S8728723H Date: 12/05/2018

Blood Group: B+ Date of issue: 20-09-2002




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 24 Jan 2008

NP 428A

License No: S8728723H



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0690/2019/DY/TF
Date	:	30-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Randeep Singh Koonar
Address	:	Blk 520B Tampines Central 8 #01-S3 Singapore 522520
Telephone	:	HP +65 91181904
Type of Claim	:	Own Damage Claims
Policy No.	:	1700026631-01
Vehicle No	:	SLR 2876 P
Model Code	:	Audi A3 SEDAN 1.0 TFSI
Model / Year	:	Aug-17
Engine No	:	CHZ 392973
Chassis No	:	WAUZZZ8V1J1001586
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	21-May-19
Place of Accident	:	Car-Park of Blk 520B Tampines-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 2876 P

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns , outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, lhs headlight and lhs front fender. Reorganize crash management components. Reinstall all parts removed.	\$ 2,450.00 1000 ✓
3	To respray front bumper and lhs front fender.	\$ 1,800.00 1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 4,802.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 2876 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	\$ 1,830.00	✓ 1466
2	FRONT BUMPER FIXING PARTS <i>Not Nec</i>	\$ 170.00	X
3	FRONT BUMPER GUIDE SECTION - LH <i>Not Nec</i>	\$ 35.00	X
4	FRONT BUMPER CLOSING ELEMENT - LH <i>Nec</i>	\$ 270.00	+
5	FRONT BUMPER COVER TRIM - LH <i>Nec</i>	\$ 148.00	+
6	FRONT BUMPER ADAPTER - LH <i>Not Nec</i>	\$ 34.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Not Nec</i>	\$ 171.00	+
8	FRONT REINFORCEMENT <i>Nec</i>	\$ 660.00	+
9	FOAM FILLER PIECE <i>Not Nec</i>	\$ 172.00	+
10	FRONT REINFORCEMENT COVER <i>Nec</i>	\$ 111.00	+
11	FRONT FENDER - LH <i>Buckled</i>	\$ 778.00	✓ 672
12	FRONT FENDER RIVET <i>Nec</i>	\$ 15.00	✓ 12
13	FRONT FENDER ATTACHMENT PARTS <i>Not Nec</i>	\$ 65.00	? X
14	FRONT FENDER BRACKET - LH <i>Not Nec</i>	\$ 35.00	? X
15	FRONT FENDER BRACE - LH <i>Bent</i>	\$ 88.00	✓ 69.84
16	FRONT WHEEL HOUSING LINER SEAL - LH <i>Nec</i>	\$ 31.00	+
17	FRONT WHEEL HOUSING LINER - LH <i>Nec</i>	\$ 158.00	+
18	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Nec</i>	\$ 81.00	+
19	FRONT HEADLIGHT - LH <i>Not Nec</i>	\$ 5,029.00	+
20	SUNDRIES <i>Not Nec</i>	\$ 400.00	? X
TOTAL SPARE PARTS CHARGES		\$ 10,281.00	
TOTAL LABOUR CHARGES		\$ 4,802.00	
GRAND TOTAL		\$ 15,083.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian King

Surveyed Date

: 10/06/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repair, 04 Days.

LISC Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To supply damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Rental must be approved and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0690/2019/DY/TF
Date : 30-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
4 days ok - Carline 18/06/2019

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Randeep Singh Koonar
Address : Blk 520B Tampines Central 8
#01-53
Singapore 522520
Telephone : HP +65 91181904
Type of Claim : Own Damage Claims
Policy No. : 1700026631-01
Vehicle No : **SLR 2876 P**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Aug-17
Engine No : CHZ 392973
Chassis No : WAUZZZ8V1J1001586
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-May-19
Place of Accident : Car-Park of Blk 520B Tampines-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 2876 P

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns , outside temperature sensor and headlight washer assv.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, lhs headlight and lhs front fender. Reorganize crash managment components. Reinstall all parts	\$ 2,450.00	\$ 1,000.00
3	To respray front bumper and lhs front fender.	\$ 1,800.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,802.00	\$ 2,652.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 2876 P

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LH	\$ 270.00	
5	FRONT BUMPER COVER TRIM - LH	\$ 148.00	
6	FRONT BUMPER ADAPTER - LH	\$ 34.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 171.00	
8	FRONT REINFORCEMENT	\$ 660.00	
9	FOAM FILLER PIECE	\$ 172.00	
10	FRONT REINFORCEMENT COVER	\$ 111.00	
11	FRONT FENDER - LH	\$ 778.00	\$ 622.00
12	FRONT FENDER RIVET	\$ 15.00	\$ 12.00
13	FRONT FENDER ATTACHMENT PARTS	\$ 65.00	
14	FRONT FENDER BRACKET - LH	\$ 35.00	
15	FRONT FENDER BRACE - LH	\$ 88.00	\$ 69.84
16	FRONT WHEEL HOUSING LINER SEAL - LH	\$ 31.00	
17	FRONT WHEEL HOUSING LINER - LH	\$ 158.00	
18	FRONT WHEEL HOUSING LINER ATTACHMENT PA	\$ 81.00	
19	FRONT HEADLIGHT - LH	\$ 5,029.00	
20	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS CHARGES		: \$ 10,281.00	\$ 2,167.84
TOTAL LABOUR CHARGES		: \$ 4,802.00	\$ 2,652.00
GRAND TOTAL		: \$ 15,083.00	\$ 4,819.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLR 2876 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0690/2019/KK

12 July 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLR 2876 P, Audi A3 SEDAN 1.0 TFSI.

With reference to the above-mentioned vehicle, no. **SLR 2876 P** claimant, **Mr. Randeep Singh Koonar**, please find the related document per attached.

1. A copy of the Original invoice no. 85014016 – S\$5,157.23.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLR 2876 P

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:08

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014016 Date: 11/07/2019 Order: SLR2876P Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLR2876P (V 34602) Regn Date: 08/08/2017 Mileage: 23699 WIP No.: 54406

Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V1J1001586 Engine: CHZ 392973 Dept: U

You have been assisted by :- UB-Siti Marsilla (137)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ABV5821105A	FENDER	Less 020%	1.00	777.50
X	ABV5807065R GRU	COVER	Less 020%	1.00	1830.00
X	ABV0821135A	SUPPORT	Less 020%	1.00	67.30
X	AN 0161857	POP-RIVET	Less 020%	5.00	3.00

Parts 2,167.84
Labour 0.00
Sublet 2,652.00
Menus 0.00
Lubricant 0.00

Sub-Total 4,819.84

7% GST 337.39

Grand Total 5,157.23



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLR 2876 P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0690/2019/TG
13 June 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages


RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V1J1001586
Vehicle Regn No. : SLR 2876 P
Vehicle Mileage : 23699 KM
Vehicle Owner : Mr. Randeep Singh Koonar
Certificate No : 1700026631-01
Own Damage Excess : WAIVED OFF
Accident Date : 21/05/2019
Place : Car Park of Blk 520B Tampines
Repair Cost : \$ 5,157.23
WIP No. : 54406
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 19.10 hrs.
Date : 13-6-19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jun 2019		10 Jun 2019 17:37 Edit Adj Rpt	S\$4,819.84 Edit Estimates	S\$4,819.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RANDEEP SINGH KOONAR , ID: S8728723H, Tel: +6591181904, Email: NOEMAIL								
Vehicle Reg. No.:	SLR2876P	Date of Loss:	21/05/2019 11:00 - :59 [21 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2964940449SG	Policy/Cover Note No.:	1700026631-01 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban@nadaraja.nadaraja@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/06/2019]								
Driver/Custodian:	RANDEEP SINGH KOONAR (31 / Male), NRIC: S8728723H, Tel: +6591181904 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (18/06/2019): SLR2876P / OD / 21/05/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR2876P (2964940449SG)
OD**

**May 21 2019 11:55AM
[RANDEEP SINGH KOONAR]
Premium Automobiles Pte Ltd**

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		Use Viewer	
Video											1 per page			
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail	Print	
1	03/06/19 16:40	Video - Accident [Linked Accident Report Documents]										Load MP4		
											3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	10/07/19 09:42	General View										Load JPG		
2	10/07/19 09:42	General View										Load JPG		
3	10/07/19 09:42	General View										Load JPG		
4	10/07/19 09:42	General View										Load JPG		
5	10/07/19 09:42	General View										Load JPG		
6	10/07/19 09:42	General View										Load JPG		
7	10/07/19 09:42	General View										Load JPG		
8	10/07/19 09:42	General View										Load JPG		
9	10/07/19 09:42	General View										Load JPG		
10	10/07/19 09:42	General View										Load JPG		
11	10/07/19 09:42	General View										Load JPG		
12	10/07/19 09:42	General View										Load JPG		
13	10/07/19 09:42	General View										Load JPG		
14	10/07/19 09:42	General View										Load JPG		
15	10/07/19 09:42	General View										Load JPG		
											1 per page			
Documentation											1 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	13/06/19 10:52	Singapore Accident Statement										Load PDF		
2	13/06/19 10:52	Certificate of Insurance										Load PDF		
3	13/06/19 10:52	Driver's Driving License										Load PDF		
4	13/06/19 10:52	ESTIMATE										Load PDF		
5	18/06/19 09:13	INTERVIEW & UNDERTAKING FORM										Load PDF		
6	17/07/19 14:31	WORKSHOP INVOICE										Load PDF		
7	17/07/19 14:31	DISCHARGE VOUCHER										Load PDF		

Linked Accident Report Documents

			View		Use Viewer
Video			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	03/06/19 16:40	Video - Accident		Load MP4	
Assessment Reports			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	03/06/19 16:48	Accident Statement		Load HTM	
Photos/Images			3 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	03/06/19 16:37	Accident Photo		Load JPG	
2	03/06/19 16:37	Accident Photo		Load JPG	
3	03/06/19 16:37	Accident Photo		Load JPG	
4	03/06/19 16:37	Accident Photo		Load JPG	
5	03/06/19 16:37	Accident Photo		Load JPG	

6	03/06/19 16:37	Accident Photo	1	Load JPG	☒
7	03/06/19 16:37	Accident Photo	1	Load JPG	☒
8	03/06/19 16:37	Accident Photo	1	Load JPG	☒
9	03/06/19 16:37	Accident Photo	1	Load JPG	☒
10	03/06/19 16:39	Accident Photo	1	Load JPG	☒
11	03/06/19 16:39	Accident Photo	1	Load JPG	☒
12	03/06/19 16:39	Accident Photo	1	Load JPG	☒
13	03/06/19 16:39	Accident Photo	1	Load JPG	☒
14	03/06/19 16:39	Accident Photo	1	Load JPG	☒
15	03/06/19 16:39	Accident Photo	1	Load JPG	☒
16	03/06/19 16:39	Accident Photo	1	Load JPG	☒
17	03/06/19 16:39	Accident Photo	1	Load JPG	☒
18	03/06/19 16:39	Accident Photo	1	Load JPG	☒
19	03/06/19 16:39	Accident Photo	1	Load JPG	☒
20	03/06/19 16:39	Accident Photo	1	Load JPG	☒
Documentation					
			1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail		Print
1	03/06/19 16:35	Sketch Plan	1	Load JPG	☒
2	03/06/19 16:35	Sketch Plan #2	1	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19010192/AQD3N2

Date: 17/07/2019

REFERENCE

Insured/Claimant: RANDEEP SINGH KOONAR
Date of Loss: 21/05/2019

Policy No: 1700026631-01
Nature of Claim: OD

Claim No: 2964940449SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2876P	Engine No:	CHZ392973
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Chassis No:	WAUZZZ8V1J1001586
Reg. Date:	08/08/2017 (Man. Year: 2017)	Odometer:	23699 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$92,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,281.00	2,167.84	8,113.16	78.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,802.00	2,652.00	2,150.00	44.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,083.00	4,819.84	10,263.16	68.04
+ GST 7.00/7.00% (S\$)	1,055.81	337.39	718.42	68.04
Nett Amount (S\$)	16,138.81	5,157.23	10,981.58	68.04

INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	35.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LH	Not Necessary	270.00 FS	*- FS
5	1		*FRONT BUMPER COVER TRIM-LH	Not Necessary	148.00 FS	*- FS
6	1		*FRONT BUMPER ADAPTER-LH	Not Necessary	34.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	171.00 FS	*- FS
8	1		*FRONT REINFORCEMENT	Not Necessary	660.00 FS	*- FS
9	1		*FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
10	1		*FRONT REINFORCEMENT COVER	Not Necessary	111.00 FS	*- FS
11	1		*FRONT FENDER-LH	Buckled	778.00 FS	*622.00 FS
12	1		*FRONT FENDER RIVET	Necessary	15.00 FS	*12.00 FS
13	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
14	1		*FRONT FENDER BRACKET-LH	Not Necessary	35.00 FS	*- FS
15	1		*FRONT FENDER BRACE-LH	Bent	88.00 FS	*69.84 FS
16	1		*FRONT WHEEL HOUSING LINER SEAL-LH	Not Necessary	31.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER LH	Not Necessary	158.00 FS	*- FS
18	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
19	1		*FRONT HEADLIGHT-LH	Not Necessary	5,029.00 FS	*- FS
20	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNetl.

Total Parts (\$\$) 10,281.00 2,167.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS HEADLIGHT AND LHS FRONT FENDER.REORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,800.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,802.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >