

22/03/2019

ASS. REC. BY:

REF: CS/FCI19010193/Asda 02 Special Instruction:

Insured: Rusu

ASSIGNMENT (Office)

From (Person): Henry Kao

of FCI

Date/Time: 7/6/2019 5.49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFZ 905G

Insured: CHA 8656E

at Workshop m/s Stuttgart Auto

Tel: C3310680

of JFA Tanjung Penjun

Policy No:

Claim No: D19003672 MESH

Sum Insured:

Excess:

D.O.A. 3/6/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10/6

Person Contacted:

EVA

Vehicle IN / OUT

Date/Time

Action/Instruction Ichimota ()

SFZ 905G - X

SHA 8656E - X

7/06/19

@ 12:15 pm revised PA to Henry via email.

108/11/14

Surveyor

REF:


1582A

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SFZ 9056
 at Workshop m/s TRANS ENOVALS
 of 27, Mansour Pansu
 Insured: FCI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SFZ 9056 Yr Regn: 2015 / 84
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: POPSCHER C.C. 13436
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 8259 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WP0222982FS132938
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/352R20
 R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>03/06/19</u>		D.O.I. <u>14/06/19</u>
Survey held at _____		

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
as FCI

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
20/08/19	Confirmed R/P \$ 8,399.89 @ 5 days with Rasel / (\$ 7,028.82 Red - 46%)

RECEIVED 20 AUG 2019

Date/Time, File Pass to? ☐ : Preli. Report1) Typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 170 + 75Transportation: 50S + RS: 50Photos: 30

Others: _____

TOTAL

375

Report Format:

Lump Sum / I.B.F. (\$ 8,399.89 R/P)

5x15 = 75



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003672MFSH

Date: 17 June 2019

Our Ref: CS/FCI19010193/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFZ 905G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/06/2019 at the premises of M/s Stuttgart Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 15,428.71
Revised Estimate Amount	: S\$ 8,992.10
"Check" Items Amount	: S\$ 2,747.79
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-06-2019	Our Ref No. D19003672MFSH
Accident Date	03-06-2019	Claim Type. Third Party
Insured Vehicle	SHA8656E	Third Party Vehicle. SFZ905G
Survey Location	27A TANJONG PENJURU	
Contact Person.	EVA KOK	
Contact No.	63310680/ 63310683	Fax No. 63310690
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	STUTTGART AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

*Veh Out***IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Tuesday, 20 August 2019 3:44 PM
To: Veron Chen (LKKAUTO)
Subject: FW: FINALIZATION MS FIRST CAP TP - SFZ905G.xlsx


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Rasul (LKKAUTO)
Sent: Wednesday, 7 August, 2019 9:47 AM
To: jessicahs@eurokars.com.sg
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg; Shirley Hiew (LKK Auto)
Subject: RE: FINALIZATION MS FIRST CAP TP - SFZ905G.xlsx

Hi Jessicahs,

Finalise amount confirmed as per attached

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: jessicahs@eurokars.com.sg [<mailto:jessicahs@eurokars.com.sg>]
Sent: Wednesday, 7 August, 2019 9:26 AM
To: Rasul (LKKAUTO); Admin A
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; rickteo@eurokars.com.sg
Subject: FINALIZATION MS FIRST CAP TP - SFZ905G.xlsx

Dear Rasul,

Please find our computation attached for your agreement.

COR: \$8,399.89 before GST

05 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case urgently.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 17 June 2019 12:15 PM
To: 'Henry Kao Cai Jie'; 'CWS Motor Claims'
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D19003672MFSH/1
Attachments: SFZ 905G - Preli Advise .pdf

Dear Henry,

Enclosed preliminary revised of vehicle SFZ 905G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 17 June 2019 12:10 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D19003672MFSH/1

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 7 June 2019 5:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003672MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

MS FIRST CAPITAL INSURANCE LTD 36 Robinson Road, City House #16-01 Singapore 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Teo Yee Wei ADDRESS : 17A Jalan Kakatua Singapore 598535 TEL :		WIP : 46622 EXCESS : DATE: 06.06.2019	
VEH NO :	SFZ905G	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ98ZF5132938	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Boxster S	DATE REG.:	08.09.2015	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	RH FRONT FENDER <i>repair</i>	1	P981-503-032-00-GRV		\$ 1,083.50
2	FUEL FILLER FLAP <i>X</i>	1	P981-503-034-00-GRV		\$ 123.30
3	RIVET <i>X</i>	3	P999-591-712-40-		\$ 3.60
4	FRONT BUMPER <i>repair</i>	1	P981-505-010-51-		\$ 1,739.40
5	NOZZLE HOLDER LH <i>X</i>	1	P981-505-761-00-		\$ 30.00
6	NOZZLE HOLDER RH <i>X</i>	1	P981-505-762-00-		\$ 30.00
7	DIRECTION INDICATOR LIGHT (RH) <i>sea</i>	1	P991-631-156-02-		\$ 69.00
8	DISC WHEEL <i>sea - * part n.?</i>	1	P981-362-160-12-88Z		\$ 3,053.10
TOTAL PARTS					\$ 6,131.90
LESS 10%					\$ 613.19
TOTAL PARTS COST					\$ 5,518.71
Labour Description					
1	TO REPLACE FRONT BUMPER, RH FRONT FENDER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			1560	\$ 4,880.00
2	TO RESPRAY FRONT BUMPER, RH FRONT FENDER & FUEL FLAP. <i>X</i>			2400	\$ 2,600.00
3	TO REPLACE 1 PC TYRE. 235 / 35 ZR20			nn X	\$ 980.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.			NETT	\$ 120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			NETT	\$ 680.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			NETT	\$ 200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT	\$ 600.00
8	SUNDRIES. <i>NEC</i>			NETT	\$ 30.00
TOTAL LABOUR				\$ -	\$ 9,910.00
TOTAL PARTS				\$ -	\$ 5,518.71

TOTAL	\$ -	\$ 15,428.71
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

[Signature]
17/6/19
Rasul
Hp 90010068
5 days
14/06/19 @ 1620
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

MS FIRST CAPITAL INSURANCE LTD		NAME :	Ms Teo Yee Wei	WIP :	46622
36 Robinson Road, City House #16-01 Singapore 068877		ADDRESS :	17A Jalan Kakatua Singapore 598535	EXCESS :	
ATTN. : MOTOR CLAIMS		TEL :		DATE :	06.06.2019
FAX :					
VEH NO :	SFZ905G	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ98ZFS132938	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Boxster S	DATE REG.:	08.09.2015	POLICY NO. :	

NATURE OF WORKS

NATURE OF WORKS					
S/NO	Parts Description				
	QTY			REVISED	PRICES
1	RH FRONT FENDER	1	P981-503-032-00-GRV	\$ -	\$ 1,083.50
2	FUEL FILLER FLAP	1	P981-503-034-00-GRV	\$ -	\$ 123.30
3	RIVET	3	P999-591-712-40-	\$ -	\$ 3.60
4	FRONT BUMPER	1	P981-505-010-51-	\$ -	\$ 1,739.40
5	NOZZLE HOLDER LH	1	P981-505-761-00-	\$ -	\$ 30.00
6	NOZZLE HOLDER RH	1	P981-505-762-00-	\$ -	\$ 30.00
7	DIRECTION INDICATOR LIGHT (RH)	1	P991-631-156-02-	\$ 69.00	\$ 69.00
8	DISC WHEEL	1	P981-362-160-12-88Z	\$ 3,053.10	\$ 3,053.10
	TOTAL PARTS			\$ 3,122.10	\$ 6,131.90
	LESS 10%			\$ 312.21	\$ 613.19
	TOTAL PARTS COST			\$ 2,809.89	\$ 5,518.71
	Labour Description				
1	TO REPLACE FRONT BUMPER, RH FRONT FENDER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ ✓ 1,560.00	\$ 4,680.00
2	TO RESPRAY FRONT BUMPER, RH FRONT FENDER & FUEL FLAP.			\$ ✓ 2,400.00	\$ 2,600.00
3	TO REPLACE 1 PC TYRE. 235 / 35 ZR20			\$ -	\$ 980.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.			\$ ✓ 120.00	\$ 120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			\$ ✓ 680.00	\$ 680.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ ✓ 200.00	\$ 200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ ✓ 600.00	\$ 600.00
8	SUNDRIES.			\$ ✓ 30.00	\$ 50.00
	TOTAL LABOUR			\$ 5,590.00	\$ 9,910.00
	TOTAL PARTS			\$ 2,809.89	\$ 5,518.71

TOTAL	\$ 8,399.89	\$ 15,428.71
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 8,399.89	
GST 7%	\$ 587.99	\$ -
GRAND TOTAL	\$ 8,987.88	\$ -

NUMBER OF DAYS: 5 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19010193/R1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8656E	Veh. Inspected	SFZ 905G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003672MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	07/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE BOXSTER 981	c.c	3436	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WP0ZZZ98ZFS132938	Colour	BLACK	
Odometer	82159	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/35 ZR20	PIRELLI	6 mm	
L/H Front Tyre	235/35 ZR20	PIRELLI	6 mm	
R/H Rear Tyre	235/35 ZR20	PIRELLI	6 mm	
L/H Rear Tyre	235/35 ZR20	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/06/2019	Inspection Date	14/06/2019	
Survey held at	STUTTGART AUTO PTE LTD 12 SUNGEI KADUT AVE . SINGAPORE 729648			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFZ 905G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH FRONT FENDER	TO REPAIR SEE LABOUR	1,083.50	-
1	FUEL FILLER FLAP	NOT NECESSARY	123.30	-
3	RIVET	NOT NECESSARY	3.60	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,739.40	-
1	NOZZLE HOLDER LH	NOT NECESSARY	30.00	-
1	NOZZLE HOLDER RH	NOT NECESSARY	30.00	-
1	DIRECTION INDICATOR LIGHT (RH)	SCRATCHED	69.00	69.00
1	DISC WHEEL	SCRATCHED	3,053.10	3,053.10
	LESS 10% DISCOUNT		-613.19	-312.21
			5,518.71	2,809.89
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	TYRE 235/35 ZR20 (SN)	NOT NECESSARY	980.00	-
			1,030.00	30.00
LABOUR				
	TO REPLACE FRONT BUMPER,RH FRONT FENDER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		4,680.00	1,560.00
	TO RESPRAY FRONT BUMPER,RH FRONT FENDER & FUEL FLAP.		2,600.00	2,400.00
	TO MOUNT 1PC SPORT RIM AND CONDUCT WHEEL BALANCING.		120.00	120.00
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		680.00	680.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		200.00	200.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			8,880.00	5,560.00
GRAND TOTAL			15,428.71	8,399.89
RECOMMENDED COST OF REPAIRS				8,399.89

Report Ref No. CS/FCI19010193/R1sd3n2



Report Ref No. CS/FCI19010193/R1sd3n2

A handwritten signature in black ink, appearing to read 'MRB'.

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to read 'A.L.P.'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.