

Trans-cab Auto Services Pte Ltd**AAD1906-053**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5138T

Not Notarized
1 Sep 8 2450

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5138T

VF1ABL15AUC276028

RENAULT

LATITUDE

5.6.19

AIG

14/1/2014

		PART	LIST	
1	1	BUMPER COVER REAR	\$ <i>Bu</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$ <i>DDM</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$ <i>SL</i> 113.47	} X
4	1	BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 135.97	
5	1	BUMPER RETAINER RH REAR	\$ <i>SL</i> 44.99	
6	1	BUMPER REFLECTOR RH	\$ <i>SL</i> 43.61	
7	1	BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 135.97	
8	1	BUMPER RETAINER LH REAR	\$ <i>SL</i> 44.99	} X
9	1	BUMPER REFLECTOR LH	\$ <i>SL</i> 43.61	
10	1	BUMPER BEAM REAR	\$ <i>Br</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$ <i>R SL</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 225.95	X
13	1	OUTER PANEL REAR (End Panel)	\$ <i>R</i> 1,471.77	} X
14	1	OUTER PANEL REAR (End Panel)TRIM	\$ <i>SL</i> 404.56	
15	1	TAILLAMP RH	\$ <i>SL</i> 552.55	
16	1	TAILLAMP PANEL RH	\$ <i>R</i> 986.70	
17	1	TAILLAMP LH	\$ <i>SL</i> 552.55	
18	1	TAILLAMP PANEL LH	\$ <i>R</i> 986.70	
19	1	BOOT REAR	\$ <i>R</i> 2,872.68	
20	1	BOOT FINISHER	\$ <i>SL</i> 470.06	
21	1	BOOT WHEATERSTRIP	\$ <i>SL</i> 323.05	
22	1	BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 493.35	
23	1	BOOT REFLECTOR LAMP RH	\$ <i>SL</i> 493.35	} X
24	1	BOOT BADGE 'RENAULT'	\$ <i>na</i> 225.36	
25	1	BOOT BADGE	\$ <i>na</i> 225.36	
26	1	BOOT STRUT LH	\$ <i>SL</i> 276.08	
27	1	BOOT STRUT RH	\$ <i>SL</i> 276.08	
28	1	BOOT HINGE LH	\$ <i>R</i> 367.84	
29	1	BOOT HINGE RH	\$ <i>R</i> 367.84	
30	1	BOOT INNER TRIM	\$ <i>SL</i> 586.45	

Trans-cab Auto Services Pte Ltd**AAD1906-053**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5138T

31	1	BOOT SWITCH	\$	Sh	168.13	X
32	1	BOOT LOCK	\$	na	202.67	X
33	1	BOOT LOCK CATCH	\$	na	74.40	X
34	1	EXHAUST REAR	\$	na	7,489.05	X
35	1	EXHAUST CAP REAR	\$	na	230.49	X
TOTAL			\$		23,766.42	
10%			\$		2,376.64	
			\$		21,389.78	

Special Nett

1	1SET	PARKING AID	\$	Sh	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	
10	1	BOOT ADVERTISEMENT STICKER	\$	na	300.00	X
11	1	REAR BUMPER ADVERTISEMENT STICKER	\$	na	300.00	X
12	1	REAR RH FENDER ADVERTISEMENT STICKER	\$	na	300.00	X
13	1	REAR LH FENDER ADVERTISEMENT STICKER	\$	na	300.00	X
14	1	EXHAUST MOUNTING REAR	\$	na	17.82	
15	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
16	1	WINDSCREEN MOULDING	\$	na	100.00	
17	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
18	1	BOOT INNER TRIM CLIP	\$	na	45.00	
19	1SET	BOOT FINISHER CLIP	\$	na	24.20	
20	1	TAILLAMP CLIP LH	\$	na	5.00	
21	1	TAILLAMP CLIP RH	\$	na	5.00	
TOTAL			\$		2,524.02	

TOTAL PARTS \$ 23,913.80**LABOUR**

To Check Electrical Lighting Concerned.

\$

170.00 15/

Trans-cab Auto Services Pte Ltd**AAD1906-053**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5138T

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,500.00	2001
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	2201
To repair and realign rear exhaust pipe.	\$	na	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	7	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4	170.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4	380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4	380.00	X

TOTAL \$ 11,890.00**Over All Total \$ 35,803.80****LUMP SUM (REPAIR DAY)****15 DAYS***2 days*

LKK Auto Consent to be in the Repairer of the following:

- To repair and water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: