

ASS. REC. BY:

REF:

CS/INC19010221/Jed302

Special Instruction:

Surveyor: Hwa Jit

ASSIGNMENT (Office)

From (Person): Theresa Vimala

of

INC.

Date/Time:

10/6/2019

Estimated Cost:

Bill to:

OD-TP/WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 3955E

Insured:

SHD1504R

at Workshop m/s

World Auto

Tel:

63621776

of Kranji Loop

Policy No:

Claim No:

MT/1047953-003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10/6

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction
	Initials (✓)
	SLT 3955E -X
	SHD 1504R -X

ASS. REC. BY: Three Jii

REF

NTUC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.


Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 3955E Yr Regn: 8 Dec 2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 216941 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU31212859

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Gti

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 7/6/19 D.O.I. 10/6/19 1151am

Survey held at World Auto

Des. of Damages: Fr / Rea / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

	23/7/19 Final amount \$14,363.76, 9 days
	THREE JII, PLS SEE my remarks.
23/07/19	Continued P/P \$ 14,363.76 @ 9 days with Steve. (\$ 9,277.04 Red - 39%)
	RECEIVED 29 JUL 2019

Date/Time, File Pass to?

26/07/19

☐ : Preli. Report

1) Typ: 4

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS, \$ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum (I.B.I): (\$ 14,363.76 P/P)

250

290

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Monday, 10 June 2019 6:18 PM
To: assignments@LKKauto.com; admin-d@LKKauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 10/06/2019

Dear LKK

I have inserted the OIC, DOA and the claim ref nbr for your info.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Theresa Vimala D/O Balagangadharan
Sent: Monday, 10 June 2019 10:07 AM
To: assignments@LKKauto.com; admin-d@LKKauto.com
Cc: Susan Ting <susan.ting@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 10/06/2019

Dear LKK

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	ERIC TANG	MT/1046211-002	SLP8887D	MUNICH AUTOMOBILES PTE LTD	30 TEBAN GARDENS CRESCENT SINGAPORE 608927	Tan Kok Ting / 9051 5581	10:30-15:00	FBK1941X	25/5/19	
2	ENG HUEY HUEY	MT/1047953-002	SLJ3955E	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Gan Ping / 63621776		SHD1504R	7/6/19	
3	JULIANA LEE	MT/1047555-001	FBP1975Y	JC MOTORS (PTE. LTD.)	13 KAKI BUKIT ROAD 4 #01-16 BARTLEY BIZ CENTRE SINGAPORE 417807	Jimmy Boey / 6584-6914	10:00-12:00	SJS5499T	21/5/19	
4	HELENA TAN	MT/1048061-001	SBS6483B	LEXBUILD INTERNATIONAL PTE. LTD.	2 LOYANG WAY Loyang Bus Depot SINGAPORE 508776	Yong Shun / 9029 6574	14:00-16:00	YP9918M	1/6/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shirley Hiew (LKK Auto)

From: Gan Ping <ganping@worldauto.com.sg>
Sent: Friday, 26 July 2019 10:57 AM
To: 'Shirley Hiew (LKK Auto)'; 'Steve Chen (LKK Auto)'
Cc: daniel@worldauto.com.sg
Subject: RE: SLJ3955E HONDA VEZEL HYBRID FINALISE DOA: 07/06/2019

Dear Shirley

Confirmed finalized COR P/P \$14,363.76 (before GST) and 09 repair days.

Gan ping
Thks & Rgds,
World Auto Pte Ltd
Tel: 63621776

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, July 26, 2019 10:10 AM
To: 'Gan Ping' <ganping@worldauto.com.sg>; Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: daniel@worldauto.com.sg
Subject: RE: SLJ3955E HONDA VEZEL HYBRID FINALISE DOA: 07/06/2019

Dear Gan Ping,

Please re-confirm P/P \$ 14,363.76/9 days before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Wednesday, 24 July 2019 2:17 PM
To: 'Gan Ping' <ganping@worldauto.com.sg>; stevechen@lkkauto.com
Cc: daniel@worldauto.com.sg
Subject: RE: SLJ3955E HONDA VEZEL HYBRID FINALISE DOA: 07/06/2019

Dear Gan Ping,

Please re-confirm P/P \$ 14,063.76/9 days before GST.

Thank you.

Best Regards,

NTPC

MWA119074166 / World Auto Pie Ltd - HQ
 ENTRY DATE & TIME: 07/06/2019 12:44
 SUBMITTED BY: Gan Ping

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/06/2019 12:44
Date Of Accident	07/06/2019 11:00
Exact Location Of Accident	PIE TWDS CHANGI (BEFORE LOR 6 TOAPAYOH)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLJ3955E
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19-MK000194-R00
Cover Note Number	
Driver	
Name of Driver	LEONG WENG HENG
NRIC No	S1791273I
Date Of Birth	25/09/1967
Occupation	OUTDOOR
Date Of Driving Pass	18/01/1986
Driving Experience	33 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96511448
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD1504R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGN1415Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SMJ1431B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.



Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Sketch Plan #2

SKETCH PLAN



- A. SLJ 3955E
- B. SHD 1504R
- C. S6N 1415Z
- D. SMJ 1431B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 07/06/2019 AROUND 1100 HIR WHEN I WAS TRAVELLING AT PIE TOWARDS CHENGAI AIRPORT

SUDDENLY THE INFRONT OF SUDDENLY APPLY I COULDN'T BRAKE IN TIME AND HIT EMERGENCY BRAKE ~~I WAS HIT BY THE INFRONT CAR~~

INFRONT CAR, AT THE SAME TIME A TAXI AT BEHIND HIT MY CAR BACK.

DECLARATION

(We/We hereby declare foregoing particulars are true in every respect)





Policyholder's Signature:
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No

Sketch Plan #3



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLJ3955E
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	LEB5912868
Chassis No.:	RU31212859
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$29,675.00
Original Registration Date:	08 Dec 2016
First Registration Date:	08 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Dec 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	07 Dec 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,089.00
COE Rebate Amount:	\$41,985.00
Total Rebate Amount:	\$45,735.00

The information contained herein is correct as at 12 Jun 2019

OK

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
 75 BRAS BASAH ROAD NTUC INCOME CENTRE
 189557

Attention : Motor Claim Department
 Contact : 336 3322

Parts — \$14581.10
 20% = \$1664.88
 S/N = \$365
 Supplementary S/N = \$40
 Labour = \$4130
\$16199.88

Estimate : ES190110

Date : 07/06/2019
 Vehicle Num. : SLJ 3955E (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 07/06/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BONNET BUC /		819.00
2.	2	FRONT BONNET HINGE BT /	95.60	191.20
3.	1	FRONT BONNET INSULATOR BUC /		140.00
4.	1	FRONT BONNET LOCK		210.00
5.	1	FRONT BUMPER DEF /		620.80
6.	1	FRONT LOWER BUMPER CUT /		495.60
7.	2	FRONT BUMPER SIDE RETAINER CRA /	38.50	77.00
8.	1	FRONT BUMPER REINFORCEMENT BT /		580.00
9.	1	FRONT BUMPER LOWER GRILLE SCR /		118.00
10.	1	FRONT BUMPER TOW COVER ANX		45.00
11.	2	HEADLAMP ASSY CRA /	1,850.00	3,700.00
12.	2	HEADLAMP TOP BRACKET CRA /	32.00	64.00
13.	2	HEADLAMP LOWER BRACKET CRA /	78.80	157.60
14.	2	FOG LAMP ASSY ANX	480.00	960.00
15.	2	FOG LAMP COVER SCR-LH /	55.00	110.00
16.	2	FOG LAMP BRACKET SCR-LH /	30.00	60.00
17.	1	FRONT GRILLE BASE CRA /		380.00
18.	1	FRONT GRILLE MOULDING LENS CRA /		360.00
19.	1	FRONT GRILLE LOWER CHROME MOULDING CRA /		98.00
20.	1	FRONT GRILLE EMBLEM NEL /		45.00
21.	1	FRONT GRILLE CENTRE LOCK BRACKET CRA /		42.00
22.	1	FRONT SUPPORT PANEL BT /		790.00
23.	1	FRONT SUPPORT PANEL TOP GARNISH ANX		95.00
24.	1	RADIATOR		1,311.90
25.	2	RADIATOR AIR GUIDE ?	75.00	150.00
26.	1	RADIATOR FAN COWLING ?		125.00
27.	1	RADIATOR FAN MOTOR ?		225.00
28.	1	RADIATOR FAN BLADE ?		122.00
29.	1	RADIATOR SPARE TANK ?		92.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190110

Date : 07/06/2019

Vehicle Num. : SLJ 3955E (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 07/06/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	RADIATOR SPARE TANK CAP ?		30.00
31.	2	RADIATOR TOP RUBBER MOUNTING ?	30.00	60.00
32.	1	AIRCON CONDENSOR BT		1,160.00
33.	1	AIRCON CONDENSOR FAN COWLING ?		168.00
34.	1	AIRCON CONDENSOR FAN MOTOR ?		238.00
35.	1	AIRCON CONDENSOR FAN BLADE ?		95.00
36.	1	AIR INTAKE AIR DUCT		132.00
37.	1	AIR RESONATOR		130.00
38.	1	REAR TAILGATE BUC		1,100.00
39.	1	REAR TAILGATE LOCK		211.90
40.	1	REAR TAILGATE INNER TRIM BOARD		278.00
41.	1	REAR TAILGATE VEZEL EMBLEM nec		84.60
42.	1	REAR TAILGATE HYBRID EMBLEM nec		88.60
43.	1	REAR BUMPER DEF		865.00
44.	1	REAR SIDE BUMPER - LH		210.00
45.	1	REAR BUMPER REFLECTOR LENS - LH CRA		132.80
46.	1	SMART BUZZER SENSOR ?		155.00
47.	1	REAR END PANEL		630.00
48.	1	REAR END PANEL TOP GARNISH		138.00
49.	1	REAR BOOT WEATHER STRIP		165.00
50.	1	REAR BOOT COMPARTMENT BOX		320.00
51.	1	REAR WINDSCREEN GLASS MOULDING nec		195.00
52.	2	FRONT FENDER WHEEL ARCH MOULDING DEF	145.00	290.00
List Total S\$:				19,051.00
20.00% Discount S\$:				3,810.20
				15,240.80
1.	1SET	SPECIAL NETT ITEMS : FRONT BONNET INSULATOR CLIP nec		15 30.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190110

Date : 07/06/2019

Vehicle Num. : SLJ 3955E (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 07/06/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1SET	FRONT BUMPER CLIP <i>rec</i>		30.00
3.	1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>rec</i>		10 20.00
4.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>rec</i>		30.00
5.	1SET	REAR BUMPER CLIP <i>rec</i>		30.00
6.	1SET	REAR END PANEL TOP GARNISH CLIPS <i>rec</i>		20.00
7.	1	WINDSCREEN SEALANT <i>rec</i>		50 80.00
8.	1SET	REVERSE SENSOR <i>shorted</i>		200 200.00
9.	2SET	FRONT FENDER WHEEL ARCH MOULDING CLIPS <i>rec</i>	20.00	20 40.00
Special Nett Total S\$:				560.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				120 180.00
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				30 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				50 180.00
REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN FRONT CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS				1000 1,600.00
REMOVE RADIATOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS INCLUDING REFILLING COOLANT AND PERFORM ENGINE COOLING SYSTEM PRESSURE TEST				30 180.00
REMOVE AIRCON CONDENSOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL AIRCON GAS AND PERFORM AIRCON LEAK TEST				30 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190110

Date : 07/06/2019

Vehicle Num. : SLJ 3955E (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 07/06/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS		1,600.00 400 \$800
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	\$250	450.00 X
		PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00 120
		PUTTY AND SPRAY PAINT FRONT ACCIDENT AFFECTED AREAS		1,600.00 120
		PUTTY AND SPRAY PAINT REAR ACCIDENT AFFECTED AREAS		1,200.00 500
		Labour Total S\$:		7,800.00

E. & O.E.

Total S\$: 23,600.80

=====

for WORLD AUTO PTE LTD

Huse Jde - LKK

10/6/19

P/P 9 days

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

75 BRAS BASAH ROAD NTUC INCOME CENTRE

189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190110

Date : 07/06/2019

Vehicle Num. : SLJ 3955E (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 07/06/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BONNET BUL /		819.00 /
2.	2	FRONT BONNET HINGE BT /	95.60	191.20 /
3.	1	FRONT BONNET INSULATOR BUL /		140.00 /
4.	1	FRONT BONNET LOCK X NAI BUL /		210.00 X
5.	1	FRONT BUMPER DEF /		620.80 /
6.	1	FRONT LOWER BUMPER LUT /		495.60 381 /
7.	2	FRONT BUMPER SIDE RETAINER CRA /	38.50	77.00 /
8.	1	FRONT BUMPER REINFORCEMENT BT /		580.00 321 /
9.	1	FRONT BUMPER LOWER GRILLE SCR /		118.00 /
10.	1	FRONT BUMPER TOW COVER n x		45.00 X
11.	2	HEADLAMP ASSY CRA /	1,850.00	3,700.00 3569
12.	2	HEADLAMP TOP BRACKET CRA /	32.00	64.00 /
13.	2	HEADLAMP LOWER BRACKET CRA /	78.80	157.60 /
14.	2	FOG LAMP ASSY n x	480.00	960.00 X
15.	2	FOG LAMP COVER SCR-LH /	55.00	110.00 55 /
16.	2	FOG LAMP BRACKET SCR-LH /	30.00	60.00 30 /
17.	1	FRONT GRILLE BASE CRA /		380.00 /
18.	1	FRONT GRILLE MOULDING LENS CRA /		360.00 /
19.	1	FRONT GRILLE LOWER CHROME MOULDING CRA /		98.00 /
20.	1	FRONT GRILLE EMBLEM n x		45.00 /
21.	1	FRONT GRILLE CENTRE LOCK BRACKET CRA /		42.00 /
22.	1	FRONT SUPPORT PANEL BT /		790.00 /
23.	1	FRONT SUPPORT PANEL TOP GARNISH n x		95.00 X
24.	1	RADIATOR ? /		1,311.90 /
25.	2	RADIATOR AIR GUIDE ? X NAI	75.00	150.00 X
26.	1	RADIATOR FAN COWLING ? X NAI		125.00 X
27.	1	RADIATOR FAN MOTOR ? X NAI		225.00 X
28.	1	RADIATOR FAN BLADE ? X NAI		122.00 X
29.	1	RADIATOR SPARE TANK ? X NAI		92.00 X

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190110

Date : 07/06/2019

Vehicle Num. : SLJ 3955E (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 07/06/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

30.	1	RADIATOR SPARE TANK CAP ? X N/A		30.00 X
31.	2	RADIATOR TOP RUBBER MOUNTING ? X N/A	30.00	60.00 X
32.	1	AIRCON CONDENSOR BT ? X N/A		1,160.00 568/
33.	1	AIRCON CONDENSOR FAN COWLING ? X N/A		168.00 X
34.	1	AIRCON CONDENSOR FAN MOTOR ? X N/A		238.00 X
35.	1	AIRCON CONDENSOR FAN BLADE ? X N/A		95.00 X
36.	1	AIR INTAKE AIR DUCT n n x		132.00 X
37.	1	AIR RESONATOR n n x		130.00 X
38.	1	REAR TAILGATE BUC /		1,100.00 /
39.	1	REAR TAILGATE LOCK n n x		211.90 X
40.	1	REAR TAILGATE INNER TRIM BOARD n n x		278.00 X
41.	1	REAR TAILGATE VEZEL EMBLEM n e c -		84.60 /
42.	1	REAR TAILGATE HYBRID EMBLEM n e c -		88.60 /
43.	1	REAR BUMPER DEF -		865.00 /
44.	1	REAR SIDE BUMPER - LH n n x		210.00 X
45.	1	REAR BUMPER REFLECTOR LENS - LH C R A -		132.80 /
46.	1	SMART BUZZER SENSOR ? / BR		155.00 852/
47.	1	REAR END PANEL ? X R		630.00 X
48.	1	REAR END PANEL TOP GARNISH n n x		138.00 X
49.	1	REAR BOOT WEATHER STRIP n n x		155.00 X
50.	1	REAR BOOT COMPARTMENT BOX n n x		320.00 X
51.	1	REAR WINDSCREEN GLASS MOULDING n e c -		195.00 /
52.	2	FRONT FENDER WHEEL ARCH MOULDING DEF -	145.00	290.00 /

List TotalS\$:

20.00% Discount S\$:

12,977.70
- 20%
10,383.76

19,051.00

3,810.20

15,240.80

SPECIAL NETT ITEMS :

1.	1SET	FRONT BONNET INSULATOR CLIP n e c -	15	30.00
----	------	-------------------------------------	----	-------

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

75 BRAS BASAH ROAD NTUC INCOME CENTRE

189557

Attention : Motor Claim Department

Contact : 336 3322

Estimate : ES190110

Date : 07/06/2019

Vehicle Num. : SLJ 3955E (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 07/06/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1SET	FRONT BUMPER CLIP <i>rec</i>		30.00 /
3.	1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>rec</i>		10 20.00 /
4.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>rec</i>		30.00 X
5.	1SET	REAR BUMPER CLIP <i>rec</i>		30.00 /
6.	1SET	REAR END PANEL TOP GARNISH CLIPS <i>rec</i>		20.00 X
7.	1	WINDSCREEN SEALANT <i>rec</i>		20 80.00 - /
8.	1SET	REVERSE SENSOR <i>shorted</i>		20 280.00 - /
9.	2SET	FRONT FENDER WHEEL ARCH MOULDING CLIPS <i>rec</i>	20.00	20 40.00 /
Special Nett Total S\$:			365	560.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS			120	180.00
WIRINGS CHECK AND RECTIFY WHERE NECESSARY			30	180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES			50	180.00
REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN FRONT CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS <i>* 800 ✓ 700 ✓ 1000</i>				1,600.00
REMOVE RADIATOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS INCLUDING REFILLING COOLANT AND PERFORM ENGINE COOLING SYSTEM PRESSURE TEST			30	180.00
REMOVE AIRCON CONDENSOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL AIRCON GAS AND PERFORM AIRCON LEAK TEST			30	180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED
 75 BRAS BASAH ROAD NTUC INCOME CENTRE
 189557

Attention : Motor Claim Department
 Contact : 336 3322

Estimate : ES190110

Date : 07/06/2019
 Vehicle Num. : SLJ 3955E (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 07/06/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	1,600.00	401
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	200
		PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	121
		PUTTY AND SPRAY PAINT FRONT ACCIDENT AFFECTED AREAS	1,600.00	120
		PUTTY AND SPRAY PAINT REAR ACCIDENT AFFECTED AREAS	1,200.00	502
		Labour Total S\$:	7,800.00	

P- 10383.76

M- 365

L- 3580

14,328.76

Supp - 35

14,363.76 ✓

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify

the Repairer of the E. & O.E.

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) may be required and is subject to final approval

Acknowledged by Repairer

Signature:

Date:

Total S\$: 23,600.80

13/6/19 Huse Jde - LKK

10/6/19

P/P 9 days

23,640.80

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED Supplementary Estimate : SE190110

75 BRAS BASAH ROAD NTUC INCOME CENTRE
189557

Attention : Motor Claim Department

Contact : 336 3322

Date : 07/06/2019

Vehicle Num. : SLJ 3955E (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 07/06/2019

Claim No. :

Reference :

Policy No. :

(Supp)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1SET	SPECIAL NETT ITEMS : FRONT NUMBER PLATE WITH CASING	35 /	40.00
		Special Nett Total S\$:		40.00

E. & O.E.

Total S\$: 40.00

for WORLD AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19010221/Esd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 01-08-2019



ATTN : ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 1504R	Veh. Inspected	SLJ 3955E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1047953-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	10/06/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31212859	Colour	WHITE
Odometer	216941 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	6 mm
L/H Front Tyre	215/60 R16	GITI	6 mm
R/H Rear Tyre	215/60 R16	GITI	6 mm
L/H Rear Tyre	215/60 R16	GITI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/06/2019	Inspect Date / Time	10/06/2019 (11:51 AM)
Survey held at	1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3955E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	BUCKLED	819.00	819.00
2	FRONT BONNET HINGE @\$95.60	BENT	191.20	191.20
1	FRONT BONNET INSULATOR	BUCKLED	140.00	140.00
1	FRONT BONNET LOCK	NOT NECESSARY	210.00	-
1	FRONT BUMPER	DEFORMED	620.80	620.80
1	FRONT LOWER BUMPER	CUT	495.60	381.00
2	FRONT BUMPER SIDE RETAINER @\$38.50	CRACKED	77.00	77.00
1	FRONT BUMPER REINFORCEMENT	BENT	580.00	321.00
1	FRONT BUMPER LOWER GRILLE	SCRATCHED	118.00	118.00
1	FRONT BUMPER TOW COVER	NOT NECESSARY	45.00	-
2	HEADLAMP ASSY @\$1850.00	CRACKED	3,700.00	3,569.00
2	HEADLAMP TOP BRACKET @\$32.00	CRACKED	64.00	64.00
2	HEADLAMP LOWER BRACKET @\$78.80	CRACKED	157.60	157.60
2	FOG LAMP ASSY @\$480.00	NOT NECESSARY	960.00	-
2	FOG LAMP COVER @\$55.00	N/S SCRATCHED	110.00	55.00
2	FOG LAMP BRACKET @\$30.00	N/S SCRATCHED	60.00	30.00
1	FRONT GRILLE BASE	CRACKED	380.00	380.00
1	FRONT GRILLE MOULDING LENS	CRACKED	360.00	360.00
1	FRONT GRILLE LOWER CHROME MOULDING	CRACKED	98.00	98.00
1	FRONT GRILLE EMBLEM	NECESSARY	45.00	45.00
1	FRONT GRILLE CENTRE LOCK BRACKET	CRACKED	42.00	42.00
1	FRONT SUPPORT PANEL	BENT	790.00	790.00
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	95.00	-
1	RADIATOR	DENTED	1,311.90	1,311.90
2	RADIATOR AIR GUIDE @\$75.00	NOT NECESSARY	150.00	-
1	RADIATOR FAN COWLING	NOT NECESSARY	125.00	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	225.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	122.00	-
1	RADIATOR SPARE TANK	NOT NECESSARY	92.00	-
1	RADIATOR SPARE TANK CAP	NOT NECESSARY	30.00	-
2	RADIATOR TOP RUBBER MOUNTING @\$30.00	NOT NECESSARY	60.00	-

Report Ref No. CS/INC19010221/Esd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON CONDENSOR	BENT	1,160.00	568.00
1	AIRCON CONDENSOR FAN COWLING	NOT NECESSARY	168.00	-
1	AIRCON CONDENSOR FAN MOTOR	NOT NECESSARY	238.00	-
1	AIRCON CONDENSOR FAN BLADE	NOT NECESSARY	95.00	-
1	AIR INTAKE AIR DUCT	NOT NECESSARY	132.00	-
1	AIR RESONATOR	NOT NECESSARY	130.00	-
1	REAR TAILGATE	BUCKLED	1,100.00	1,100.00
1	REAR TAILGATE LOCK	NOT NECESSARY	211.90	-
1	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	278.00	-
1	REAR TAILGATE VEZEL EMBLEM	NECESSARY	84.60	84.60
1	REAR TAILGATE HYBRID EMBLEM	NECESSARY	88.60	88.60
1	REAR BUMPER	DEFORMED	865.00	865.00
1	REAR SIDE BUMPER - LH	NOT NECESSARY	210.00	-
1	REAR BUMPER REFLECTOR LENS - LH	CRACKED	132.80	132.80
1	SMART BUZZER SENSOR	BROKEN	155.00	85.20
1	REAR END PANEL	TO REPAIR SEE LABOUR	630.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	138.00	-
1	REAR BOOT WEATHER STRIP	NOT NECESSARY	155.00	-
1	REAR BOOT COMPARTMENT BOX	NOT NECESSARY	320.00	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	195.00	195.00
2	REAR FENDER WHEEL ARCH MOULDING @\$145.00	DEFORMED	290.00	290.00
	LESS 20% DISCOUNT		-3,810.20	-2,595.94
			15,240.80	10,383.76
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BONNET INSULATOR CLIP (SN)	NECESSARY	30.00	15.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00

Report Ref No. CS/INC19010221/Esd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT NUMBER PLATE WITH CASING (SN) (ADDITIONAL)	CRUSHED	40.00	35.00
2	SET FRONT FENDER WHEEL ARCH MOULDING CLIPS @\$20.00 (SN)	NECESSARY	40.00	20.00
			600.00	400.00
	LABOUR			
	PUTTY AND SPRAY PAINT REAR ACCIDENT AFFECTED AREAS.		1,200.00	500.00
	REMOVE & REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		180.00	30.00
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	50.00
	REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN FRONT CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		1,600.00	800.00
	REMOVE RADIATOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS INCLUDING REFILLING COOLANT AND PERFORM ENGINE COOLING SYSTEM PRESSURE TEST.		180.00	30.00
	REMOVE AIRCON CONDENSOR AND RELATED COMPONENTS IN ORDER TO FACILITATE REPAIRS AND REPLACE ABOVE PARTS, REFILL AIRCON GAS AND PERFORM AIRCON LEAK TEST.		180.00	30.00
	REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,600.00	500.00
	DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	200.00
	PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	120.00
	PUTTY AND SPRAY PAINT FRONT ACCIDENT AFFECTED AREAS.		1,600.00	1,200.00
			7,800.00	3,580.00
GRAND TOTAL			23,640.80	14,363.76

Report Ref No. CS/INC19010221/Esd3e2



RECOMMENDED COST OF REPAIRS (CONFIRMED)			14,363.76
---	--	--	-----------

Report Ref No. CS/INC19010221/Esd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.