

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA	DATE	: 10/06/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLG4083E		
MODEL	: KIA FORTE K3 1.6A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 7-Jun-19
		TIME	: 19:30HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET <i>Cracked</i>	1	\$ 920.00	\$ 920.00
2	FRONT BUMPER <i>Distorted</i>	1	\$ 780.00	\$ 780.00
3	FRONT BUMPER SIDE RETAINER <i>RH Dmg</i>	2	\$ 58.00	\$ 116.00
4	FRONT BUMPER LOWER GRILLE <i>new cracked</i>	1	\$ 222.30	\$ 222.30
5	FRONT BUMPER DAYLIGHT GARNISH RH <i>distorted</i>	1	\$ 90.00	\$ 90.00
6	FRONT BUMPER FOG LAMP RH <i>new</i>	1	\$ 344.70	\$ 344.70
7	FRONT BUMPER FOG LAMP GARNISH RH <i>new</i>	1	\$ 150.00	\$ 150.00
8	FRONT BUMPER REINFORCEMENT <i>best</i>	1	\$ 490.00	\$ 490.00
9	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 140.00	\$ 140.00
10	FRONT FENDER RH <i>Distorted</i>	1	\$ 580.00	\$ 580.00
11	FRONT FENDER INNER COWLING RH <i>Distorted</i>	1	\$ 150.00	\$ 150.00
12	FRONT FENDER INNER PROTECTOR RH <i>new</i>	1	\$ 60.00	\$ 60.00
13	WASHER TANK <i>cracked</i>	1	\$ 130.00	\$ 130.00
14	WASHER TANK MOTOR <i>new</i>	1	\$ 210.00	\$ 210.00
15	HEADLAMP RH <i>Smashed</i>	1	\$ 2,255.00	\$ 2,255.00
16	HEADLAMP LOWER BRACKET RH <i>smashed</i>	1	\$ 55.00	\$ 55.00
17	SUPPORT PANEL <i>cracked</i>	1	\$ 930.00	\$ 930.00
18	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 460.00	\$ 460.00

19	FRONT KNUCKLE ARM RH <i>Bent</i>	1	\$ 420.00	\$ 420.00
20	FRONT KNUCKLE ARM BEARING RH <i>Na</i>	1	\$ 290.00	\$ 290.00
21	FRONT WHEEL HUP RH <i>2nd</i>	1	\$ 249.60	\$ 249.60
22	FRONT LOWER ARM RH <i>Bent</i>	1	\$ 374.90	\$ 374.90

7859.50

TOTAL PRICE \$ 8,497.50

7073.55

LESS 10% \$ 849.75

SUB TOTAL PRICE \$ 7,647.75

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Neu</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIPS(SET) <i>Na</i>	1	\$ 20.00	\$ 20.00
3	FRONT FENDER INNER COWLING CLIPS(SET) <i>Na</i>	1	\$ 20.00	\$ 20.00
4	RADIATOR COOLANT <i>Na</i>	1	\$ 80.00	\$ 80.00
5	WHEEL TYRE <i>64 Neu</i>	1	\$ 350.00	\$ 350.00
6	WHEEL RIM <i>ut</i>	1	\$ 850.00	\$ 850.00

580

TOTAL \$ 1,370.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>900.</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>800</i>	
3	TUFF COAT	\$ 150.00	<i>x.</i>	
4	WIRING CHECK	\$ 50.00	<i>30.</i>	
5	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>x</i>	
6	REMOVE AND REFIX AIRCON CONDENSOR	\$ 120.00	<i>60</i>	
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 100.00	<i>60</i>	
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 220.00	<i>180.</i>	
9	WHEEL ALIGNMENT	\$ 100.00	<i>80</i>	

\$3,620.00

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- and survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final price on Insurance Company

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,017.75

TOTAL LABOUR COST : \$ 3,620.00

TOTAL REPAIR COST : \$ 12,637.75

Acknowledged by Repairer Signature: _____

Date: _____

APPROVED DETAILS

7.8K

Adrian Lj
H/S 10/06/19
06 pms.
total 9763.55
H/S: 7.8K.

SURVEYOR :
CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :