

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SLH8390L

Date of Accident : 08 June 2019

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Kwa Tiong Guan

Date : 10 June 2019

Estimate To Repair SKA3353B - Mercedes Benz C180K

Chassis No : WDD2040452A505982

S/No	Quantity	Description	Amount
		<u>NETT ITEMS</u>	
01	1 pc	front bumper <i>20/22</i>	\$ 1,358.00
02	1 pc	front bumper centre grille <i>11</i>	\$ 83.00
03	8 ps	front bumper clips @ \$7.00 <i>22</i>	\$ 56.00
04	1 pc	front number plate garnish <i>22</i>	\$ 125.00
05	1 pc	front centre grille assy <i>one</i>	\$ 680.00
06	1 pc	front bumper foam <i>Torn</i>	\$ 155.00
07	1 pc	front bumper reinforcement <i>22</i>	\$ 288.00
08	1 pc	front bumper reinforcement bracket <i>11</i>	\$ 250.00
09	1 pc	front bumper chrome moulding <i>22</i>	\$ 82.00
10	2 ps	headlamps @ \$1010.00 <i>one</i>	\$ 2,020.00
11	1 pc	headlamp top rubber seal <i>22</i>	\$ 35.00
12	2 ps	front support air guide @ \$120.00 <i>Torn</i>	\$ 240.00
13	1 pc	front support panel top <i>2</i>	\$ 120.00
14	1 pc	front support panel top garnish <i>one</i>	\$ 70.00
15	6 ps	front support panel top garnish clips @ \$9.00 <i>11</i>	\$ 54.00
16	1 pc	bonnet star logo <i>one</i>	\$ 75.00
17	1 pc	bootlid <i>20/22</i>	\$ 1,550.00
18	1 pc	bootlid C180 badge <i>22</i>	\$ 48.00
19	1 pc	bootlid CC badge <i>22</i>	\$ 58.00
20	1 pc	bootlid centre emblem badge <i>22</i>	\$ 48.00
21	1 pc	bootlid kompressor badge <i>22</i>	\$ 98.00
22	1 pc	bootlid inner trim <i>11</i>	\$ 205.00
23	5 ps	bootlid inner trim clips @ \$7.00 <i>11</i>	\$ 35.00
24	1 pc	bootlid inner trim lower garnish <i>11</i>	\$ 120.00
25	2 ps	bootlid hinges @ \$140.00 <i>11</i>	\$ 280.00
26	2 ps	bootlid hinge cover @ \$36.00 <i>11</i>	\$ 72.00
27	4 ps	bootlid hinge cover clips @ \$7.00 <i>11</i>	\$ 28.00
28	1 pc	bootlid weatherstrip <i>22</i>	\$ 158.00
29	1 pc	bootlid lock <i>22</i>	\$ 270.00
30	2 ps	bootlid stoppers @ \$19.00 <i>11</i>	\$ 38.00
31	1 pc	rear licence plate lamp chrome garnish <i>22</i>	\$ 150.00
32	2 ps	rear lamps @ \$545.00 <i>20/22</i>	\$ 1,090.00
33	6 ps	rear lamp clip holders @ \$6.00 <i>11</i>	\$ 36.00
34	1 pc	rear end panel <i>2</i>	\$ 1,165.00
35	1 pc	rear end panel inner trim <i>11</i>	\$ 110.00
36	1 pc	rear bumper <i>20/22</i>	\$ 1,460.00
37	1 pc	rear bumper reinforcement <i>22</i>	\$ 635.00
38	1 pc	rear bumper centre chrome moulding <i>22</i>	\$ 105.00
39	2 ps	rear bumper side chrome moulding @ \$93.00 <i>22</i>	\$ 186.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLH8390L

Date of Accident : 08 June 2019

Mr Kwa Tiong Guan

Date : 10 June 2019

Estimate To Repair SKA3353B - Mercedes Benz C180K

Chassis No : WDD2040452A505982

S/No	Quantity	Description	Amount
		<u>NETT ITEMS</u>	
40	2 ps	rear bumper side retainers @ \$35.00 <i>one</i>	\$ 70.00 ✓
41	1 pc	rear luggage floor inner trimboard <i>17</i>	\$ 255.00 X
42	1 pc	left rear fender air vent <i>17</i>	\$ 65.00 X
43	1 pc	front passenger seat headrest <i>Amul/cu 713.20</i>	\$ 900.00 ?
44	1 pc	front driver seat headrest <i>Amul/cu 713.20</i>	\$ 900.00 ?
			\$ 15,826.00
		Less 10 %	\$ 1,582.60
			\$ 14,243.40
		<u>SPECIAL NETT ITEMS</u>	
45	1 pc	front licence plate <i>11 991 / 100 / 10791.50</i>	\$ <i>ser</i> 80.00 40
			\$ 80.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60.00 30
02		To rust-proofing of the affected areas.	\$ 180.00 80
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00 80
04		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 150.00 60
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,800.00 1200
06		Putty and spray painting of the affected portion.	\$ 1,800.00 1500
			\$ 4,170.00
		Total	\$ 18,493.40 2990
			137 81.9