

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

Jiale

AIIG Asia Pacific Insurance Pte Ltd

AIIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-067

Date : 28/05/2019

Vehicle Num. : SLT889E

Make/Model : Audi Q5-2017

Chassis/Eng# : WAUZZZF6H2040577/DAX010637

Accident Date : 26/05/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 pc	Rear Bumper Assy <i>Rehd</i>		1,580.65 <i>✓</i>
2.	10 pcs	Rear Bumper Clips <i>m</i>	3.80	38.00 <i>✓</i>
3.	2 pcs	Rear Bumper Side Holder L/R <i>m</i>	68.15	136.30 <i>✓</i>
4.	2 pcs	Rear Bumper Bracket L/R <i>m</i>	54.10	108.20 <i>✓</i>
5.	1 pc	Rear Bumper Inner Sponge <i>ould</i>		78.56 <i>✓</i>
6.	1 pc	Rear Bumper Reinforcement <i>Burt</i>		685.75 <i>✓</i>
7.	1 pc	Rear Bumper Lower Exhaust Guard <i>ould new</i>		196.56 <i>✓</i>
8.	2 pcs	Rear Exhaust End Chrome Pipe <i>new</i>	255.12	510.24 <i>✓</i>
9.	1 pc	Rear Bumper Tow Hook Cover <i>new</i>		45.31 <i>✓</i>
10.	4 pcs	Rear PDC - Parking Sensor <i>new</i>	280.85	1,123.40 <i>✓</i>
11.	1 pc	Rear Lower Bumper <i>Repair</i>		911.25 <i>✓</i>
12.	2 pcs	Rear Bumper Reflector Lamp L/R <i>RH could</i>	75.12	150.24 <i>✓</i>
13.	1 pc	Rear End Panel <i>Repair</i>		575.87 <i>✓</i>
		<i>Rear Bumper Lower Sponges</i>		
		List Total S\$:		6,140.33
		5.00% Discount S\$:		307.02
				5,833.31
LABOUR :				
		To remove, rearrange electrical wirings, check lighting		120.00 <i>30</i>
		To remove, instal exhaust & align pipe.		150.00 <i>✓</i>
		To reset PDC.		100.00 <i>80</i>
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident		1,500.00 <i>400</i>
		To putty and respray painting on affected area.		1,000.00 <i>400</i>
		Labour Total S\$:		2,870.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 8,703.31

SUCCESS UNITED PTE LTD

Adrian Lj
4/5 10/06/19
0309p.

total: 3530.64
4/5: 3.1K.