

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G**AAD1906-043***Not with hand**Resurvey by paint*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHD 480G

VF1ABL15AUC283456

RENAULT

LATITUDE

5.6.19

AIG

3/7/2017

PART		LIST	
1	FENDER PANEL FRT RH	\$	<i>11</i> 783.83 X
1	WHEELARCH FRT RH	\$	<i>12</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>11</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>12</i> 130.84 X
1	FRONT BRACE PANEL	\$	<i>11</i> 177.22 X
1	DOOR PANEL FRT RH	\$	<i>12</i> 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	<i>11</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>11</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>12</i> 194.77
1	DOOR LOCK FRT RH	\$	<i>11</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>11</i> 131.23
1	DOOR WHEATHESTRIIP FRONT RH	\$	<i>12</i> 410.66
1	DOOR MOULDING FRONT RH	\$	<i>12</i> 176.82
1	DOOR FINISHER INNER FRONT RH	\$	<i>12</i> 323.44
1	DOOR FINISHER FRONT RH	\$	<i>12</i> 423.10
1	DOOR HANDLE OUTER FRT RH	\$	<i>12</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>12</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>12</i> 133.60
1	DOOR REGULATOR FRT RH	\$	505.19 ?
1	DOOR REGULATOR MOTOR FRT RH	\$	796.46 ?
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>12</i> 120.97 X
1	DOOR CASING FRONT RH	\$	<i>12</i> 1,509.06 X
1	DOOR GRAB HANDLE FRONT RH	\$	<i>12</i> 210.96
1	DOOR BLIND FRONT RH	\$	<i>12</i> 741.80
1	DOOR SEAL FRONT RH	\$	<i>12</i> 162.02
1	DOOR GLASS RUNNER SEAL FRONT RH	\$	<i>12</i> 229.31
1	DOOR WAIST SEAL OUTER FRONT RH	\$	<i>12</i> 334.69
1	DOOR WAIST SEAL INNER FRONT RH	\$	<i>12</i> 115.64
1	DOOR MIRROR ASSY RH	\$	<i>12</i> 1,483.40

Trans-cab Auto Services Pte Ltd

AAD1906-043

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G

1	DOOR MIRROR GLASS RH	\$	SL	148.20	X
1	DOOR MIRROR BACK COVER RH	\$	SL	218.46	X
1	ROCKER PANEL INNER GARNISH RH	\$	SL	466.51	X
1	ROCKER PANEL INNER RH	\$	N	1,024.79	X
1	ROCKER PANEL OUTER RH	\$	N	1,184.99	X
1	ROCKER PANEL CENTER RH	\$	N	990.25	✓
1	DOOR HARNESS WIRE RH	\$	SL	2,670.00	X
TOTAL		\$		20,899.05	
10%		\$		2,089.91	
		\$		18,809.15	

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	N	80.00	15 SL
1	FRONT DOOR STICKER 'Classic'	\$	N	80.00	60 SL
1	WHEELARCH CLIP FRT RH	\$	N	30.50	} X
1	FRONT RIGHT TYRE	\$	SL	300.00	
1	FRONT RIGHT TYRE RIM	\$	SL	380.00	
1	WINDSCREEN SEALANT	\$	N	253.80	
1	FRONT WINDSCREEN MOULDING	\$	N	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	N	100.00	
1	DOOR CHECK BOLT	\$	N	22.69	
1	DOOR GUIDE SCREW	\$	N	10.85	
1	DOOR HINGE BOLT	\$	N	10.85	
1	DOOR HINGE NUT RH	\$	N	14.60	
1	DOOR CHECK BOLT	\$	N	22.69	
1	DOOR CHECK NUT	\$	N	3.75	
1	DOOR LOCK SCREW L70Y	\$	N	6.12	
1	DOOR CATCH SCREW L70Y	\$	N	10.06	
TOTAL		\$		1,445.93	
TOTAL PARTS		\$		20,255.08	

LABOUR

Panel beating, knocking and straightening the
 necessary portion, remove and renewal of parts, adjust
 and realign the same

\$

6,000.00

6000

Trans-cab Auto Services Pte Ltd

AAD1906-043

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 480G

To transfer of front windscreen fittings and conduct water seepage test.	\$	170.00	170.00	X
To rust-proofing of the affected areas.	\$	170.00	170.00	601
Putty and spray painting of the affected portion.	\$	6,000.00	6,000.00	4401
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	380.00	801
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	380.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	170.00	201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	380.00	X
Towing Fees.	\$	150.00	150.00	X
TOTAL	\$	14,950.00		

Over All Total \$ 35,205.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PART BY PART (REPAIR DAY)**20 DAYS**

4 days