COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 3718H

MAKE

DATE 10/6/2019 17:03

AXA

ULV	Parts Description/ Labour	Type	Unit Price	£	Amount
Qty	Rear Bumper			\$	553.00
	Rear Bumper Clip 10 pcs			\$	22.00
	Rear Bumper Under Cover			\$	228.00
	Real Bumper Order Cover			2	
	SUB TOTAL			\$	803.00
	LESS 20%			\$	160.60
	DISCOUNTED TOTAL			\$	642.40
	Rear Bumper Rubber Mat			\$	50.00
	Rear Bumper Advertisement Logo			\$	50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$	200.00
				\$	300.00
	Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor			\$ \$ \$ \$	40 0.00 30 .00 30.00 80.00
	TOTAL LABOUR			\$	810.00
	ESTIMATE TOTAL			\$	1,752.40
	ESTIMATE TOTAL			4	1,732.40
	Kehineller 11/6/19 1110h 2lys He Rymplh	the Rapa the Rapa to resun parts Thir	o ces actively is on a allower	naice b	and Company

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.