



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLZ 5717 D

*Not Authorized
Resurvey B & paint*

Parts	(a) Cost / List Price Items	\$	4,593.10
	Plus/Less 20%	\$	918.62
	Total of Cost / List	\$	3,674.48
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	3,674.48
Labour		\$	3,010.00
Total		\$	6,684.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennerly
Company : LKK
Survey conducted on : 12/6/18 at 10.15am

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : ~~Required~~ / Not Required

(d) Excess : \$

(e) Signature of surveyor : Sc Date: 12/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLZ 5717 D**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71208031**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (Motor) <i>CM</i>	1	\$527.00		✓
2	RH wing mirror (glass)	1			
3	RH wing mirror (cover) <i>h. x</i>	1	\$47.30		✓
4	RH quarter glass <i>CM</i>	1	\$290.70		✓
5	RH front door <i>R</i>	1	\$1,050.00		✓
6	RH front door hinge top <i>R</i>	1	\$48.50		X
7	RH front door hinge bottom <i>R</i>	1	\$48.50		X
8	RH front door lock <i>R</i>	1	\$262.30		X
9	RH front door catch <i>R</i>	1	\$27.50		X
10	RH front door checker <i>h</i>	1	\$48.00		X
11	RH front door weatherstip <i>h</i>	1	\$143.40		X
12	RH front door trim <i>h</i>	1	\$655.00		X
13	RHF door outer handle <i>h</i>	1	\$322.70		X
14	RHF door glass <i>h</i>	1	\$685.60		✓
15	RHF door glass outer moulding <i>h</i>	1	\$75.60		✓
16	RHF power window motor <i>h</i>	1	\$361.00		?
17	RHF power window regulator <i>h</i>	1			
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLZ 5717 D** Submit By : **Carmen Lim**
Make & Model : **HONDA SHUTTLE** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RHF DOOR,RHR DOOR,RHF FENDER, RHR FENDER,RHS MIRROR)	\$1,000.00	2501
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RHF DOOR,RHR DOOR,RHF FENDER, RHR FENDER,RHS MIRROR)	\$1,000.00	4401
3	To check Wiring	\$50.00	201
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	601
5	To remove & refit RHF door glass	\$120.00	
6	To do wheel alignment <i>nn</i>	\$120.00	X
7	To remove & refit inner seat & upholstery to assist work load. <i>nn</i>	\$250.00	X
8	To tuff coat.	\$200.00	301
9	Towing <i>(B.71)</i>	\$120.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.