

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2019 Edit Reg		10 Jun 2019 00:00 Edit Adj Rpt	S\$2,950.00 Edit Estimates	S\$2,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TWINCAR LEASING PTE LTD , Co. Reg. No.: -									
Main Claimant: COLOR SPECS PTE LTD , Co. Reg. No.: 200907710Z									
Vehicle Reg. No.:	GBB4965E	Date of Loss:	06/06/2019 15:00 - :59 [120 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6196749474SG	Policy/Cover Note No.:	0999994387 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKX4350G	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Team Autopro Pte Ltd (KAKI BUKIT) No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 20/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (23/06/2020): Alert - Adj Mandate Approved (S\$4067.45) - GBB4965E - Claim Handler: Loh, Chee-H... - AIG_SG_EXPRESS (22/05/2020): Alert - Adj Mandate Approved (S\$3797.49) - GBB4965E - Claim Handler: Loh, Chee-H... - AIG_SG (26/06/2019): Re: No OI GIA Report - AIG_SG (12/06/2019): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBB4965E (6196749474SG)
[SKX4350G]
TP
COLOR SPECS PTE LTD
Jun 6 2019 3:00PM
[TWINCAR LEASING PTE LTD]
Team Autopro Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences				
			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Assessment Reports				
			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	21/05/20 22:18	Adjuster Immediate Advice		Load HTM
2	19/06/20 19:44	Adjuster Immediate Advice		Load HTM
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	15/08/19 18:16	Accident Statement From:SC - Reg. No: SKX4350G, Claimant: TWINCAR LEASING PTE LTD		Load HTM
Photos/Images				
			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	19/05/20 14:02	Before Repair Photo		Load JPG
2	19/05/20 14:02	Before Repair Photo		Load JPG
3	19/05/20 14:02	Before Repair Photo		Load JPG
4	19/05/20 14:02	Before Repair Photo		Load JPG
5	19/05/20 14:02	Before Repair Photo		Load JPG
6	19/05/20 14:02	Before Repair Photo		Load JPG
7	19/05/20 14:02	Before Repair Photo		Load JPG
8	19/05/20 14:02	Before Repair Photo		Load JPG
9	19/05/20 14:02	Before Repair Photo		Load JPG
10	19/05/20 14:02	Before Repair Photo		Load JPG
11	19/05/20 14:02	Before Repair Photo		Load JPG
12	19/05/20 14:02	Before Repair Photo		Load JPG
13	19/05/20 14:02	Before Repair Photo		Load JPG
14	19/05/20 14:02	Before Repair Photo		Load JPG
15	19/05/20 14:02	Before Repair Photo		Load JPG
16	19/05/20 14:02	Before Repair Photo		Load JPG
17	19/05/20 14:02	Before Repair Photo		Load JPG
18	19/05/20 14:02	Before Repair Photo		Load JPG
19	19/05/20 14:02	Before Repair Photo		Load JPG
20	19/05/20 14:02	Before Repair Photo		Load JPG
21	19/05/20 14:03	Before Repair Photo		Load JPG
22	19/05/20 14:03	Before Repair Photo		Load JPG
23	19/05/20 14:03	Before Repair Photo		Load JPG
24	19/05/20 14:03	Before Repair Photo		Load JPG
25	19/05/20 14:03	Before Repair Photo		Load JPG
26	19/05/20 14:03	Before Repair Photo		Load JPG
27	19/05/20 14:03	Before Repair Photo		Load JPG
28	19/05/20 14:03	Dismantled Parts		Load JPG
29	19/05/20 14:03	Dismantled Parts		Load JPG
30	19/05/20 14:03	Dismantled Parts		Load JPG
31	19/05/20 14:03	Dismantled Parts		Load JPG

Letters/Correspondences			1 per page	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
32	19/05/20 14:03	Dismantled Parts		Load JPG ✓
33	19/05/20 14:03	Dismantled Parts		Load JPG ✓
34	19/05/20 14:03	Dismantled Parts		Load JPG ✓
35	19/05/20 14:03	After Repair Photo		Load JPG ✓
36	19/05/20 14:03	After Repair Photo		Load JPG ✓
37	19/05/20 14:03	After Repair Photo		Load JPG ✓
38	19/05/20 14:03	After Repair Photo		Load JPG ✓
39	19/05/20 14:03	After Repair Photo		Load JPG ✓
40	19/05/20 14:03	After Repair Photo		Load JPG ✓
41	19/05/20 14:03	After Repair Photo		Load JPG ✓
42	19/05/20 14:03	After Repair Photo		Load JPG ✓
43	19/05/20 14:03	After Repair Photo		Load JPG ✓
44	19/05/20 14:03	After Repair Photo		Load JPG ✓
45	19/05/20 14:03	After Repair Photo		Load JPG ✓
46	19/05/20 14:03	After Repair Photo		Load JPG ✓
47	19/05/20 14:03	After Repair Photo		Load JPG ✓
48	19/05/20 14:03	After Repair Photo		Load JPG ✓
49	19/05/20 14:03	After Repair Photo		Load JPG ✓
50	19/05/20 14:03	After Repair Photo		Load JPG ✓
51	19/05/20 14:03	After Repair Photo		Load JPG ✓
52	19/05/20 14:03	After Repair Photo		Load JPG ✓
Documentation			1 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	11/06/19 17:05	EMAIL FROM AIG DD 10062019		Load PDF
2	11/06/19 17:05	NOTICE & GIA REPORT		Load PDF
3	03/07/19 17:54	First Reminder Letter		Load PDF
4	22/07/19 09:04	TP ESTIMATE- MARKED		Load PDF
5	31/07/19 17:59	Final Reminder Letter		Load PDF
6	30/09/19 17:05	LETTER TO OI		Load PDF
7	19/06/20 19:06	LOD, ATA, REPAIR BILL, RENTAL AGREEMENT, RENTAL INVOICE, LTA AND GIA SEARCH		Load PDF
8	27/07/20 11:42	Authorisation to Act		Load PDF
9	27/07/20 11:42	GIA LTA SEARCH		Load PDF
10	27/07/20 11:42	REGISTERED MAIL FEE		Load PDF
11	27/07/20 11:42	Release Voucher		Load PDF
12	27/07/20 11:42	RENTAL RECEIPT		Load PDF
13	27/07/20 11:42	WORKSHOP INVOICE		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	15/08/19 18:16	TP GIA		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKX4350G (Insd veh)	Model:	HYUNDAI H-1 STAREX 2.5 D
	GBB4965E (TP veh)		CRDI (A)
Date of Accident:	06/06/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:\$	7,633.16	
Final Repair Cost	:\$	4,000.00	
Loss of Use	:\$	days at \$0.00 per day	
Rental (if any)	:\$	9 days	
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$	4,000.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Team Autopro Pte Ltd	:\$	4,000.00
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

27 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19010290/BKA3S2**Date:** 27/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994387
Claimant Vehicle No :	GBB4965E	Insured Vehicle No :	SKX4350G
Date of Loss:	06/06/2019	Nature of Claim:	TP
		Claim No:	6196749474SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB4965E	Engine No:	D4CB9477260
Make & Model:	HYUNDAI H-1 STAREX, 2.5 D CRDi (A)	Chassis No:	KMFVBH7JR9U142509
Reg. Date:	16/05/2009 (Man. Year: 2009)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/75 R16	Rear Tyre Size:	215/75 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,383.16	1,743.92	2,639.24	60.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,990.00	1,260.00	38.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,633.16	3,733.92	3,899.24	51.08
Approved Total (Overridden) (S\$)		2,950.00		
Nett Amount (S\$)	7,633.16	2,950.00	4,683.16	61.35
+ Car Rental (9.0 x S\$120.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		37.45		
Nett Liability (S\$)		4,067.45		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment:	10/06/2019	
Date Inspected:	10/06/2019	Inspected At: 385 Sin Ming Drive #01-02 Singapore 575718
Estimated Period of Repair:	6.0 days	Repairer: Team Autopro Pte Ltd

Adjuster: Lim Teow Guan**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,685.50 FL	*1,285.20 FL
2	1		*TAILGATE LOGO	Necessary	75.80 FL	*33.80 FL
3	1		*TAILGATE EMBLEM HYUNDAI	Necessary	48.30 FL	*35.80 FL
4	1		*TAILGATE OUTER GARNISH	Not Necessary	132.50 FL	*- FL
5	1		*TAILGATE INNER TRIM BOARD	Not Necessary	253.10 FL	*- FL
6	1		*TAILGATE INNER HANDLE	Not Necessary	45.00 FL	*- FL
7	1		*TAILGATE LOCK ASSY	Not Necessary	128.30 FL	*- FL
8	1		*TAILGATE STRIKER	Not Necessary	65.00 FL	*- FL
9	1		*REAR BUMPER	Dented	388.30 FL	*388.30 FL
10	2		*REAR BUMPER SIDE RETAINER	Necessary	130.60 FL	*42.00 FL
11	3		*REAR BUMPER BRACKET	Not Necessary	255.75 FL	*- FL
12	1		*REAR WINDSCREEN MOULDING	Necessary	182.90 FL	*107.30 FL
13	1		*TAILLAMP RH	Not Necessary	488.50 FL	*- FL
14	1		*TAILLAMP LH	Not Necessary	488.50 FL	*- FL
15	1		*TAIL LAMP LOWER GARNISH RH	Not Necessary	71.90 FL	*- FL
16	1		*TAIL LAMP LOWER GARNISH LH	Not Necessary	71.90 FL	*- FL
17	1		*TAILLAMP BRACKET LH	Not Necessary	64.80 FL	*- FL
18	1		*TAILLAMP BRACKET RH	Not Necessary	64.80 FL	*- FL
19	1		*TAILGATE STICKER 70KM/H	Necessary	30.00 FS	*30.00 FS
20	2		*REAR BUMPER REVERSE SENSOR	Short Circuit	300.00 FS	*200.00 FS
21	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	180.00 FS	*- FS
22	1		*REAR WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,311.45	2,122.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	928.29	378.48
Total Parts (\$\$)	4,383.16	1,743.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR WINDSCREEN.	New	200.00	120.00
2	R&R REVERSE SENSOR.	New	100.00	60.00
3	R&R TAILGATE COMPONENT.	New	150.00	100.00
4	R&R REAR WINDSCREEN WIPER COMPONENT.	New	100.00	0.00
5	R&R WIRE HARNESS TO FACILITATE REPAIR, RECONNECT AND CHECK FUNCTION.	New	100.00	50.00
6	PANEL BEAT.	New	1,200.00	800.00
7	SPRAY PAINTING.	New	1,200.00	800.00
8	RUST PROOFING.	New	200.00	60.00
Gross Labour Cost (\$\$)			3,250.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >