

SJE :

Date of Survey :

10/6/19

Date of ReSurvey:

13/6/19

After-Paint:

Contacts :

Vehicle Nos : **GBB 4965E**

Model : Hyundai Starex

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,685.50	\$1,285.20 1,685.50
2	Tailgate logo	1	\$ 75.80	\$ 33.80 75.80
3	Tailgate emblem 'Hyundai'	1	\$ 48.30	\$ 35.90 48.30
4	Tailgate outer garnish	1	\$ 132.50	\$ 132.50
5	Tailgate inner trim board	1	\$ 253.10	\$ 253.10
6	Tailgate inner handle	1	\$ 45.00	\$ 45.00
7	Tailgate lock assy	1	\$ 128.30	\$ 128.30
8	Tailgate striker	1	\$ 65.00	\$ 65.00
9	Rear bumper	1	\$ 388.30	\$ 388.30 ✓ 388.30
10	Rear bumper side retainer	2	\$ 65.30	\$ 42.80 130.60
11	Rear bumper bracket	3	\$ 85.25	\$ 255.75
12	Rear windscreen moulding	1	\$ 182.90	\$ 107.30 182.90
13	Taillamp rh	1	\$ 488.50	\$ 488.50
14	Taillamp Lh	1	\$ 488.50	\$ 488.50
15	Tail lamp lower garnish Rh	1	\$ 71.90	\$ 71.90
16	Tail lamp lower garnish Lh	1	\$ 71.90	\$ 71.90
17	Taillamp bracket Lh	1	\$ 64.80	\$ 64.80
18	Taillamp bracket Rh	1	\$ 64.80	\$ 64.80
Parts Sub Total :				\$1892.40 4,641.45
20% Discount:				\$ 378.48 928.29
PARTS TOTAL :				\$1513.92 3,713.16

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Tailgate sticker '70km/h'	1	\$ 30.00	\$ 30.00
2	Rear bumper reverse sensor	2 1	\$ 300.00	\$ 200.00 300.00
3	Rear windscreen inner seal	1	\$ 180.00	\$ 180.00
4	Rear windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
5	Sundries	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :				\$ 230.00 160.00

Nos.	LABOUR	S\$
1	R&R Rear windscreen	\$ 120.00 200.00
2	R&R reverse sensor	\$ 60.00 100.00
3	R&R tailgate component	\$ 100.00 150.00
4	R&R rear windscreen wiper component	\$ 100.00
5	R&R wire harness to facilitate repair, reconnect and check function	\$ 50.00 100.00
6	Panel beat	\$ 800.00 1,200.00
7	Spray painting	\$ 800.00 1,200.00
8	Rust proofing	\$ 60.00 200.00
LABOUR TOTAL :		\$1990.00 3,250.00

PARTS TOTAL : \$ 3,713.16

SPECIAL NETT TOTAL : \$ 160.00

LABOUR TOTAL : \$ 3,250.00

GRAND TOTAL : \$ 7,123.16

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey on 13/6/19

1770 hrs

Lump sum repair

Repair days 6

Parts 1513.92

S/N 230.00

Labour 1990.00

3733.92

@ 20% 746.78

2987.14

L/s 2,950/2

TG Lim

19/7/19