

INSURANCE

INS. CASE OWNER:

CC 3 /AIG190

10292, E H639

LKK:  
IDAC:

Surveyor:

STEVE

DOI:

ASSIGNMENT

12/6/14

Date / Time:

11/6/14

Registered in Merimen:

11/6/14

Pre-assign / CCU / FTE



Insured Vehicle No.

GBG 49322

Name of Insured

MASTER & WHEEL 61 PLU

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

8/6/14

Is driver the owner?

( YES / NO )

Nature of Accident :

If NO, Driver Name / Age :

UM THAM CHYER PETER

Driver Tel No. :

(VL: YES / NO )

Claim No. :

365460656356

Policy No. :

130007498

Make / Model :

TOYOTA

Place of Accident :

21 KAPU PT PLACE

OI GIA REPORT: YES / NO :

TP GIA REPORT: YES / NO

Insured Liability :

% Final ? Yes / No

SLZ 555T



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

performance



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

25/7/14

SLZ 555T - 8

GBG 49322 - 8

\* TP 400 in.

File pass to shupen to close

Performance  
Motor  
BOSS.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

19/7/14

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/p

SS 6,887.95

( 5 days) Reduction:

36 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

22/7/14

Confirm with:

caroline

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : NIL

Repair Cost:

(w/GST)

SS 7,370.11

Loss of Rental (LOR):

SS -

( - days)

Loss of Use (LOU):

SS 500

(S 100 x 5 days)

Loss of Income (LOI):

SS -

(S - x - days)

LOR only ☐

LOU only ☒

LOR + LOU ☐

LOR + LO ☐

[Tick only one]

GIA/LTA Search:

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent )

Legal Cost:

SS -

Total:

SS 7,870.11

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 7,870.11

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$ 320

CTP REVERSE HIT OI DOOR

ALREADY OPEN

(AIG APPROVED)

COPIES SENT

Steve

REF A161

# ASSIGNMENT

From:

Date: 12.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SC2555T

at Workshop n/s Performance Motor

of 303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: VIP Mummy

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SC2555T

Yr Regr: 21/11/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer or

Make: BMW X5

c.c. 2998

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 4278

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBACR 62040LB11653

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 275/42R21

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front:

Rear:

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

8/6/19

D.O.I.

12/6/19

Survey held at:

Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-300K

CP/p\$ 6,887.95 / Rd\$ 3,900.82 / 36% )

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

2 + RS. 51

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

## Performance Motors Limited

a Sime Darby Motors Company  
 Co. Reg. No. 197401115W GST Reg. No. W2-0020081-X  
 Toll-Free Number: (1800-2255289)



101, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax: 64747770

280, Kampong Alam Road  
 East Coast Centre  
 Singapore 438140  
 Fax: 63449773

115, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax: 64794801 (AfterSales)  
 64794824 (Motorcar)

Store (LKK)

VL  
 P/P

12/6/19, 10.30am  
 GST REG. NO : M2 - 0020081 - X

CAR IN

11 JUN 2019

Reg before spray ESTIMATE  
 5 day

Estimate No. : b1 51521  
 Date Estimated : 11/06/2019  
 Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
 Performance Motors Limited  
 303 Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941

- ACCOUNT - 121  
 AIG Asia Pacific Insurance Pte. Ltd.  
 78 Shenton Way  
 #08-16 Chartis Building  
 Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SC2555T	LB11653	21/01/2019	X5 xDrive40i	0

## DESCRIPTION

To replace rear left door, attachments, repair b pillar and repair front left door.

✓ 1700 3,400.00

Painting rear left door, front left door and B pillar.

✓ 1868 3,114.00

To check electrical wiring systems

✓ 150 177.00

To carry out body cavity preservation.  
 (Per panel).

✓ 100 118.00

Sundries

New

✓ 80.00

Total Labour 1: 5,889.00

## DESCRIPTION

Door hinge, X - DO 2005  
 Door hinge, X - DO 2005  
 REAR LH DOOR  
 REAR DOOR BR  
 REAR LH DOOR WINDOW GUIDE X FA 2005 TN  
 REAR LH DOOR SIDE WINDOW FIXED Y ME  
 REAR LH DOOR WINDOW FRAME C COLUMN  
 Cover, windo  
 Weatherstrip X FA NN  
 LH C PILLAR SEAL  
 Door weather

QTY	PRIC	VALUE
1	57.15	✓ 57.15
1	58.60	✓ 58.60
1	2,262.50	✓ 2,262.50
1	101.15	✓ 101.15
1	267.80	✓ 267.80
1	435.85	✓ 435.85
1	112.65	✓ 112.65
1	309.70	✓ 309.70
1	47.95	✓ 47.95
1	33.70	✓ 33.70
1	195.65	✓ 195.65

Total Parts : 3,882.70

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559K GST Reg. No. M2-0020081-X  
Toll-Free Number: (800-2251265)

101, Alexandra Road  
Sime Darby Performance Centre  
Singapore 119943  
Fax: 67477775

140, Kampong Arang Road  
East Coast Centre  
Singapore 439180  
Fax: 63447775

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796001 (AfterSales)  
64796034 (MotorRep)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 51521  
Date Estimated : 11/06/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCZ555T	LB11653	21/01/2019	X5 xDrive40i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,889.00
Parts	:	3,882.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	754.02
Grand Total	:	11,525.72

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559N, GST Reg. No. M2-000001-X



## SUPPLEMENTARY

Estimate No : b1 51521  
Date Estimated : 11/06/2019  
Prepared By : Inthiran A/L. Thurasamy

Page No. :

REPAIR FOR -  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
  
Singapore 159941

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MLEAGE
SCZ555T	LB11653	21/01/2019	X5 xDrive40i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLIP * <i>1/c</i>	3.30	5.00		✓ 16.50

Total Labour :	
Total Parts :	16.50
Total Labour & Parts :	16.50

## FINAL REPORT



Estimate No. : b1 51521  
Date Estimated : 11/06/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE		
SC2555T	LB11653	21/01/2019	X5 xDrive40i	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear LH door and attachments include making good the LH 'B' pillar and knocking out dents caused by the accident	1700.00		1,700.00	✓		
To spray paint rear LH door and LH 'B' pillar	1868.00		1,868.00	✓		
To check electrical wiring systems and lightings at the LH section for proper function	150.00		150.00	✓		
To carry out body cavity preservation (Per panel)	100.00		100.00	✓		
Sundries	80.00		80.00	✓		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT		
REAR LH DOOR	2,262.50	1.00		2,262.50	✓	
REAR DOOR BRAKE *	101.15	1.00		101.15	✓	
REAR LH DOOR WINDOW GUIDE	267.80	1.00		267.80	✓	
REAR LH DOOR WINDOW FRAME C COLUMN	112.65	1.00		112.65	✓	
# CLIP *	3.30	5.00		16.50	✓	
LH C PILLAR SEAL	33.70	1.00		33.70	✓	
(S/L) DOOR WEATHERSTRIP *	195.65	1.00		195.65	✓	

### # SUPPLEMENTARY ITEMS

Total Labour :	3,898.00
Total Parts :	2,989.95
Total Labour & Parts :	6,887.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,887.95
GST @7%:	482.16
Grand Total :	7,370.11

## Khanchna (LKK Auto)

---

**From:** Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>  
**Sent:** Thursday, 13 June 2019 9:16 AM  
**To:** Khanchna (LKK Auto)  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** RE: YR REF: GBG4932Z [ACCIDENT INVOLVING GBG4932Z (OI) & SCZ555T (TP) ON 8/6/2019]

Dear Khanchna,

Kindly proceed as proposed, in view that there is no evidence to show that the door was just opened when insured driver is reversing.

Thank you.

**Best Regards,**

**Bernard Ler**  
**AIG**  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]  
**Sent:** 12 June 2019 18:04  
**To:** Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>  
**Cc:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** [EXTERNAL] YR REF: GBG4932Z [ACCIDENT INVOLVING GBG4932Z (OI) & SCZ555T (TP) ON 8/6/2019]

This message is from an external sender; be cautious with links and attachments.

YOUR REF: GBG4932Z  
OUR REF: CC3/AIG19010292/KB3

Dear Bernard,

The above matter refers.

Insured reported that whilst reversing his vehicle to park he did not see Third party vehicle door was open.

Whereas, Third party reported that his vehicle door was open and Insured reversed to park and hit the Third party vehicle door.

Based on all the documents at hand, we note that the collision occurred when Insured driver reversed to park and collided into Third party's vehicle door which was already open.

We have contacted and spoken with Insured (company representative: Mr. Wee), whom confirmed the accident and agreed to settle.

We have also reviewed the matter and opine that liability is not in our Insured's favour because Insured driver in his statement stated that he did not see the Third party vehicle door was already open whilst reversing his m/vehicle to park and hit the Third party vehicle door.

Please refer to the Insured's GIA sketch & statement below for your easy reference.



A: G8G4932  
B: S0255T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I notice vehicle B was parked at the lot I slowly reversed along the driveway I did not see vehicle B rear left door was open. While in the midst of reversing suddenly I hear a sound, I immediately stop & come down to check, then realised that vehicle B has his rear left door opened & hit against it.

DECLARATION

I HEREBY DECLARE that:

1. The reporting herein presented has explained the above statement & sketch also shown.
2. I fully understand and agree with the above statement.
3. The information given is true and correct to best of my own knowledge and belief.

*Peter*  
Name, Signature & Company  
Date of completion

INSURER: AIG.

VEHICLE: G8G4932

DOA: 8/6/19.


CLAIM TYPE: Repair

WORKSHOP: N/A

Kindly refer to the Third party's GIA sketch & statement below as well:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The XS was parked in front of the shop.
The rear left door was open as my wife
put my son in his child seat.
The truck, driven by LIM THIAM CHYE PETER
reversed into the lot next to the XS.
The truck hit the rear left door of the
stationary XS, damaging it.

In view of this, we propose to resolve this matter amicably at 100% basis.

Appreciate your views/instruction please.

Thank you.

\*FYI: Third party is the Workshop Agent's boss.

Best Regards,  
**Khanchna** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
 DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108  
 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1<sup>ST</sup> JUNE 2008  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	SC2555T	<b>Model:</b>	BMW
<b>Date of Accident:</b>	8-6-2019		

<b>Global Sum Settlement:</b>	<input type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Repair Estimate</b>	: \$	11525.72
<b>Final Repair Cost</b>	: \$	7370.11
<b>Loss of Use</b>	: \$	600.00
<b>Rental (if any)</b>	: \$	
<b>LTA / GIA Search Fee</b>	: \$	
<b>Others</b>	: \$	
	: \$	
<b>Final Settlement Sum</b>	: \$	7970.11

**Is Third Party Workshop GIA Registered?** ☐ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No  
BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

**Payment Instruction: Payee's Breakdown**

1)	Performance Motor Limited	: \$	7370.11
2)	Performance Motor Ltd	: \$	600.00
3)		: \$	

\_\_\_\_\_  
Signed by appointed surveyor

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.

Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;  
Survey Report; Medical Report / Bill (if any)

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Monday, 22 July 2019 11:46 AM  
**To:** PBSP  
**Cc:** Admin A  
**Subject:** OFFER - RE: FINAL REPORT/ SCZ555T & GBG 4932Z [AIG] ON 8/6/2019

OUR REF: CC3/AIG19010292/Ekb3

**Without Prejudice**  
**(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 7,370.11
2. Loss of Use(5days x \$100.00)	\$ 500.00
<b>TOTAL</b>	<b>\$ 7,870.11</b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,  
**Khanchna** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Monday, 1 July 2019 5:07 PM  
**To:** Steve Chen (LKK Auto) <SteveChen@lkkauto.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>  
**Subject:** FINAL REPORT/ SCZ555T

Dear Khanchna and Steve

We refer to the above and attached Final Report.

Total Labour : 3,898.00  
Total Parts : 2,989.95  
Total Labour & Parts : 6,887.95

Repair days: 5

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## **Khanchna (LKK Auto)**

---

**From:** Khanchna (LKK Auto)  
**Sent:** Wednesday, 12 June 2019 5:19 PM  
**To:** wong@castorwheel.com  
**Subject:** ACCIDENT INVOLVING GBG4932Z & SCZ555T ALONG 29 KAKI BT PLACE ON 08/06/2019

Our Ref: CC3/AIG19010292/kb3

Your Ref: GBG4932Z [Driver: LIM THAM CHYE PETER]

**CASTOR & WHEEL SINGAPORE PTE LTD**

**Attn: Mr. Wong**

Dear Sir/Madam,

### **ACCIDENT INVOLVING GBG4932Z [AIG] & SCZ555T ALONG 29 KAKI BT PLACE ON 08/06/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, **AIG Asia Pacific Insurance Pte Ltd** to deal with the third party claim against your policy.

We have received a claim from SCZ555T against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

I, Performance Motors Ltd ("the third party claimant")  
of 303 Alexandra Road S(159441) (address),  
owner of SC2555T (vehicle no.) hereby authorize  
Performance Motors Ltd  
("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SC2555T that was  
damaged pursuant to the accident which occurred on 8.6.2019 (date) along  
29 Kaki Bukit Plaza (location)  
involving vehicle no/s GBG 49322 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 08 day of 06 (month) 20 19 (year)

  
PERFORMANCE MOTORS LIMITED  
303 Alexandra Road  
Singapore 159441  
Tel: 6733 8100 (Main)  
6733 8111 (Fax)

Signed by "the third party claimant"

  
Signature of the workshop  
Name of the workshop  
Address of the workshop  
Singapore 1111

Signed by "the workshop"



**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd, LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 7,370.11 (repair costs), S\$ 500.00 (loss of use/rental) S\$ - (search fees) for vehicle no. SC2555T that was damaged pursuant to the accident which occurred on 8-6-19 (date) along 29 Kaki Bukit Plaza (location) involving vehicle no/s GGG 49222.

This is pursuant to the inspection conducted on 12-6-2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Performance Motors Ltd ("third party claimant") of vehicle no. SC2555T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SC2555T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23 day of JULY (month) 20 19 (year)



CTY

Signed by AIG appointed surveyor

PERFORMANCE MOTORS LTD  
203 Aljunied Road  
Singapore 10041  
TEL: 61122100 (Singapore)  
63190111 (Abroad)

*[Signature]*

Chopped & Signed by "the workshop"

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770288, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1369863	Page No. : 1 of 2
Date IN : 13/06/2019	Invoice Number : 2119850 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 05/07/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
  
Singapore 159941

- INVOICE TO - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO. SCZ555T	CHASSIS NO. LB11653	REGN. DATE 21/01/2019	MODEL X5 XDRIVE40I	MILEAGE 4305
----------------------	------------------------	--------------------------	-----------------------	-----------------

## - - - - LABOUR 1 - - - -

To replace rear left door and attachments including to make good the left 'B' pillar and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.

To respray rear left door and left 'B' pillar.

To check electrical wiring system and lighting at the left section for proper function.

To carry out body cavity preservation.

Sundries.

INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT.

DATE OF ACCIDENT : 8.6.2019. 3RD PARTY CAR : GBG4932Z.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK AUTO CONSULTANTS PTE LTD ON 12.6.2019 AT 10.39 AM. AUTHORISED REPAIR BY KHANCHNA FROM LKK ON 13.6.2019 VIA E-MAIL.

PROPOSE LOSS OF USE = \$ 120X5. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

NOTE : VEHICLE WAS DRIVEN BY PML MD - MR ARTT BAYER WHEN

TIME OF ACCIDENT.

NETT

1,700.00

1,868.00

150.00

100.00

80.00

0.00

0.00

0.00

Total Labour 1: 3,898.00

## - - - - PARTS - - - -

REAR LH DOOR

(S/L) DOOR WEATHERSTRIP

REAR DOOR BRAKE

CLIP

REAR LH DOOR WINDOW FRAME C COLUMN

REAR LH DOOR WINDOW GUIDE

LH C PILLAR SEAL

	Retail	
Qty	Price	

1 2,262.50

1 195.65

1 101.15

5 3.30

1 112.65

1 267.80

1 33.70

NETT

2,262.50

195.65

101.15

16.50

112.65

267.80

33.70

Total Parts : 2,989.95



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64787770288, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773319, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1369863</b>	Page No. : <b>2 of 2</b>
Date IN : <b>13/06/2019</b>	Invoice Number : <b>2119850 / WSB</b>
Cust. Svc. Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>05/07/2019</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

Labour Charges : <b>3,818.00</b>	Total Labour & Parts Charges : <b>S\$ 6,887.95</b>
Parts Charges : <b>2,989.95</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>80.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 6,887.95</b>
	GST @ 7% : <b>S\$ 482.16</b>
	Invoice Total Amount Include GST : <b>S\$ 7,370.11</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 7,370.11**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jun 2019 <a href="#">Edit Reg</a>		12 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$56,887.95</b> <a href="#">Edit Estimates</a>	<b>\$56,887.95</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>CASTOR &amp; WHEEL (SINGAPORE) PTE LTD</b> , Co. Reg. No.: 198300787H								
Main Claimant:	<b>PERFORMANCE MOTORS LTD</b> , Co. Reg. No.: 197401559W								
Vehicle Reg. No.:	<b>SCZ555T</b>	Date of Loss:	08/06/2019 12:00 - :59 [4 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 3654606563SG</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBG4932Z</b>	Policy No. (Claimant):	1320401Z						
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 20/06/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SCZ555T (3654606563SG)  
[GBG4932Z]  
TP  
PERFORMANCE MOTORS LTD  
Jun 8 2019 12:00PM  
[CASTOR & WHEEL (SINGAPORE) PTE LTD]  
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1		Edit			
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
2	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
3	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
4	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
5	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
6	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
7	12/06/19 19:33		Odometer Reading												1		Load JPG		<input checked="" type="checkbox"/>	
8	12/06/19 19:33		Chassis Number												1		Load JPG		<input checked="" type="checkbox"/>	
9	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
10	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
11	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
12	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
13	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
14	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
15	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
16	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
17	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
18	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
19	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
20	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
21	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
22	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
23	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
24	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
25	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
26	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
27	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
28	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
29	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
30	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
31	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
32	12/06/19 19:33		General View												1		Load JPG		<input checked="" type="checkbox"/>	
33	14/06/19 09:30		Reinspection Photo												1		Load JPG		<input checked="" type="checkbox"/>	
34	14/06/19 09:30		Reinspection Photo												1		Load JPG			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	14/06/19 09:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	14/06/19 09:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	19/06/19 08:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	19/06/19 08:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	19/06/19 08:39	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/19 17:20	TP ESTIMATE	Load PDF	
2	11/06/19 17:20	TP GIA REPORT	Load PDF	
3	12/06/19 17:19	EMAIL TO OI	Load PDF	
4	14/06/19 09:02	TP ESTIMATE- MARKED	Load PDF	
5	31/07/19 09:50	WORKSHOP INVOICE	Load PDF	
6	31/07/19 09:50	AUTHORISATION TO ACT FORM	Load PDF	
7	31/07/19 09:50	Release Voucher	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/19 11:00	OI GIA REPORT	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG4932Z (Insd veh)	Model:	BMW X5 3.0 XDRIVE35I (A)
	SCZ555T (TP veh)		
Date of Accident:	08/06/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	11,543.37
Final Repair Cost	:	\$	7,370.11
Loss of Use	:	\$	500.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,870.11

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_(%)

B) For **GIA Registered Workshop:** BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_100\_\_\_\_(%) Assessed Liability (\*): \_\_\_\_\_(%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 7,870.11
2)		:	\$

JOANNE LEE KHANG MIN

31 Jul  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sun@lkkauto.com](mailto:sun@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19010292/EKB3Q2

Date: 31/07/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SCZ555T

Insured Vehicle No : GBG4932Z

Date of Loss: 08/08/2019

Nature of Claim: TP

Claim No: 3654606563SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCZ555T

Make & Model: BMW X5, 3.0 xDrive35i (A)

Engine No: 16785382B58B30C

Reg. Date: 21/01/2019 (Man. Year: 2018)

Chassis No: WBACR62040LB11653

Colour: Blue

Odometer: 4278 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 275/40 R21

Rear Tyre Size:

275/40 R21

Front Left Side: Pirelli 7 mm

Rear Left Side:

Pirelli 7 mm

Front Right Side: Pirelli 7 mm

Rear Right Side:

Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,979.20	3,069.95	909.25	22.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,809.00	3,818.00	2,991.00	43.93
Paintwork/Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,788.20</b>	<b>6,887.95</b>	<b>3,900.25</b>	<b>36.15</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>755.17</b>	<b>482.16</b>	<b>273.01</b>	<b>36.15</b>
<b>Nett Amount (S\$)</b>	<b>11,543.37</b>	<b>7,370.11</b>	<b>4,173.26</b>	<b>36.15</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		<b>500.00</b>		
<b>Nett Liability (S\$)</b>		<b>7,870.11</b>		

### INSPECTION

Date of Assignment: 12/06/2019

Date Inspected: 12/06/2019 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*DOOR HINGE	Not Necessary	57.15 FS	*- FS
3	1		*DOOR HINGE	Not Necessary	58.60 FS	*- FS
4	1		*REAR LH DOOR	Dented	2,262.50 FS	*2,262.50 FS
5	1		*REAR DOOR BR	Necessary	101.15 FS	*101.15 FS
6	1		*REAR LH DOOR WINDOW GUIDE	Torn	267.80 FS	*267.80 FS
7	1		*REAR LH DOOR SIDE WINDOW FIXED	Not Necessary	435.85 FS	*- FS
8	1		*REAR LH DOOR WINDOW FRAME C COLUMN	Torn	112.65 FS	*112.65 FS
9	1		*COVER ,WINDO	Not Necessary	309.70 FS	*- FS
10	1		*WEATHERSTRIP	Not Necessary	47.95 FS	*- FS
11	1		*LH C PILLAR SEAL	Necessary	33.70 FS	*33.70 FS
12	1		*DOOR WEATHER	Torn	195.65 FS	*195.65 FS
13	5		*CLIP	Necessary	16.50 FS	*16.50 FS
Total Parts (S\$)					3,979.20	3,069.95

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR LEFT DOOR ,ATTACHMENTS ,REPAIR B PILLAR AND REPAIR FRONT LEFT DOOR	New	3,400.00	1,700.00
2	PAINTING REAR LEFT DOOR ,FRONT LEFT DOOR AND B PILLAR	New	3,114.00	1,868.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			6,809.00	3,818.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >