



FINAL REPORT

Estimate No. : b1 51521
Date Estimated : 11/06/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCZ555T	LB11653	21/01/2019	X5 xDrive40i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear LH door and attachments include making good the LH 'B' pillar and knocking out dents caused by the accident	1700.00		1,700.00 ✓
To spray paint rear LH door and LH 'B' pillar	1868.00		1,868.00 ✓
To check electrical wiring systems and lightings at the LH section for proper function	150.00		150.00 ✓
To carry out body cavity preservation (Per panel)	100.00		100.00 ✓
Sundries	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR LH DOOR	2,262.50	1.00		2,262.50 ✓
REAR DOOR BRAKE * <i>hcc</i>	101.15	1.00		101.15 ✓
REAR LH DOOR WINDOW GUIDE	267.80	1.00		267.80 ✓
REAR LH DOOR WINDOW FRAME C COLUMN	112.65	1.00		112.65 ✓
# CLIP *	3.30	5.00		16.50 ✓
LH C PILLAR SEAL	33.70	1.00		33.70 ✓
(S/L) DOOR WEATHERSTRIP *	195.65	1.00		195.65 ✓

SUPPLEMENTARY ITEMS

Total Labour :	3,898.00
Total Parts :	2,989.95
Total Labour & Parts :	6,887.95 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,887.95
GST @7%:	482.16
Grand Total :	7,370.11

Performance Motors Limited

A member of the Sime Darby Group
Co, Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 51521
Date Estimated : 11/06/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 159941

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCZ555T	LB11653	21/01/2019	X5 xDrive40i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLIP * / APC	3.30	5.00		16.50

Total Labour :	
Total Parts :	16.50
Total Labour & Parts :	16.50

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Steve (LKK)

P/P

GST REG. NO : M2 - 0020081 - X

Reg before spray ESTIMATE
5 days

CAR IN

11 JUN 2019

Estimate No. : b1 51521 Page No. : 1 of 5
Date Estimated : 11/06/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCZ555T	LB11653	21/01/2019	X5 xDrive40i	0

DESCRIPTION

To replace rear left door, attachments, repair b pillar and repair front left door.

1700 3,400.00

Painting rear left door, front left door and B pillar.

1860 3,114.00

To check electrical wiring systems

150 177.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries.

80.00

Total Labour 1: 6,889.00

DESCRIPTION

Door hinge, / DD
Door hinge, / DD
REAR LH DOOR / DD
REAR DOOR BR / EAF APC
REAR LH DOOR WINDOW GUIDE / TAI
REAR LH DOOR SIDE WINDOW FIXED / APC
REAR LH DOOR WINDOW FRAME C COLUMN ? / TAI
Cover, windo ?
Weatherstrip X EAF NIN
LH C PILLAR SEAL / APC
Door weather / TAI

QTY	PRIC	VALUE
1	57.15	57.15
1	58.60	58.60
1	2,262.50	2,262.50
1	101.15	101.15
1	267.80	267.80
1	435.85	435.85
1	112.65	112.65
1	309.70	309.70
1	47.95	47.95
1	33.70	33.70
1	195.65	195.65

Total Parts : 3,882.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 51521	Page No. : 2 of 5
Date Estimated	: 11/06/2019	
Prepared By	: Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCZ555T	LB11653	21/01/2019	X5 xDrive40i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour 1	:	6,889.00
Parts	:	3,882.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	754.02
Grand Total	:	<u>11,525.72</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **