



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLQ 340 L

*Not Authorized
Resurvey Blowing*

Parts	(a) Cost / List Price Items	\$	7,867.65
	Plus/Less 25%	\$	1,966.91
	Total of Cost / List	\$	5,900.74
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	5,900.74
Labour		\$	3,360.00
Total		\$	9,260.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

11/6/11

at *16:30*

Remarks By Surveyor

(a) The repair of this vehicle is *not* authorized / is not authorized until further notice.

(b) Recommended Days of Repair : *04* day(s)

(c) Resurvey : Required / *Not Required*

(d) Excess : \$

(e) Signature of surveyor

De

Date: *11/6/11*



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLQ 340 L

TOYOTA PRIUS

JTDKB3FU303560740

Submit By :
Year Manufacture :
Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (arm)	1			
2	RH wing mirror (signal lamp)	1	\$1,374.20		✓
3	RH wing mirror (glass)	1			
4	RH wing mirror (cover)	1	\$87.40		✓
5	RH front door	1	\$1,121.75		✓
6	RH front door hinge top	1	\$78.30		X
7	RH front door hinge bottom	1	\$78.30		X
8	RH front door lock	1	\$470.33		X
9	RH front door catch	1	\$43.95		X
10	RH front door checker	1	\$130.70		X
11	RH front door weatherstip	1	\$211.69		X
12	RH front door trim	1	\$856.90		X
13	RHF door glass outer moulding	1	\$121.75		✓
14	RHF door centre pillar garnish	1	\$78.50		✓
15	RH rear door	1	\$1,211.40		X
16	RH rear door hinge top	1	\$78.34		X
17	RH rear door hinge bottom	1	\$78.34		X
18	RH rear door lock	1	\$425.63		X
19	RH rear door catch	1	\$37.80		X
20	RH rear door checker	1	\$126.70		X
21	RH rear door weatherstip	1	\$212.47		X
22	RH rear door trim	1	\$856.90		X
23	RHR door glass outer moulding	1	\$107.80		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLQ 340 L
Make & Model : TOYOTA PRIUS
Chassis No. : JTDKKB3FU303560740

Submit By : Carmen Lim

Year Manufacture : 2017

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RHR door centre pillar garnish <i>Sen</i>	1	\$78.50		✓
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Labour

Vehicle No. : SLQ 340 L Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RHF DOOR,RHR DOOR,RHR FENDER, RHF FENDER,RHS MIRROR)	\$1,000.00	4001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RHF DOOR,RHR DOOR,RHR FENDER, RHF FENDER,RHS MIRROR)	\$1,200.00	6001
3	To check Wiring	\$50.00	201
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	801
5	To remove & refit RHF door glass & RHR door glass	\$240.00	601
6	To do wheel alignment <i>nn</i>	\$120.00	X
7	To remove & refit inner seat & upholstery to assist work load. <i>nn</i>	\$250.00	X
8	To tuff coat.	\$200.00	601
9	Towing	\$120.00	501

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.