

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date :04/06/2019

Reference: CHEVROLET

Make: CRUZE

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SJZ6694C
CHASSIS NO.: KL1JA6961BK055381
ENGINE NO.: F16D37806171

Name of insured : TAN HWA LEONG

Date of accident.: 01.06.2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>new</i>	\$ 1,650.00
2	1	FRT BUMPER <i>Delint</i>	\$ 1,096.00
3	1	FRT BUMPER TOW COVER <i>new</i>	\$ 94.00
4	1	FRT BUMPER LOGO <i>new</i>	\$ 204.00
5	1	FRT NUMBER PLATE BASE <i>Delint</i>	\$ 40.00
6	1	FRT BUMPER SIDE RETAINER LH <i>new</i>	\$ 86.00
7	1	FRT BUMPER SIDE RETAINER RH <i>new</i>	\$ 86.00
8	1	FRT BUMPER SPONGE <i>new</i>	\$ 140.00
9	1	FRT BUMPER REINFORCEMENT <i>new</i>	\$ 1,030.00
10	1	FRT SUPORT PANEL TOP GARNISH <i>new</i>	\$ 227.00
11	1	FRT GRILLE UPP <i>new</i>	\$ 352.00
12	1	FRT GRILLE LOW <i>new</i>	\$ 526.00
13	1	RH HEADLAMP <i>new</i>	\$ 865.00
14	1	LH HEADLAMP <i>new</i>	\$ 865.00
15	1	A/C CONDENSER	\$ 1,052.00
16	1	INTAKE AIR DUCT AIR HOSE(air duct to resonator box) <i>new</i>	\$ 224.00
17	1	FRT FOG LAMP LH <i>new</i>	\$ 298.00
18	1	FRT FOG LAMP COVER LH <i>new</i>	\$ 130.00
19	1	FRT FOG LAMP RH <i>new</i>	\$ 298.00
20	1	FRT FOG LAMP COVER RH <i>new</i>	\$ 130.00

1512
1360.80

Parts Total: \$ 9,393.00
Less 10%: \$ 939.30
Total : \$ 8,453.70

Labour

No.

Labour Description

Price (SGD)

1		To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00	200
2		Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL	\$ 1,000.00	200
3		To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	30
4		To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 200.00	+

430

Labour Total : \$ 2,320.00

Others

Other Description

No.			Price (SGD)	
1	10	FRT BUMPER CLIP <i>na</i>	\$ 40.00	50
2	10	FRT GRILLE CLIP <i>na</i>	\$ 40.00	+
3	1	FRT NUMBER PLATE <i>Best</i>	\$ 65.00	50

80

Other Total: 145.00

TOTAL: 10,918.70

GRAND TOTAL : 10,918.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Kelvin Chew
HP: 8292 5595 Fax: 68445185

Adrian L
H/c 10/06/19
03 Days
total: 1870.80
H/S: 1.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: