

No.	Qty	Part Description	Price (SGD)
1	1	Bonnet	\$ 1,758.00
2	1	LH Bonnet Hinge	\$ 54.00
3	1	RH Bonnet Hinge	\$ 54.00
4	1	Bonnet Latch	\$ 220.00
5	1	LHF Headlamp	\$ 4,314.00
6	1	RHF Headlamp	\$ 4,314.00
7	1	Front Radiator Grille Moulding, Base	\$ 734.00
8	1	Front Radiator Grille Chrome Moulding - RH	\$ 218.00
9	1	Front Radiator Grille Chrome Moulding - LH	\$ 218.00
10	1	Front Opel Emblem	\$ 160.00
11	1	Front Bumper	\$ 1,994.00
12	1	Front Bumper Lower Grille	\$ 202.00
13	1	Front Bumper Towing Cover	\$ 28.00
14	1	LHF Foglamp Cover	\$ 120.00
15	1	LHF Foglamp	\$ 434.00
16	1	RHF Foglamp Cover	\$ 120.00
17	1	RHF Foglamp	\$ 434.00
18	1	Front Bumper Absorber	\$ 154.00
19	1	Front Bumper Reinforcement Bar	\$ 798.00
20	1	LHF Bumper Bracket - Guide	\$ 38.00
21	1	RHF Bumper Bracket - Guide	\$ 38.00
22	1	Rear Tailgate	\$ 2,928.00
23	1	Lettering "ASTRA"	\$ 74.00
24	1	Lettering "ECOFLEX"	\$ 112.00
25	1	Rear Windscreen With Moulding	\$ 1,138.00
26	1	LHR Tailgate Lamp	\$ 666.00
27	1	RHR Tailgate Lamp	\$ 666.00
28	1	Tailgate Inner Trim Board	\$ 212.00

29	1	Rear Wiper Motor		\$	928.00	*
30	1	Rear Tailgate Latch		\$	340.00	x
31	1	Rear Tailgate Striker	new	\$	46.00	x
32	1	LHR Taillamp	cracked	\$	618.00	x
33	1	RHR Taillamp	new	\$	618.00	x
34	1	Rear Bumper Upper	del	\$	2,886.00	x
35	1	Rear Bumper Lower	del	\$	362.00	x
36	1	Rear Bumper Towing Cover	new	\$	44.00	x
37	1	LHR Bumper Reflector	cracked	\$	48.00	x
38	1	RHR Bumper Reflector	new	\$	48.00	x
39	1	Rear Number Plate Lamp	new	\$	22.00	x
40	1	Rear Bumper Reinforcement Bar	But-	\$	716.00	x
41	1	Rear Bumper Air Ventilator	cracked	\$	36.00	x
42	1	LHR Bumper Bracket, Guide	3 new	\$	54.00	x
43	1	RHR Bumper Bracket, Guide	3 new	\$	54.00	x
44	1	LHR Bumper Bracket	new	\$	26.00	x
45	1	RHR Bumper Bracket	new	\$	26.00	x
46	1	Rear Bumper Bracket Centre	new	\$	60.00	x
47	1	Rear End Panel	del	\$	816.00	x
48	1	Rear End Panel Trim	del	\$	196.00	x

13910
12519.

Parts Total: \$ 30,144.00
Less 10%: \$ 3,014.40
Total: \$ 27,129.60

Labour

Labour Description

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$	1,950.00	650
2	Carry out spray painting on accident affected area (\$550 per panel)	\$	2,750.00	550
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$	325.00	50
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$	700.00	x
5	To refocus headlamp	\$	130.00	x
6	To remove and refit front sensor	\$	130.00	60

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$	3,900.00	1300
2	Carry out spray painting on accident affected area (\$550 per panel)	\$	3,250.00	1100
3	To conduct anti rust of under carriage tuff coat	\$	130.00	x
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$	130.00	30
5	To remove and refix reverse sensor and conduct test	\$	130.00	60
6	To remove and refix reverse camera and conduct test	\$	130.00	60
7	To conduct transfer of parts from old tailgate to new tailgate	\$	325.00	150
8	To conduct water leakage test after repairs of vehicle	\$	130.00	x

4010

Labour Total: \$ 14,110.00

Others

Other Description

No.	Qty		Price (SGD)	
<u>Front portion</u>				
1	1	Number plate with casement <i>new</i>	\$ 45.00	+
2	10	Front bumper clip <i>new</i>	\$ 65.00	50
3	10	Bonnet insulator clip <i>new</i>	\$ 65.00	+
4	2	Front sensor(1 set) <i>new</i>	\$ 264.00	+
<u>Rear portion</u>				
1	1	Rear number plate <i>cracked</i>	\$ 45.00	✓
2	10	Rear bumper clip <i>new</i>	\$ 65.00	50
3	10	Tailgate insulator clip <i>new</i>	\$ 65.00	+
4	6	Rear fender liner clips <i>new</i>	\$ 39.00	+
5	6	Rear end panel trim clip <i>new</i>	\$ 39.00	7.
6	1	Reverse sensor (1 set) <i>new 2nd</i>	\$ 440.00	✓
7	1	Rear reverse camera <i>new</i>	\$ 230.00	✓
8	1	Rear end panel insulation seal <i>new</i>	\$ 120.00	+
9	10	Tail gate inner trim board clip <i>new</i>	\$ 65.00	+
10	1	Tailgate windscreen sealant <i>new</i>	\$ 120.00	60
11	1	Tailgate windscreen solar film <i>new</i>	\$ 250.00	+
12	1	Rear Spoiler Sealant <i>new</i>	\$ 120.00	60
935			Other Total: \$	2,037.00

Total: \$ 43,276.60
 GST 7%: \$ 3,029.36
 GRAND TOTAL: \$ 46,305.96

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

 Suhaimi Ong

Service Executive
 Suhaimi Ong
 HP : 8298 8933 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lij
P/P 26 days
10/06/15.
Supplementary 2569.50
total: 20033.50 (P/P)

VEHICLE NO: 9LS 8336L

VEHICLE NO: 9LS 8336L

[illegible]

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 7/6/2019

Reference: SLS8336L
OPEL ASTRA
Make: HB 1.0 AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLS8336L
CHASSIS NO.:W0LB6EA7HG169903
ENGINE NO.:B1171437HRXX0515

Name of insured :Lim Wen Shien
Date of accident.: 31/05/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	Bonnet	\$ 1,758.00	x
2	1	LH Bonnet Hinge	\$ 54.00	+
3	1	RH Bonnet Hinge	\$ 54.00	+
4	1	Bonnet Latch	\$ 220.00	+
5	1	LHF Headlamp	\$ 4,314.00	+
6	1	RHF Headlamp	\$ 4,314.00	+
7	1	Front Radiator Grille Moulding, Base	\$ 734.00	?
8	1	Front Radiator Grille Chrome Moulding - RH	\$ 218.00	?
9	1	Front Radiator Grille Chrome Moulding - LH	\$ 218.00	?
10	1	Front Opel Emblem	\$ 160.00	?
11	1	Front Bumper	\$ 1,994.00	✓
12	1	Front Bumper Lower Grille	\$ 202.00	+
13	1	Front Bumper Towing Cover	\$ 28.00	+
14	1	LHF Foglamp Cover	\$ 120.00	+
15	1	LHF Foglamp	\$ 434.00	+
16	1	RHF Foglamp Cover	\$ 120.00	+
17	1	RHF Foglamp	\$ 434.00	+
18	1	Front Bumper Absorber	\$ 154.00	?
19	1	Front Bumper Reinforcement Bar	\$ 798.00	?
20	1	LHF Bumper Bracket - Guide	\$ 38.00	✓
21	1	RHF Bumper Bracket - Guide	\$ 38.00	✓
22	1	Rear Tailgate	\$ 2,928.00	✓
23	1	Lettering "ASTRA"	\$ 74.00	✓
24	1	Lettering "ECOFLEX"	\$ 112.00	✓
25	1	Rear Windscreen With Moulding	\$ 1,138.00	?
26	1	LHR Tailgate Lamp	\$ 666.00	x
27	1	RHR Tailgate Lamp	\$ 666.00	x
28	1	Tailgate Inner Trim Board	\$ 212.00	x

29	1	Rear Wiper Motor	?			
30	1	Rear Tailgate Latch	?		\$ 928.00	x
31	1	Rear Tailgate Striker	new		\$ 340.00	x
32	1	LHR Taillamp			\$ 46.00	+
33	1	RHR Taillamp			\$ 618.00	+
34	1	Rear Bumper Upper	3 Del d		\$ 618.00	x
35	1	Rear Bumper Lower			\$ 2,886.00	L
36	1	Rear Bumper Towing Cover	new		\$ 362.00	✓
37	1	LHR Bumper Reflector	?		\$ 44.00	x
38	1	RHR Bumper Reflector	new		\$ 48.00	?
39	1	Rear Number Plate Lamp	new		\$ 48.00	x.
40	1	Rear Bumper Reinforcement Bar	?		\$ 22.00	x
41	1	Rear Bumper Air Ventilator	?		\$ 716.00	?
42	1	LHR Bumper Bracket, Guide	?		\$ 36.00	?
43	1	RHR Bumper Bracket, Guide	?		\$ 54.00	?
44	1	LHR Bumper Bracket	new		\$ 54.00	✓
45	1	RHR Bumper Bracket	new		\$ 26.00	✓
46	1	Rear Bumper Bracket Centre	new		\$ 26.00	✓
47	1	Rear End Panel	?		\$ 60.00	✓
48	1	Rear End Panel Trim	?		\$ 816.00	?
					\$ 196.00	?

Parts Total: \$ 30,144.00

Less 10%: \$ 3,014.40

Total: \$ 27,129.60

Labour

No.	Labour Description	Price (SGD)
Front portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 1,950.00 650
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 2,750.00 550
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 325.00 50
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 700.00 x
5	To refocus headlamp	\$ 130.00 +
6	To remove and refit front sensor	\$ 130.00 60
Rear portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 3,900.00 1300
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 3,250.00 1100
3	To conduct anti rust of under carriage tuff coat	\$ 130.00 x
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 130.00 30
5	To remove and refix reverse sensor and conduct test	\$ 130.00 60
6	To remove and refix reverse camera and conduct test	\$ 130.00 60
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 325.00 150
8	To conduct water leakage test after repairs of vehicle	\$ 130.00 x

Labour Total: \$ 14,110.00

OthersOther DescriptionNo. QtyPrice (SGD)Front portion

1	1	Number plate with casement <i>new</i>	\$ 45.00	+
2	10	Front bumper clip <i>new</i>	\$ 65.00	50
3	10	Bonnet insulator clip <i>new</i>	\$ 65.00	+
4	2	Front sensor(1 set) <i>new</i>	\$ 264.00	+

Rear portion

1	1	Rear number plate <i>cracked</i>	\$ 45.00	✓
2	10	Rear bumper clip <i>new</i>	\$ 65.00	50
3	10	Tailgate insulator clip <i>new</i>	\$ 65.00	+
4	6	Rear fender liner clips <i>new</i>	\$ 39.00	+
5	6	Rear end panel trim clip <i>?</i>	\$ 39.00	?
6	1	Reverse sensor (1 set) <i>new</i>	\$ 440.00	+
7	1	Rear reverse camera <i>?</i>	\$ 230.00	?
8	1	Rear end panel insulation seal <i>new</i>	\$ 120.00	+
9	10	Tail gate inner trim board clip <i>new</i>	\$ 65.00	+
10	1	Tailgate windscreen sealant <i>new</i>	\$ 120.00	60
11	1	Tailgate windscreen solar film <i>new</i>	\$ 250.00	+
12	1	Rear Spoiler Sealant <i>new</i>	\$ 120.00	60

Other Total: \$ 2,037.00

Total: \$ 43,276.60

GST 7%: \$ 3,029.36

GRAND TOTAL: \$ 46,305.96

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully


 Service Executive
 Suhaimi Ong
 HP : 8298 8933 Fax: 6844 5185

Adrian Lij
 P/P 26849
 10/06/15.

Finalisation

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd
78 SHENTON WAY
#07-16
SINGAPORE 079120

GST Ref. No: 20-0000274-Z

Vehicle No: SLS8336L
Chassis No: W0LBE6EA7HG169903
Engine No: B1171437HRXX0515

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	LHF Headlamp	\$ 1,180.00
2	1	Front Radiator Grille Moulding, Base	\$ 734.00
3	1	Front Radiator Grille Chrome Moulding - RH	\$ 218.00
4	1	Front Radiator Grille Chrome Moulding - LH	\$ 218.00
5	1	Front Opel Emblem	\$ 160.00
6	1	Front Bumper	\$ 1,994.00
7	1	Front Bumper Lower Grille	\$ 202.00
8	1	Front Bumper Absorber	\$ 154.00
9	1	Front Bumper Reinforcement Bar	\$ 798.00
10	1	LHF Bumper Bracket - Guide	\$ 38.00
11	1	RHF Bumper Bracket - Guide	\$ 38.00
12	1	Rear Tailgate	\$ 2,928.00
13	1	Lettering "ASTRA"	\$ 74.00
14	1	Lettering "ECOFLEX"	\$ 112.00
15	1	LHR Taillamp	\$ 618.00
16	1	Rear Bumper Upper	\$ 2,886.00
17	1	Rear Bumper Lower	\$ 362.00
18	1	LHR Bumper Reflector	\$ 48.00
19	1	Rear Bumper Reinforcement Bar	\$ 716.00
20	1	Rear Bumper Air Ventilator	\$ 36.00
21	1	LHR Bumper Bracket, Guide	\$ 54.00
22	1	RHR Bumper Bracket, Guide	\$ 54.00
23	1	LHR Bumper Bracket	\$ 26.00
24	1	RHR Bumper Bracket	\$ 26.00
25	1	Rear Bumper Bracket Centre	\$ 60.00
26	1	Rear End Panel Trim	\$ 196.00

Supplementary Items

27	1	Front Intake Cooler Air Guide	\$ 153.00
----	---	-------------------------------	-----------

28	1	Front A/C Condensor Air Guide LH	\$ 174.00
29	1	Front A/C Condensor Air Top Centre	\$ 184.00
30	1	Front Grille Bracket	\$ 288.00
31	1	Front intake cooler turbo	\$ 1,060.00
32	1	Front Air Con condensor	\$ 780.00
33	1	Rear Tailgate Weatherstrip	\$ 216.00

Total: \$ 16,765.00
Less 10%: \$ 1,676.50
Parts Total: \$ 15,088.50

Labour

No.	Description	Price (SGD)
Front portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 650.00
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 550.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 50.00
4	To remove and refit front sensor	\$ 60.00
Rear portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 1,300.00
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 1,100.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
4	To remove and refit reverse sensor and conduct test	\$ 60.00
5	To remove and refit reverse camera and conduct test	\$ 60.00
6	To conduct transfer of parts from old tailgate to new tailgate	\$ 150.00

Labour Total: \$ 4,010.00

Other

No.	Other Description	Price (SGD)
Front portion		
1	10 Front bumper clip	\$ 50.00
Rear portion		
1	1 Rear number plate	\$ 45.00
2	10 Rear bumper clip	\$ 50.00
3	1 Reverse sensor (1 set)	\$ 440.00
4	1 Rear reverse camera	\$ 230.00
5	1 Tailgate windscreen sealant	\$ 60.00
6	1 Rear Spoiler Sealant	\$ 60.00

Other Total : \$ 935.00

Total : \$ 20,033.50

GST (7%) \$ 1,402.35

Grand Total: \$ 21,435.85

Yours Faithfully,

A handwritten signature in black ink, appearing to read 'Suhaimi', is written over a circular stamp. The stamp contains the text 'Suhaimi Ong' and 'Service Advisor' around a central emblem.

Suhaimi Ong

Service Advisor

Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice