

COMFORTDELGRO ENGINEERING PTE LTD

E R A O

REPAIR ESTIMATE*

VEHICLE NO : SHB 6629S

DATE 7/6/2019 9:41

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 553.00
	Rear Bumper Reinforcement ✕			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) ✕		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs ✓			\$ 22.00
	Rear Bumper Bracket ✕		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ✕			\$ 103.50
	Rear Bumper Under Cover ✓			\$ 228.00
	Rear Bumper Reflector Lamp,RH ✕			\$ 30.60
	Exhaust Pipe Insulator,RH ✕			\$ 58.55
	Exhaust Silencer,RH ✕			\$ 967.70
	Exhaust Pipe Hanger,RH ✕			\$ 58.55
	SUB TOTAL			\$ 2,682.10
	LESS 20%			\$ 536.42
	DISCOUNTED TOTAL			\$ 2,145.68
	Rear Bumper Reverse Sensor ✓			\$ 135.70
				\$ 135.70
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 300.00 ²⁰⁰
	Wiring Charge			\$ 50.00 ✕
	Remove/Refix Reverse Sensor			\$ 80.00 30
	Remove/Refix Exhaust Pipe			\$ 150.00 ✕
	TOTAL LABOUR			\$ 980.00
	ESTIMATE TOTAL			\$ 3,261.38
<i>Kali Kaly</i> <i>10/6/19 1430h</i> <i>2 Pys</i> <i>4/5</i> <i>After Repair photo</i> <i>Larry Ng</i> LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before / after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				