



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLR 6537 S

Parts	(a) Cost / List Price Items	\$	69,022.28	TBC
	Plus/Less 25%	\$	17,255.57	
	Total of Cost / List	\$	51,766.71	
	(b) Nett Price Items			
	Less			
	Total of Nett Item			
	(c) Special Nett Items	\$	795.00	
	Total Parts Cost	\$	52,561.71	
	Labour	\$	6,460.00	
	Total	\$	59,021.71	

Not Authorized
Resurvey B4 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 11/6/19 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 18 day(s)
- (c) Resurvey : Required / ~~Not Required~~
- (d) Excess : \$ _____
- (e) Signature of surveyor : Lc Date: 11/6/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLR 6537 S**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU003564552**

Submit By : **SERENCE**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$129.00		✓
3	Bonnet	1	\$812.40		✓
4	Bonnet lock	1	\$130.00		✓
5	Bonnet hinge LH	1	\$57.80		✓
6	Bonnet hinge RH	1	\$57.80		✓
7	Bonnet heat insulator	1	\$440.12		?
8	Bonnet heat insulator clip	10	\$35.00		?
9	Front support panel centre	1	\$338.50		✓
10	Front support panel LH	1	\$213.50		✓
11	Front support panel RH	1	\$213.50		✓
12	Headlamp panel LH	1	\$89.20		✓
13	Headlamp panel RH	1	\$89.20		?
14	Support panel lower	1	\$387.95		?
15	Front support panel top garnish	1	\$285.40		✓
16	Front support panel top garnish clip	10	\$35.00		✓
17	Air duct	1	\$195.40		✓
18	Air duct - inlet	1	\$109.75		?
19	Brace panel	1	\$105.20		✓
20	Condenser	1	\$1,544.70		?
21	Radiator	1	\$1,841.80		?
22	Radiator fan motor RH	1	\$455.70		?
23	Radiator fan motor LH	1	\$491.79		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLR 6537 S**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU003564552**

Submit By : **SERENCE**

Year Manufacture : **2017**

Engine No. : **0**

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	\$197.80		✓
25	Radiator fan blade RH	1	\$219.80		✓
26	Radiator fan cowling	1	\$287.67		✓
27	Radiator top hose	1	\$49.80		✓
28	Radiator bottom hose	1	\$46.95		✓
29	Radiator spare tank	1	\$186.70		✓
30	Intake manifold	1	\$892.74		✓
31	Headlamp LH	CM 1	\$2,531.60		✓
32	Headlamp RH	CM 1	\$2,531.60		✓
33	Front bumper	CM 1	\$450.80		✓
34	Front bumper clip	CM 10	\$40.00		✓
35	Front bumper reinforcement - upper	CM 1	\$711.50		✓
36	Front bumper reinforcement - lower	CM 1	\$245.30		✓
37	Front bumper side retainer RH	CM 1	\$107.20		✓
38	Front bumper side retainer LH	CM 1	\$107.20		✓
39	Front bumper upper grille	CM 1	\$321.90		✓
40	Front bumper lower grille	CM 1	\$148.60		✓
41	Front bumper emblem	CM 1	\$87.10		✓
42	Front bumper tow cover RH	CM 1	\$25.70		✓
43	Front bumper tow cover LH	CM 1	\$25.70		✓
44	Front bumper sponge - upper	CM 1	\$89.81		✓
45	Front bumper sponge - lower	CM 1	\$135.70		✓
46	Fog lamp LH	CM 1	\$910.70		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLR 6537 S**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU003564552**

Submit By : **SERENCE**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp RH	1	\$910.70		?
48	Engine under cover	1	\$198.30		?
49	Engine under cover clip	10	\$35.00		?
50	Air cleaner box	1	\$967.80		?
51	Washer tank	1	\$195.60		?
52	Washer tank motor	1	\$196.74		?
53	LH front fender	1	\$868.70		✓
54	LH front fender undershield	1	\$195.60		✓
55	LH front fender undershield clip	10	\$25.00		✓
56	LHF fender wording "HYBRID"	1	\$44.17		✓
57	LH front fender quarter garnish	1	\$122.70		✓
58	LH front shock absorber	1	\$462.70		?
59	LH front shock absorber top mounting	1	\$195.07		?
60	LH front shock absorber stopper	1	\$37.02		?
61	LH front knuckle arm	1	\$476.75		?
62	LH front knuckle bearing	1	\$573.20		?
63	LH front wheel hub	1			
64	LH front wheel hub lock nut	1	\$28.02		X
65	LH front tie rod	1	\$1,721.85		?
66	LH front tie rod end	1	\$116.40		?
67	LH front hub cap	1	\$195.62		✓
68	LH front rim	1	\$1,555.10		?
69	LH front tyre	1	\$350.00	S.N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLR 6537 S

TOYOTA PRIUS
 JTDKB3FU003564552

Submit By :
 Year Manufacture :
 Engine No. :

SERENCE

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	RH front fender	1	\$868.70		✓
71	RH front fender undershield	1	\$176.50		✓
72	RH front fender undershield clip	1	\$25.00		✓
73	RHF fender wording "HYBRID"	1	\$45.17		✓
74	RH front fender quarter garnish	1	\$112.40		✓
75	RH front lower arm	1	\$492.65		X
76	RH front shock absorber	1	\$462.70		X
77	RH front shock absorber top mounting	1	\$195.07		X
78	RH front shock absorber stopper	1	\$37.02		X
79	RH front knuckle arm	1	\$476.75		X
80	RH front knuckle bearing	1	\$573.20		X
81	RH front wheel hub	1			X
82	RH front wheel hub lock nut	1	\$28.02		X
83	RH front tie rod	1	\$1,721.85		X
84	RH front tie rod end	1	\$116.40		X
85	RH front hub cap	1	\$195.65		X
86	RH front rim	1	\$1,555.10		✓
87	RH front tyre	1	\$350.00	S.N	✓
88	Aircon compressor	1	\$2,859.70		?
89	Horn	1	\$150.40		?
90	Air flow sensor	1	\$256.09		?
91	Water pump	1	\$601.73		?
92	Bonnet cable	1	\$74.60		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLR 6537 S**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU003564552**

Submit By : **Carmen Lim**

Year Manufacture : **2017**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Radiator top garnish <i>Dir</i>	1	\$54.24		✓
94	Air resonator	1	\$195.74		?
95	Battery	1	\$13,652.74		?
96	Battery tray	1	\$61.40		?
97	Battery top bracket <i>Re</i>	1	\$49.70		X
98	Battery bracket screw <i>Re</i>	1	\$12.70		X
99	Air bag steering <i>Re</i>	1	\$2,577.30		✓
100	Air bag slip ring (module) <i>Re</i>	1	\$781.60		✓
101	Airbag wire @ steering	1			
102	Air bag passenage <i>Re</i>	1	\$3,505.40		✓
103	Airbag wire @ passenage <i>Re</i>	1	\$89.70		✓
104	Air bag control unit <i>Re</i>	1	\$1,183.60		✓
105	Air bag steering lower <i>Re</i>	1			✓
106	Driver seat aig bag <i>Re</i>	1			✓
107	Passenger seat airbag <i>Re</i>	1			✓
108	Roof lining <i>Reform</i>	1			✓
109	Roof lining clip <i>Re</i>	1			✓
110	Roof Air bag LH <i>Re</i>	1			✓
111	Roof Air bag RH <i>Re</i>	1			✓
112	Seat belt LH <i>Re</i>	1	\$978.80		✓
113	Seat belt RH <i>Re</i>	1	\$978.80		✓
114	Seat belt buckle LH	1	\$195.50		?
115	Seat belt buckle RH	1	\$195.50		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLR 6537 S**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU003564552**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
64	Seat belt LHR <i>T_h</i>	1	\$828.60		<i>✓</i>
65	Sear belt RHR <i>T_h</i>	1	\$828.60		<i>✓</i>
66	Seat belt buckle LHR	1	\$211.67		<i>7</i>
67	Seat belt buckle RHR	1	\$211.67		<i>7</i>
68	Dashboard <i>T_h</i>	1	\$1,625.10		<i>✓</i>
69	Front windscreen <i>C M_h</i>	1	\$1,826.40		<i>✓</i>
62	Front windscreen moulding <i>M_h</i>	1	\$70.20		<i>✓</i>
63	Front windscreen sealant <i>M_h</i>	1	\$50.00	S.N	<i>4052</i>
124					
125					
126					
127					
128					
129					
130					
131					
132					
133					
134					
135					
136					
137					
138					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLR 6537 S** Submit By : **SERENCE**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, SUPPORT PANEL, BONNET,LHF FENDER, LHF DOOR,RHF FENDER,RHF DOOR)	\$1,600.00	1000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, SUPPORT PANEL, BONNET.LHF FENDER,LHF DOOR,RHF FENDER,RHF DOOR)	\$1,800.00	1200
3	To tuff coat.	\$250.00	120
4	To check wiring & focus Headlamp	\$50.00	30
5	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
6	To remove & refit undercarriage to assist work load.	\$500.00	?
7	To do wheel alignment.	\$120.00	60
8	To remove & refit roof lining, inner trim to assist work load.	\$600.00	200
9	Towing Bill	\$120.00	?
10	To refit airbag system.	\$250.00	180
11	To reset airbag control unit.	\$250.00	200

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : SLR 6537 S

Submit By : **Carmen Lim**

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.