

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHB 4620D (Supplementary)

DATE : 12.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Outer Handle Cover (LH) <i>Done</i>			\$ 56.00
	Front Door Handle Pad (Front) (LH) <i>New</i>			\$ 35.00
	Front Door Handle Pad (Rear) (LH) <i>New</i>			\$ 35.00
	SUB TOTAL			\$ 126.00
	LESS 20%			\$ 25.20
	DISCOUNTED TOTAL			\$ 100.80
<p><i>Ign 24/06/19</i></p> <p><i>2KK And</i></p> <p><i>main estimate</i></p> <p><i>16141.48</i></p> <p><i>100.80</i></p> <p><i>16242.28</i></p> <p><i>1/512500/-</i></p> <p><i>24794.12</i></p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				