

AXA 17/6



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 5277 L

*Not Authorized
Resurvey Repairing*

Parts	(a) Cost / List Price Items	\$	8,870.85
	Plus/Less 25%	\$	2,217.71
	Total of Cost / List	\$	6,653.14
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	250.00
Total Parts Cost		\$	6,903.14
Labour		\$	2,810.00
Total		\$	9,713.14

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 17/6/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : De Date: 17/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	SLF 5277 L	Submit By :	SERENCE
Make & Model :	TOYOTA PRIUS	Year Manufacture :	2017
Chassis No. :	JTDKB3FU203531603	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>Bu</i>	1	\$450.80		✓
2	Front bumper clip <i>u</i>	10	\$40.00		✓
3	Front bumper side retainer RH <i>dis</i>	1	\$107.20		✓
4	Front bumper side retainer LH <i>su</i>	1	\$107.20		X
5	RH front fender <i>Rf</i>	1	\$868.70		✓
6	RH front fender undershield <i>su</i>	1	\$185.64		X
7	RH front fender undershield clip <i>u</i>	10	\$25.00		X
8	RHF fender wording "HYBRID" <i>u</i>	1	\$44.17		✓
9	RH front lower arm <i>su</i>	1	\$492.65		X
10	RH front shock absorber <i>su</i>	1	\$462.70		X
11	RH front shock absorber top mouting <i>su</i>	1	\$195.07		X
12	RH front shock absorber stopper <i>su</i>	1	\$37.02		X
13	RH front knuckle arm <i>su</i>	1	\$476.75		X
14	RH front knuckle bearing <i>u</i>	1	\$573.20		X
15	RH front wheel hub	1			
16	RH front wheel hub lock nut <i>su</i>	1	\$28.02		X
17	RH front tie rod <i>su</i>	1	\$1,721.85		X
18	RH front tie rod end <i>su</i>	1	\$116.40		X
19	RH front rim <i>nd</i>	1	\$1,555.10		✓
20	RH front tyre <i>su</i>	1	\$250.00	S.N	X
21	RH front door <i>u</i>	1	\$1,226.70		X
22	RH front door hinge top <i>u</i>	1	\$78.34		X
23	RH front door hinge bottom <i>u</i>	1	\$78.34		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLF 5277 L** Submit By : **SERENCE**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, SUPPORT PANEL, RHF FENDER, RHF DOOR)	\$1,000.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, SUPPORT PANEL, RHF FENDER, RHF DOOR)	\$1,000.00	600
3	To tuff coat.	\$150.00	30
4	TO Check wiring	\$50.00	20
5	To do wheel alignment.	\$120.00	60
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load. <i>nn</i>	\$240.00	X
7	To remove & refit undercarriage to assist work load. <i>nn</i>	\$250.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.