



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:
Vehicle:
Make / Model:
Chassis:

10 Jun 19
SMJ4126M
HONDA/ CIVIC TYPE R

No.	Description		Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER	1	\$ 1,029.00	\$ 1,029.00
2	REAR BUMPER UPPER FACE	1	\$ 206.00	\$ X 206.00
3	REAR BUMPER MID FACE	1	\$ 311.00	\$ X 311.00
4	REAR BUMPER LOWER FACE	1	\$ 405.00	\$ X 405.00
5	REAR BUMPER RETAINER	2	\$ RHK 60.00	\$ HMC 60.00
7	REAR LH TAILLAMP	1	\$ 360.00	\$ 360.00
6	END PANEL	1	\$ 455.00	\$ X 455.00
7	END PANEL TOP GARNISH	1	\$ 165.00	\$ X 165.00
				\$ 2,991.00
			Less 20%	\$ 598.20
			Total	\$ 2,392.80
S/Nett Items:				
19	REAR BUMPER CLIP	1 SET	\$ 40.00	\$ 20 40.00
20	REAR REVERSE SENSOR	1 SET	\$ 400.00	\$ X 300.00
	JOINT SEALANT	1	\$ 150.00	\$ X 150.00
				\$ 490.00
Labour to:				
23	CHECK WIRING AND LIGHTNING SYSTEM		\$ 60.00	\$ 30 60.00
24	REMOVE AND REFIT LINING, TRIM AND GARNISH		\$ 120.00	\$ X 120.00
25	REMOVE AND RENEW REAR REVERSE SENSOR		\$ 150.00	\$ 30 150.00
29	PANEL BEATING ON AFFECTED AREAS		\$ 800.00	\$ 300 800.00
30	SPRAY PAINTING ON AFFECTED AREAS		\$ 900.00	\$ 300 900.00
31	APPLY ANTI RUST ON AFFECTED AREAS		\$ 150.00	\$ X 150.00
				\$ 2,180.00
Parts Replacement Amount			\$	2,882.80
Total Amount for Labour			\$	2,180.00
Total Amount			\$	5,062.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Tanjin 97495749

WP

10/6/19 @ 430pm.

Resurvey after repair

sure@lkkauto.com

03 days

1825.20

4/5/1450.