

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Xiao Tony.

Quotation No	Jun 001/2019
Date	06/06/19
Vehicle No	SJH2856J
Make / Model	TOYOTA Estima

To: M/s India International Insurance Pte Ltd

Address: 64 Cecil Street #04/#05 IOB Building Singapore 049711

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	rear bumper <i>del</i>		\$ 685.00 ✓
2 pcs	rear bumper side retainer <i>per.</i>		\$ 194.00 ✓
2 pcs	rear bumper bracket <i>Ne n</i>		\$ 170.00 + ✓
1 pc	rear bumper reflector <i>RT missing</i>		\$ 78.00 ✓
1set	rear bumper reverse sensor <i>Del</i>		\$ 200.00 ✓
1 pc	rear bumper inner sponge <i>embd</i>		\$ 110.00 → 85. ✓
1 pc	tailgate <i>Del</i>		\$ 1,865.00 → 1585 ✓
1 pc	tailgate "CENTRE" emblem <i>Ne</i>		\$ 87.00 ✓
1 pc	tailgate outer chrome handle <i>Ne n</i>		\$ 355.00 + ✓
1 pc	reverse camera <i>Ne n</i>		\$ 300.00 + ✓
1 pc	tailgate centre reflector <i>Ne n</i>		\$ 276.00 + ✓
2 pcs	tailgate reflector <i>RT embd</i>	\$ 337.00	\$ 674.00 337 ✓
2 pcs	tail lamp <i>RT embd</i>	\$ 352.00	\$ 704.00 352 ✓
1 pc	tailgate inner lock (top) <i>Del</i>		\$ 485.00 → 398.60 ✓
1 pc	tailgate inner lock (lower) <i>Ne n</i>		\$ 54.00 + ✓
1 pc	tailgate windstrip <i>cut</i>		\$ 456.00 → 299.80 ✓
1 pc	tailgate glass sealant <i>Green</i>		\$ 80.00 ✓
1 pc	tailgate glass moulding <i>Green</i>		\$ 250.00 ✓
1 pc	tailgate inner trim board <i>embd</i>		\$ 565.00 ✓
1 set	tailgate inner trim board clip <i>per</i>		\$ 50.00 → 30. ✓
1 set	rear bumper clip <i>Ne</i>		\$ 50.00 30 ✓
1 pc	tailgate inner top garnish <i>Del Ne n</i>		\$ 197.00 + ✓
1 pc	rear end panel <i>Del</i>		\$ 785.00 ✓
1 pc	rear end panel top garnish <i>Del</i>		\$ 286.00 ✓
1 set	rear end panel top garnish clip <i>Ne</i>		\$ 50.00 20 ✓
1 set	tailgate inner garnish clip <i>Ne n</i>		\$ 50.00 ✓
1 pc	rear end panel inner lower garnish <i>Del</i>	7306.40	\$ 387.00 → 235 ✓
1 set	rear end panel inner lower garnish clip <i>Ne</i>	5479.80	\$ 50.00 20 ✓
1 pc	n/s rear fender inner garnish <i>Ne n</i>		\$ 795.00 + ✓
1 pc	n/s tailgate absorber <i>Ne n</i>		\$ 272.00 + ✓
1 pc	rear bumper tow cover <i>del</i>		\$ 47.00 ✓
1 pc	rear compartment top cover		\$ 1,390.00 → 687. ✓
1 pc	rear wiper motor <i>Ne n</i>		\$ 860.00 + ✓
1 pc	rear number plate <i>Ne n</i>		\$ 60.00 ✓

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Labour Charge			
1	to dismantle damaged parts, panel beat, repair	\$	1,000.00
2	to putty and spray painting on affected area	\$	1,000.00
3	anti rust	\$	150.00
4	tailgate glass	\$	180.00
5	transfer tailgate	\$	80.00
6	wiring check	\$	50.00
Subtotal:		\$	15,372.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Adrian Lij
1/s 10/06/19.
0722p.

total 7369.80

h/s: 5.9K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: