

Trace

ASS. REC. BY:

REF- CS / CT1 19010324 / K9d324

Special Instruction:

Surveyor Kenneth

ASSIGNMENT (Office)

From (Person): Chung Boun Sen of CT1 Date/Time: 11.6.2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 75527 Insured: SML 6505 D

at Workshop m/n Esteem Performance Tel: 65662112

of BIK 5033 Aml Ind Park 2 #01-259

Policy No: DMPCSA 30392219000 Claim No: SM19D20252102

Sum Insured: Excess:

Make of Veh: D.O.A. 1.6.2019
(Client's Record) 12.19

CA / REV / REP. / REV 24 HRS ^{sup} H.O.D. Endorsement:

Date/Time: 11.6.2019 3.44 pm Person Contacted: Jenny Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMA 75527 - X
	SML 6505 D - X
012	820658.24 Confirmed (Ref #4448.3r, 19%)

ASSIGNMENT

From: Date: 12.6.2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMA 7552J

at Workshop n/s Esteem performance

of BIK 5033 AMK Ind Part 2

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 887K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 18 days Res.: Yes or No

Lum Sum: 1.03.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMA 7552J Yr Regn: 06/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle c.c. 1498

Colour: M-Black NC: Insured / Std / NI / NA

Sp. Reading: 83395 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: ☒ Fair / Poor / BurntSteering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt orModi: ☒ S/Rim / STD A/Rim orTyre Size: F: ☒ Fikun 185/60R15

R: Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 7 mm

L/Bal. 8 mm

L/Bal. 7 mm

D.O.A. 1/6/19

D.O.A. 12/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8/11

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 06 FEB 2020

Date/Time, File Pass to?

☐

: Preli. Report

1) 06/2/2020

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 18

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

3 + RS, 50

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

MER-71

20658.74

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2019		11 Jun 2019 15:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Vehicle Reg. No.:	SMA7552T	Date of Loss:	01/06/2019 17:00 - :59
Claim Type:	TP / SNM19D202521C02	Policy/Cover Note No.:	DMPCSN30398219000
Vehicle Reg. No. (Insured):	SML6505D	Policy No. (Claimant):	999994314
		Excess:	\$50.00
Repairer:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/06/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	0651D

Vehicle Details

Vehicle No.:	SMA7552T
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	LEB6553054
Chassis No.:	GP71210729
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,196.00
Original Registration Date:	19 Jun 2018
First Registration Date:	19 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2028
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	18 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,010.00
COE Rebate Amount:	\$33,360.00
Total Rebate Amount:	\$37,110.00

The information contained herein is correct as at 13 Jun 2019

OK

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 10 Years Car Renewal Toyota Estima 2.4L



1.8L 1800 & 2.4L 2400cc Foreign GV
Exceeds 2 Years Warranty
Warranty From \$188
GV Credit Pte Ltd 012-444

**Lake View
Credit Pte Ltd**

[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▼

◀ Back (1 2) Next ▶

Sort by Date Posted ▼ 20 results/page ▼

25 vehicles

Honda Shuttle

Advanced Search 🔍

Model	Price	Depreciation	Reg Tax	Eng Cap	Mileage	Veh Type	Status
Search Selection Honda Shuttle	Any	Any	2018	Any	Any	Any	Available



Honda Shuttle Hybrid 1.5A

\$83,000

\$9,350 /yr

11-Jan-2018

1,496 cc

-

Stationwagon

Available

Fuel Type: Petrol-Electric

Elegant White, Almost New Condition, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 12-Jun-2018

Tags: 2018 Honda Shuttle, 2018 Honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A

\$89,800

\$9,770 /yr

18-May-2018

1,496 cc

10,249 km

Stationwagon

Available

Fuel Type: Petrol-Electric

100% Beautiful Condition, High Trade-In, Bank Loan/ In-House Loan/ High Loan Available! New Road Tax. Hurry! Don't Miss!

Creative Auto

Posted: 12-Jun-2018

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A X

\$86,000

\$9,430 /yr

20-Apr-2018

1,496 cc

18,500 km

Stationwagon

Available

Fuel Type: Petrol-Electric

Very Good Fuel Consumption With Good Pickup, Almost Brand New With Full Accessories And High Spec x Model, 4 Years Warranty Remaining On Car And Hybrid Battery, Serviced By PJ Workshop, Current Number...

STREET OWNED

Posted: 12-Jun-2018

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$71,800

\$7,600 /yr

09-May-2018

1,496 cc

18,000 km

Stationwagon

Available

Low Interest Rate Just At 1.98%! Condition Very Well Maintained By Previous Owner, Low Mileage, Like Brand New, 2 Years Warranty/Servicing By Platinum Motoring In House Workshop, New Paint Color Of Yo...

PREMIUM 2018

Posted: 11-Jun-2018

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but
Unsure of its Condition?
Call STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



Honda Shuttle Hybrid 1.5A

\$87,800

\$9,680 /yr

03-Apr-2018

1,496 cc

-

Stationwagon

Available

Fuel Type: Petrol-Electric

Low Fuel Consumption, In House Loan Available, 3 Years Or 100,000km Warranty, 3 x Free Servicing. Call Our Friendly Salesperson Now!

Posted: 10-Jun-2018

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$73,800

\$7,670 /yr

27-Jun-2018

1,496 cc

5,000 km

Stationwagon

Available

2018 New Facelifted Honda Shuttle 1.5 With Fog Lamp, LED Edition, Best Fuel Efficient Stationwagon In Town, Almost New Honda Shuttle, 10 Years Repayment, In House Loan Or Balloon Scheme Available. Diff...

PREMIUM 2018

Trust Motoring

Posted: 09-Jun-2018

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle Hybrid 1.5A

\$89,800

\$9,130 /yr

24-Jul-2018

1,496 cc

8,000 km

Stationwagon

Available

Fuel Type: Petrol-Electric

Newly Registered Honda Hybrid, 2018 Facelifted Model, 10 Years Repayment, In House Loan Or Balloon Scheme Available! Lowest Interest Rate In Lowest Depreciation Ever! Make And Assemble In Japan...

PREMIUM 2018

Compare

otoring

1/17



Spacious And Comfortable Stationwagon That Is Fuel Efficient! In An Immaculate Condition, Almost Like Brand New. An Opportunity To Snap Up This Car, With No Waiting Time And Needless To Pay Over \$100K...

Posted: 10-May-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A X****\$87,000****\$9,120 /yr****27-Feb-2018****1,496 cc****-****Stationwagon****Available****Fuel Type: Petrol-Electric****Call Us To Make An Appointment To View This Car.**

Posted: 10-May-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A X****\$94,988****\$10,390 /yr****07-May-2018****1,496 cc****30 km****Stationwagon****Available****Fuel Type: Petrol-Electric****Choice Of Color.**

Posted: 10-May-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A****\$81,000****\$9,000 /yr****02-Mar-2018****1,496 cc****-****Stationwagon****Available****Fuel Type: Petrol-Electric****Call Our Sales Executive For Viewing.**

Posted: 30-Apr-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

◀ Back (1 2) Next ▶

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Shuttle, Honda Shuttle Singapore, used Honda Shuttle Singapore, used Honda Shuttle, used vehicles Singapore or even buy used Honda Shuttle Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/06/2019 14:25
Date Of Accident	01/06/2019 17:30
Exact Location Of Accident	SLIP ROAD OF PUNGGOL WAY TO TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA7552T
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66039399

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994314
Cover Note Number	

Driver

Name of Driver	LIM KIM YAM (LIN JINYAN)
NRIC No	S7400362A
Date Of Birth	06/01/1974
Occupation	OUTDOOR
Date Of Driving Pass	01/11/2006
Driving Experience	12 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82777497
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 499C TAMPINES AVENUE 9 #12-282
Postcode	523499
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 461 TAMPINES STREET 44 #01-56 , POSTCODE: 520461 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7818999 - FAX NO: 67838603
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN, 2 PASSENGERS AND POLICE REPORT: T/20190603/2140.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO - ESTEEM PERFORMANCE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML6505D
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKA8508P
Vehicle Make/Model/Colour BMW
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver MOHD ISMAIL B. IBRAHIM
NRIC/Passport Number S1268164Z
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM KIM YAM
Approximate Age 45
Injuries Sustain
Injured person in which vehicle? SMA7552T
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? YES
Address BLK 499C TAMPINES AVE 9
#12-282
Postcode 523499

DETAILS OF INJURED PERSON 2

Name SERENE LIM
Approximate Age
Injuries Sustain
Injured person in which vehicle? SMA7552T
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address BLK 499C TAMPINES AVE 9
#12-282
Postcode 523499

DETAILS OF INJURED PERSON 3

Name KENNETH LIM
Approximate Age
Injuries Sustain
Injured person in which vehicle? SMA7552T
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address BLK 499C TAMPINES AVE 9
#12-282
Postcode 523499

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 07 JUL 2019
14:25H5

Driver's Signature

(If driver is not the policyholder)


Date & Time: 03.06.19 @ 18:30

Reporting Centre Personnel's Signature

Name: Poh Kwee Choo
NRIC/FIN No.: S8940583A

Sketch Plan Pg. 2

SKETCH PLAN



A: SMA 7552 T

B: SKA 8508 P

C: 3ML 6505 D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER AS POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 07 JUN 2019

Driver's Signature
(If driver is not the policyholder)

Date & Time: 03-06-19 @ 18:30

Reporting Centre Personnel's Signature
Name: Pon Kwee Choo
NRIC/FIN No.: S8840583A



**SINGAPORE
POLICE FORCE**



T/20190603/2140

1 of 4

Report No. T/20190603/2140

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7618999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/06/2019 16:42	Vide Report No.:	Station Diary No.: 65
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: LIM KIM YAM		Address: APT BLK 499C TAMPINES AVENUE 9 #12-282 SINGAPORE 523499	
ID Type / ID No.: NRIC NO / S7400362A		Contact No.: Home/Office: Mobile: 82777497	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 45	Date of Birth: 06/01/1974	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/06/2019 17:30	Type of Location: Slip Road
Location: Along Road 1 Traveling Toward Road 2 PUNGGOL WAY TAMPINES EXPRESSWAY Slip Road into TPE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SKA8508P	Car				Slightly Damaged	1
SMA7552T	Car				Slightly Damaged	2
SML6505D	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190603/2140

2 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-58 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20190603/2140

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Mohd Ismail bin Ibrahim	ID No.	S1268164Z
Related Vehicle	SKA8508P (Car)	Contact No.	0
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM KIM YAM	ID No.	S7400362A
Related Vehicle	SMA7552T (Car)	Contact No.	82777497
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	01/06/2019	Date Discharge	03/06/2019
No. of Days granted Medical Leave	10	Degree of Injury	Slight
Name			
Name	Unknown	ID No.	NIL
Related Vehicle	SML6505D (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/06/2019 @ 1715hrs, I was travelling on the slip road of Punggol Way towards TPE in the direction of Changi Airport when a BMW SKA8508P in front of me jam braked and I followed suit. However, the car SML6505D behind me hit me on the rear and thus causing me to hit the back of the BMW.

I was conveyed by Ambulance to Sengkang General Hospital and Traffic Police came to scene. I was hospitalized till 03/06/2019 and was given 10 days MC.

My daughter Serene Lim and my Son Kenneth Lim was given outpatient treatment and was given MC for



**SINGAPORE
POLICE FORCE**



T/20190603/2140

3 of 4

Report No. T/20190603/2140

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

CONTINUATION OF REPORT

3 days.

My car is equipped with an in car camera. And my car was badly damaged at the rear portion.



**SINGAPORE
POLICE FORCE**



T/20190603/2140

4 of 4

Report No. T/20190603/2140

Police Station Of Origin;
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sr Staff Sgt MOHAMMAD ABDULGHANI BIN
MOHD ADNAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
03/06/2019 16:42

Officer In Charge Of Case:
TP / GIT /
Staff Sgt SUFIYAN BIN KHAIRI
Contact No.: 65476390

Classification Of Case:

SINGAPORE
POLICE FORCE

Authentication Stamp
NP168

SIGNATURE



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 7552 T

Parts	(a) Cost / List Price Items	\$	21,487.20
	Plus/Less 20%	\$	4,297.44
	Total of Cost / List	\$	17,189.76
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	1,490.00
Total Parts Cost		\$	18,679.76
Labour		\$	5,600.00
Total		\$	24,279.76

The above total will be subjected to 7% G.S.T.

Not Authorized
Henry B. G. print

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before start any painting
- To display damaged parts/painting insurance
- Parts stores are subject to inspection
- When any survey is done, without "Pioneer" form
- All work must be signed "Approved"
- Supply survey report form to insurance and is subject to their approval from time to time. On doing

Acknowledged by Repairer
Signature: _____
Date: _____

7546.56

Name of Surveyor : Hennerth
Company : LKK
Survey conducted on : 12/6/19 at 10am

Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 18 day(s)
- (c) Resurvey : Required / ~~Not Required~~
- (d) Excess : \$ _____
- (e) Signature of surveyor : Le Date: 12/6/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. : SMA 7552 T
Make & Model : HONDA SHUTTLE
Chassis No. : GP71210729

Submit By : Carmen Lim
Year Manufacture : 2018
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓
2	Bonnet	1	\$920.80		✓
3	Bonnet lock	1	\$135.00		X
4	Bonnet hinge LH	1	\$40.00		✓
5	Bonnet hinge RH	1	\$40.00		✓
6	Headlamp LH	1	\$2,250.00		✓
7	Headlamp RH	1	\$2,250.00		✓
8	Headlamp clip	10	\$20.00		X
9	Front support panel (complete)	1	\$785.00		X
10	Front bumper	1	\$1,050.00		✓
11	Front bumper clip	10	\$39.00		✓
12	Front bumper reinforcement	1	\$420.90		✓
13	Front bumper side retainer LH	1	\$15.40		✓
14	Front bumper side retainer RH	1	\$15.40		✓
15	Front bumper bracket LH	1	\$38.00		✓
16	Front bumper bracket RH	1	\$38.00		✓
17	Front emblem	1	\$23.40		✓
18	Front grille	1	\$395.00		✓
19	Front grille upper chrome	1	\$362.50		✓
20	Front grille lower chrome	1	\$220.70		✓
21	Front bumper lower grille	1	\$140.00		X
22	Front bumper lower grille LH	1	\$95.00		X
23	Front bumper lower grille RH	1	\$95.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SMA 7552 T**

Make & Model : **HONDA SHUTTLE**

Chassis No. : **GP71210729**

Submit By : **Carmen Lim**

Year Manufacture : **2018**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Front bumper tow cover <i>Sm</i>		\$25.00		X
25	Rear windscreen <i>Shatter</i>	1	\$1,650.00		✓
26	Rear windscreen solar film <i>Nu</i>	1	\$450.00	S.N	X
27	Private hirer sticker <i>Nu</i>	1	\$20.00	S.N	X
28	Rear windscreen moulding <i>Nu</i>	1	\$120.00		✓
29	Rear windscreen sealant <i>Nu</i>	1	\$50.00	S.N	4012
30	Reverse sensor <i>Shen</i>	2	\$200.00	S.N	✓
31	Rear number plate <i>Nu</i>	1	\$45.00	S.N	✓
32	Rear No.plate lamp LH <i>Sm</i>	1	\$38.50		X
33	Rear No.plate lamp RH <i>Sm</i>	1	\$38.50		X
34	Rear bumper <i>Bz</i>	1	\$1,150.60		✓
35	Rear bumper clip <i>Nu</i>	10	\$35.00		✓
36	Rear bumper side retainer LH <i>CM</i>	1	\$26.50		✓
37	Rear bumper side retainer RH <i>CM</i>	1	\$26.50		✓
38	Rear bumper bracket LH <i>N</i>	1	\$48.70		X
39	Rear bumper bracket RH <i>N</i>	1	\$48.70		X
40	Rear bumper sponge <i>CM</i>	2	\$179.00		✓
41	Rear bumper reflector LH <i>Sm</i>	1	\$45.00		✓
42	Rear bumper reflector RH <i>CM</i>	1	\$45.00		✓
43	Rear bumper reflector garnish LH <i>Nu</i>	1	\$45.00		✓
44	Rear bumper reflector garnish RH <i>Nu</i>	1	\$45.00		✓
45	Tail door <i>Bz</i>	1	\$1,193.00		✓
46	Tail door lock <i>As/Sm</i>	1	\$157.10		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SMA 7552 T

HONDA SHUTTLE

GP71210729

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim

2018

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Tail door emblem <i>RM</i>	1	\$38.00		<i>✓</i>
48	Wording "SHUTTLE" <i>RM</i>	1	\$55.00		<i>✓</i>
49	Wording "HYBRID" <i>RM</i>	1	\$80.10		<i>✓</i>
50	Tail door chrome <i>Warp</i>	1	\$383.10		<i>✓</i>
51	Tail door trim <i>RM</i>	1	\$320.00		<i>✓</i>
52	Tail door trim clip <i>RM</i>	10	\$35.00		<i>✓</i>
53	Taildoor reflector LH <i>CM</i>	1	\$395.00		<i>✓</i>
54	Taildoor reflector RH <i>CM</i>	1	\$395.00		<i>✓</i>
55	Tail end panel <i>RM</i>	1	\$560.80		<i>✓</i>
56	Tail end panel garnish <i>RM</i>	1	\$155.50		<i>✓</i>
57	Tail end panel garnish clip <i>RM</i>	10	\$35.00		<i>✓</i>
58	Boot weatherstrip <i>RM/LM</i>	1	\$168.50		<i>✓</i>
59	Tail lamp LH <i>CM</i>	1	\$520.50		<i>✓</i>
60	Tail lamp RH <i>CM</i>	1	\$520.50		<i>✓</i>
61	Spare tyre well panel <i>RM</i>	1	\$956.00		<i>✓</i>
62	Spare tyre board <i>Return</i>	1	\$655.00		<i>✓</i>
63	Rear camera <i>RM</i>	1	\$680.00	S.N	<i>X</i>
64	Gargo Box <i>RM</i>	1	\$295.00		<i>X</i>
65	Tail door inner pocket <i>RM</i>	1	\$19.50		<i>✓</i>
66	Fender inner trim LH <i>Return</i>	1	\$455.00		<i>✓</i>
67	Fender inner trim RH <i>✓</i>	1	\$455.00		<i>✓</i>
68	Rear wiper motor <i>RM</i>	1	\$490.00		<i>X</i>
69	Rear wiper motor link <i>✓</i>	1	N/A		<i>X</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SMA 7552 T
 Make & Model : HONDA SHUTTLE
 Chassis No. : GP71210729

Submit By : Carmen Lim
 Year Manufacture : 2018
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Rear wiper arm <i>Sm</i>	1	\$95.50		X
48	Rear wiper arm cover <i>Sm</i>	1	\$15.00		X
49	Rear wiper blade <i>Sm</i>	1	\$66.50		X
50	Rear bumper tow cover <i>Sm</i>	1	\$16.50		X
51					
52					
53					
54					
55					
56					
57					
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SMA 7552 T** Submit By : **Carmen Lim**
Make & Model : **HONDA SHUTTLE** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,TAILDOOR,END PANEL, SPARE TYRE WELL PANEL,FRONT BUMPER,BONNET, SUPPORT PANEL)	\$2,200.00	1600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,TAILDOOR,END PANEL, SPARE TYRE WELL PANEL,FRONT BUMPER,BONNET, SUPPORT PANEL)	\$2,200.00	1800
3	To check wiring & focus headlamp	\$50.00	30
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$250.00	120
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SMA 7552 T**

Submit By : **Carmen Lim**

Make & Model : HONDA SHUTTLE

Year of Manufacture : 2018

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. : **SMA 7552 T**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71210729**

Submit By : **CARMEN LIM**
Year Manufacture : **2018**
Engine No. :
Cost / List

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front support top garnish <i>CM</i>	1	\$89.20		✓
2	Rear tool kit sponge <i>CM</i>	1	\$165.00		✓
3	Rear antenna control <i>CM</i>	1	\$78.10		✓
4	Rear smart buzzer <i>CM</i>	1	\$108.00		✓
5	Rear hybrid battery air duct <i>nd</i>	1	\$265.60		✓
6	Front grille stay <i>DI</i>	1	\$65.00		✓
7	Rear pillar lower quarter panel LH <i>B</i>	1	\$125.80		✓
8	Rear pillar lower quarter panel RH <i>B</i>	1	\$125.80		✓
9	Cargo box board <i>re form</i>	1	\$386.00		✓
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

1408.50 ✓

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2019		11 Jun 2019 15:09 Edit Adj Rpt	S\$20,658.24 Edit Estimates	S\$20,658.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D									
Vehicle Reg. No.:	SMA7552T	Date of Loss:	01/06/2019 17:00 - :59 [11 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202521C02	Policy/Cover Note No.:	DMPCSN30398219000						
Vehicle Reg. No. (Insured):	SML6505D	Policy No. (Claimant):	999994314						
		Excess:	S\$0.00						
Repairer: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMA7552T (SNM19D202521C02)**
[SML6505D]
TP
GOLDBELL CAR RENTAL PTE LTD
Jun 1 2019 5:00PM
[-]
Esteem Performance Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page		☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	07/06/19 16:19	Accident Statement	1	Load HTM	
Photos/Images			3 per page		☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	07/06/19 16:14	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
2	07/06/19 16:14	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
3	07/06/19 16:14	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
4	07/06/19 16:14	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
5	07/06/19 16:15	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
6	07/06/19 16:15	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
7	07/06/19 16:15	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
8	07/06/19 16:15	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
9	07/06/19 16:16	SCENE PHOTO [Linked Accident Report Documents]	1	Load JPG	☒
10	07/06/19 16:17	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
11	07/06/19 16:17	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
12	07/06/19 16:17	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
13	07/06/19 16:18	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
14	07/06/19 16:18	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
15	07/06/19 16:18	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/02/20 16:00	General View	1	Load JPG	☒
2	06/02/20 16:00	General View	1	Load JPG	☒
3	06/02/20 16:00	General View	1	Load JPG	☒
4	06/02/20 16:00	General View	1	Load JPG	☒
5	06/02/20 16:00	General View	1	Load JPG	☒
6	06/02/20 16:00	General View	1	Load JPG	☒
7	06/02/20 16:00	General View	1	Load JPG	☒
8	06/02/20 16:00	General View	1	Load JPG	☒
9	06/02/20 16:00	General View	1	Load JPG	☒
10	06/02/20 16:00	General View	1	Load JPG	☒
11	06/02/20 16:00	General View	1	Load JPG	☒
12	06/02/20 16:00	General View	1	Load JPG	☒
13	06/02/20 16:00	General View	1	Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
				☒
14	06/02/20 16:00	General View	 Load JPG	☒
15	06/02/20 16:00	General View	 Load JPG	☒
16	06/02/20 16:00	General View	 Load JPG	☒
17	06/02/20 16:00	General View	 Load JPG	☒
18	06/02/20 16:00	General View	 Load JPG	☒
19	06/02/20 16:00	General View	 Load JPG	☒
20	06/02/20 16:00	General View	 Load JPG	☒
21	06/02/20 16:00	General View	 Load JPG	☒
22	06/02/20 16:00	General View	 Load JPG	☒
23	06/02/20 16:00	General View	 Load JPG	☒
24	06/02/20 16:00	General View	 Load JPG	☒
25	06/02/20 16:00	General View	 Load JPG	☒
26	06/02/20 16:00	General View	 Load JPG	☒
27	06/02/20 16:00	General View	 Load JPG	☒
28	06/02/20 16:00	General View	 Load JPG	☒
29	06/02/20 16:00	General View	 Load JPG	☒
30	06/02/20 16:00	General View	 Load JPG	☒
31	06/02/20 16:00	General View	 Load JPG	☒
32	06/02/20 16:00	General View	 Load JPG	☒
33	06/02/20 16:00	General View	 Load JPG	☒
34	06/02/20 16:00	General View	 Load JPG	☒
35	06/02/20 16:00	General View	 Load JPG	☒
36	06/02/20 16:00	General View	 Load JPG	☒
37	06/02/20 16:00	General View	 Load JPG	☒
38	06/02/20 16:00	Odometer Reading	 Load JPG	☒
39	06/02/20 16:00	General View	 Load JPG	☒
40	06/02/20 16:00	Chassis Number	 Load JPG	☒
41	06/02/20 16:03	DISMANTLE PHOTOS	 Load JPG	☒
42	06/02/20 16:03	DISMANTLE PHOTOS	 Load JPG	☒
43	06/02/20 16:03	DISMANTLE PHOTOS	 Load JPG	☒
44	06/02/20 16:03	DISMANTLE PHOTOS	 Load JPG	☒
45	06/02/20 16:03	DISMANTLE PHOTOS	 Load JPG	☒
46	06/02/20 16:03	DISMANTLE PHOTOS	 Load JPG	☒
47	06/02/20 16:03	DISMANTLE PHOTOS	 Load JPG	☒
48	06/02/20 16:03	DISMANTLE PHOTOS	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/06/19 16:11	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	07/06/19 16:12	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	
3	07/06/19 16:12	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	 Load TIF	
4	07/06/19 16:12	DRIVER'S NRIC, DRIVING LICENCE + VOCATIONAL LICENCE [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/06/19 15:10	PRI CONTACT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/20 14:30	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		1 per page	☒
1	04/09/19 01:19	Accident Statement		Load HTML	
Photos/Images				3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	07/06/19 16:14	SCENE PHOTO		Load JPG	☒
2	07/06/19 16:14	SCENE PHOTO		Load JPG	☒
3	07/06/19 16:14	SCENE PHOTO		Load JPG	☒
4	07/06/19 16:14	SCENE PHOTO		Load JPG	☒
5	07/06/19 16:15	SCENE PHOTO		Load JPG	☒
6	07/06/19 16:15	SCENE PHOTO		Load JPG	☒
7	07/06/19 16:15	SCENE PHOTO		Load JPG	☒
8	07/06/19 16:15	SCENE PHOTO		Load JPG	☒
9	07/06/19 16:16	SCENE PHOTO		Load JPG	☒
10	07/06/19 16:17	Accident Photo		Load JPG	☒
11	07/06/19 16:17	Accident Photo		Load JPG	☒
12	07/06/19 16:17	Accident Photo		Load JPG	☒
13	07/06/19 16:18	Accident Photo		Load JPG	☒
14	07/06/19 16:18	Accident Photo		Load JPG	☒
15	07/06/19 16:18	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	07/06/19 16:11	Sketch Plan		Load TIF	
2	07/06/19 16:12	POLICE REPORT		Load TIF	
3	07/06/19 16:12	CERTIFICATE OF INSURANCE		Load TIF	
4	07/06/19 16:12	DRIVER'S NRIC, DRIVING LICENCE + VOCATIONAL LICENCE		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119010324/KQD3E2

Date: 07/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30398219000

Claimant Vehicle
No : SMA7552TInsured Vehicle
No : SML6505D

Date of Loss: 01/06/2019

Nature of Claim: TP

Claim
No: SNM19D202521C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA7552T	Engine No:	LEB6553054
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71210729
Reg. Date:	19/06/2018 (Man. Year: 2018)	Odometer:	83395 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Falken 8 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,806.56	16,688.24	3,118.32	15.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,600.00	3,970.00	1,630.00	29.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,406.56	20,658.24	4,748.32	18.69
+ GST 7.00/7.00% (S\$)	1,778.46	1,446.08	332.38	18.69
Nett Amount (S\$)	27,185.02	22,104.32	5,080.70	18.69

INSPECTION

Date of Assignment: 11/06/2019

Date Inspected: 12/06/2019 Inspected At:

Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Feb 2020)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA7552T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Dented	45.00 FS	*45.00 FS
2	1		*BONNET	Bent	920.80 FL	*920.80 FL
3	1		*BONNET LOCK	Repair	135.00 FL	*- FL
4	1		*BONNET HINGE LH	Distorted	40.00 FL	*40.00 FL
5	1		*BONNET HINGE RH	Distorted	40.00 FL	*40.00 FL
6	1		*HEADLAMP LH	Mtg Cracked	2,250.00 FL	*2,250.00 FL
7	1		*HEADLAMP RH	Mtg Cracked	2,250.00 FL	*2,250.00 FL
8	10		*HEADLAMP CLIP	Not Necessary	20.00 FL	*- FL
9	1		*FRONT SUPPORT PANEL (COMPLETE)	Repair	785.00 FL	*- FL
10	1		*FRONT BUMPER	Buckled	1,050.00 FL	*1,050.00 FL
11	10		*FRONT BUMPER CLIP	Necessary	39.00 FL	*39.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	420.90 FL	*420.90 FL
13	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	15.40 FL	*15.40 FL
14	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	15.40 FL	*15.40 FL
15	1		*FRONT BUMPER BRACKET LH	Distorted	38.00 FL	*38.00 FL
16	1		*FRONT BUMPER BRACKET RH	Distorted	38.00 FL	*38.00 FL
17	1		*FRONT EMBLEM	Necessary	23.40 FL	*23.40 FL
18	1		*FRONT GRILLE	Cracked	395.00 FL	*395.00 FL
19	1		*FRONT GRILLE UPPER CHROME	Cracked	362.50 FL	*362.50 FL
20	1		*FRONT GRILLE LOWER CHROME	Scratched	220.70 FL	*220.70 FL
21	1		*FRONT BUMPER LOWER GRILLE	Serviceable	140.00 FL	*- FL
22	1		*FRONT BUMPER LOWER GRILLE LH	Serviceable	95.00 FL	*- FL
23	1		*FRONT BUMPER LOWER GRILLE RH	Serviceable	95.00 FL	*- FL
24	1		*FRONT BUMPER TOW COVER	Serviceable	25.00 FL	*- FL
25	1		*REAR WINDSCREEN	Shattered	1,650.00 FL	*1,650.00 FL
26	1		*REAR WINDSCREEN SOLAR FIRM	Not Necessary	450.00 FS	*- FS
27	1		*PRIVATE HIRER STICKER	Not Necessary	20.00 FS	*- FS
28	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
29	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
30	2		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
31	1		*REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS
32	1		*REAR NO. PLATE LAMP LH	Serviceable	38.50 FL	*- FL
33	1		*REAR NO. PLATE LAMP RH	Serviceable	38.50 FL	*- FL
34	1		*REAR BUMPER	Bent	1,150.60 FL	*1,150.60 FL
35	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
36	1		*REAR BUMPER SIDE RETAINER LH	Cracked	26.50 FL	*26.50 FL
37	1		*REAR BUMPER SIDE RETAINER RH	Cracked	26.50 FL	*26.50 FL
38	1		*REAR BUMPER BRACKET LH	Repair	48.70 FL	*- FL
39	1		*REAR BUMPER BRACKET RH	Repair	48.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*REAR BUMPER SPONGE	Cracked	179.00 FL	*179.00 FL
41	1		*REAR BUMPER REFLECTOR LH	Scratched	45.00 FL	*45.00 FL
42	1		*REAR BUMPER REFLECTOR RH	Cracked	45.00 FL	*45.00 FL
43	1		*REAR BUMPER REFLECTOR GARNISH LH	Dented	45.00 FL	*45.00 FL
44	1		*REAR BUMPER REFLECTOR GARNISH RH	Dented	45.00 FL	*45.00 FL
45	1		*TAIL DOOR	Bent	1,193.00 FL	*1,193.00 FL
46	1		*TAIL DOOR LOCK	Bent / Jammed	157.10 FL	*157.10 FL
47	1		*TAIL DOOR EMBLEM	Necessary	38.00 FL	*38.00 FL
48	1		*WORDING SHUTTLE	Necessary	55.00 FL	*55.00 FL
49	1		*WORDING HYBRID	Necessary	80.10 FL	*80.10 FL
50	1		*TAIL DOOR CHROME	Warped	383.10 FL	*383.10 FL
51	1		*TAIL DOOR TRIM	Buckled	320.00 FL	*320.00 FL
52	10		*TAIL DOOR TRIM CLIP	Necessary	35.00 FL	*35.00 FL
53	1		*TAILDOOR REFLECTOR LH	Cracked	395.00 FL	*395.00 FL
54	1		*TAILDOOR REFLECTOR RH	Cracked	395.00 FL	*395.00 FL
55	1		*TAIL END PANEL	Bent	560.80 FL	*560.80 FL
56	1		*TAIL END PANEL GARNISH	Dented	155.50 FL	*155.50 FL
57	10		*TAIL END PANEL GARNISH CLIP	Necessary	35.00 FL	*35.00 FL
58	1		*BOOT WEATHERSTRIP	Dented / Cut	168.50 FL	*168.50 FL
59	1		*TAIL LAMP LH	Cracked	520.50 FL	*520.50 FL
60	1		*TAIL LAMP RH	Cracked	520.50 FL	*520.50 FL
61	1		*SPARE TYRE WELL PANEL	Bent	956.00 FL	*956.00 FL
62	1		*SPARE TYRE BOARD	Deformed	655.00 FL	*655.00 FL
63	1		*REAR CAMERA	Serviceable	680.00 FS	*- FS
64	1		*GARGO BOX	Serviceable	295.00 FL	*- FL
65	1		*TAIL DOOR INNER POCKET	Dented	19.50 FL	*19.50 FL
66	1		*FENDER INNER TRIM LH	Deformed	455.00 FL	*455.00 FL
67	1		*FENDER INNER TRIM RH	Deformed	455.00 FL	*455.00 FL
68	1		*REAR WIPER MOTOR	Serviceable	490.00 FL	*- FL
69	1		*REAR WIPER MOTOR LINK (NPA)	Serviceable	0.00 FL	*- FL
70	1		*REAR WIPER ARM	Serviceable	95.50 FL	*- FL
71	1		*REAR WIPER ARM COVER	Serviceable	15.00 FL	*- FL
72	1		*REAR WIPER BLADE	Serviceable	66.50 FL	*- FL
73	1		*REAR BUMPER TOW COVER	Serviceable	16.50 FL	*- FL
74	1		*FRONT SUPPORT TOP GARNISH	Cracked	89.20 FL	*89.20 FL
75	1		*REAR TOOL KIT SPONGE	Cracked	165.00 FL	*165.00 FL
76	1		*REAR ANTENNA CONTROL	Cracked	78.10 FL	*78.10 FL
77	1		*REAR SMART BUZZER	Cracked	108.00 FL	*108.00 FL
78	1		*REAR HYBRID BATTERY AIR DUCT	Dented	265.60 FL	*265.60 FL
79	1		*FRONT GRILLE STAY	Distorted	65.00 FL	*65.00 FL
80	1		*REAR PILLAR LOWER QUARTER PANEL LH	Bent	125.80 FL	*125.80 FL
81	1		*REAR PILLAR LOWER QUARTER PANEL RH	Bent	125.80 FL	*125.80 FL
82	1		*CARGO BOX BOARD	Deformed	386.00 FL	*386.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,385.70	20,777.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,579.14	4,089.56
Total Parts (\$\$)	19,806.56	16,688.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, FRONT BUMPER, BONNET, SUPPORT PANEL)	New	2,200.00	1,600.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL, FRONT BUMPER, BONNET, SUPPORT PANEL)	New	2,200.00	1,800.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	50.00	30.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD	New	150.00	100.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO TUFF COAT	New	250.00	120.00
8	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
9	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	30.00
10	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD, TO TOP UP A/C GAS	New	150.00	0.00
11	TOWING FEE	New	120.00	60.00
Gross Labour Cost (S\$)			5,600.00	3,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >