



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Ho Kok Soon Blk 80 Bedok North Road #14-280 Singapore 460080 Contact No Mobile: 98501575	Cust No/Name	/Mr Ho Kok Soon
	Reg No/Reg Date	SLE6774S / 29/07/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH001574
	Engine No	3A92UDG3209
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	08/06/2019/ 16:21	QUE	261 / Edwin Caina	40756		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							3000.00
RENEW & RE-ALIGN RR DAMAGED PORTION:							
-RENEW RR BUMPER							
-REPAIR RR FENDER LH , RR END PNL & BOOTLID							
E PNT98000							1700.00
RESPRAY RR BUMPER , RR END PNL , BOOTLID & RR FENDER LH							
E PNT88000							275.00
REMOVE & REFIT RR FLR BOARD,TRIM & CARPET TO FACILITATE REPAIR							
A 54900099							50.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							120.00
APPLY ANTI CORROSION ON AFFECETED AREAS							
E PNT88000							100.00
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							220.00
SUPPLY REVERSE SENSOR							
M SUNDRY							40.00
SUPPLY C&C BADGE							
M SUNDRY							40.00
SUPPLY MIVEC EMBLEM							
M SUNDRY							50.00
Sundries							
M FACE,RR BUMPER				1.00	740.00	00.00	740.00
M CLIP,RR BUMPER				4.00	3.00	00.00	12.00
M BRACKET,RR BUMPER,LH				1.00	27.00	00.00	27.00
M BRACKET,RR BUMPER,RH				1.00	27.00	00.00	27.00
M LAMP ASSY,COMB,RR LH				1.00	332.00	00.00	332.00
M MARK,THREE-DIA				1.00	45.00	00.00	45.00
M MARK,ATTRAGE				1.00	21.00	00.00	21.00
SURVEYOR NAME: <u>Rahul - Hy 9000068</u>							
SURVEYOR SIGNATURE: <u>[Signature]</u>							
DATE: <u>22/07/19 @ 1300</u>							
REMARKS: <u>5 days</u>							
<u>Reay before print</u>							

Confirm & accepted by

Net 6,999.00
 7% GST on 6999.00 489.93
Total Payable 7,488.93

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.