

LOH HENG

Automotive Repair Services
Accident Insurance Claims

6-Nov-19

India International Insurance Pte Ltd

Attn. : Motor Claim Department

Re : Estimated Quotation

Vehicle No. SJL5710U

S/N		Amount (\$S)
A	PART REPLACEMENT	
	Rear bumper <i>CM</i>	\$ 784.00 ✓
	Rear bumper spone	\$ 261.00 ?
	Retainer bumper right	\$ <i>PIV</i> 39.00 ✓
	Boot lid lock <i>RL</i>	\$ 298.00 ✓
	Boot rubber <i>Dis/ln</i>	\$ 254.00 501m
	Rear bumper reinforcement	\$ <i>Ry</i> 398.00 ✓
	Rear right tail mudguard lamp	\$ 491.00 ?
	Rear Tail panel	\$ <i>Ry</i> 478.00 ✓
	Boot Lid emblem 'IMPREZA' <i>M</i>	\$ 76.00 ✓
	Boot Lid emblem 'SUBARU' <i>M</i>	\$ 98.00 ✓
	Tail boot lib <i>Ry</i>	\$ 1,218.00 ✓
	Tail lib right lamp	\$ <i>Sn</i> 356.00 X
	Rear exhaust <i>Ry</i>	\$ 1,154.00 ✓
	Tail top panel garnish <i>Bu</i>	\$ 167.00 ✓
	Tail lamp right garnish	\$ 183.00
		\$ 6,255.00
	Sub-Total	
	Less: 10% <i>20%</i>	\$ 5,629.50
B	LABOUR CHARGES	
	To change rear damaged accident area, cut reweld tail panel and replacement parts.	\$ 950.00 650
	To redo sealant on gap.	\$ 80.00 30
	To remove sockets wiring and refix	\$ 70.00 20
	To rust proof on the affected area	\$ 90.00 60
	To putty and respraying damaged area	\$ 900.00 800
	Tow to workshop (4 wheel lifted) <i>(Bill)</i>	\$ 120.00 ✓
	Remove rear glass and change new sealant	\$ 200.00 120
	GRAND TOTAL OF A & B	\$ 8,039.50

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

Not Notarised
U/L Rep & ?
Resurvey After Paint
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: