

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 1991014942
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
HUI
LI YAO, LAURA
7 SIMEI STREET 4
#11-03
Singapore 529864

Document no.
Document date 11-06-2019
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2019000924/ 1
Job order date 11-06-2019
Service Advisor EDMUND, HUI HUANG GOH

License plate	Model code	First registration	VIN	Model	Mileage
SLS3696E	5G13HZ	20-09-2017	WVWZZZAUZHW112090	Golf 1.4 CLBM 92 TSI D7F	9,800

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5G0807217BNGRU	Cover For Bumper Primed	1	pcs.	1,083.64	#1	1,083.64	1,159.49
5G0807248F	Foam Insert	1	pcs.	38.75	#1	38.75	41.46
5G0807109AL	Impact Beam	1	pcs.	587.84	#1	587.84	628.99
5G0807723D	Support Part (BUMPER GUIDE LH)	1	pcs.	50.49	#1	50.49	54.02
5G0807724D	Support Part (BUMPER GUIDE RH)	1	pcs.	50.49	#1	50.49	54.02
5G0807049A	Guide Piece (BUMPER BRACKET LH)	1	pcs.	19.18	#1	19.18	20.52
5G0807050A	Guide Piece (BUMPER BRACKET RH)	1	pcs.	19.18	#1	19.18	20.52
5G0805915 9B9	Retainer For Spoiler Sati	1	pcs.	174.53	#1	174.53	186.75
5G0853677 9B9	Cooling Air Grill Satin B (CENTER LOWER GRILL)	1	pcs.	119.98	#1	119.98	128.38
5G0853211E 9B9	Cover Part For Bumper Sat (LH FOGLAMP GRILL)	1	pcs.	25.58	#1	25.58	27.37
5G0853665 9B9	Cooling Air Grill Satin B (LH LOWER GRILLE)	1	pcs.	84.62	#1	84.62	90.54
5G0919493	Sensor Bracket	1	pcs.	13.21	#1	13.21	14.13
5G0919493A	Sensor Bracket	2	pcs.	13.21	#1	26.42	28.27
5G0919494	Sensor Bracket	1	pcs.	13.21	#1	13.21	14.13
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29	#1	74.29	79.49
5Q0919133 9B9	Seal Ring Satin Black	1	pcs.	1.18	#1	1.18	1.26
5Q0919275B GRU	Sensor Primed	1	pcs.	164.62	#1	164.62	176.14
5G2941005E	Twin Halogen Headlamps	1	pcs.	694.01	#1	694.01	742.59
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	Spray Painting	4	pcs.	800.00	#1	3,200.00	3,424.00

Quotation valid till 18-06-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	9,858.12	7%	743.27	10,618.12	11,361.39
Total	760.00	9,858.12		743.27	10,618.12	11,361.39

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer

Service Advisor