

Kp

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

MCQUIRENS RENTAL PTE LTD  
c/o 46 Lenton Plain  
Singapore 786548

Date: 11-06-19

| QUANTITY                                    | PARTICULARS                             | AMOUNT (\$)               |
|---------------------------------------------|-----------------------------------------|---------------------------|
| <b>RE : TOYOTA COROLLA AXIO/ SKZ 8576 K</b> |                                         |                           |
| 1 pc                                        | rear boot lid <i>895.00</i>             | <i>Bu</i> 975.30          |
| 1 pc                                        | rear boot emblem logo <i>59.20</i>      | <i>m</i> 97.60            |
| 1 pc                                        | rear boot emblem "G" <i>42.00</i>       | <i>m</i> 56.80            |
| 1 pc                                        | rear boot emblem 'AXIO' <i>45.00</i>    | <i>m</i> 86.50            |
| 1 pc                                        | rear boot emblem 'COROLLA' <i>59.10</i> | <i>m</i> 75.80            |
| 2 pcs                                       | rear boot hinge                         | @ 192.40                  |
| 1 pc                                        | rear boot lock                          | <i>n</i> 384.80           |
| 1 pc                                        | rear boot lock catch                    | <i>n</i> 397.80           |
| 1 pc                                        | rear boot weatherstrip <i>187.00</i>    | <i>n</i> 68.30            |
| 1 pc                                        | rear boot lock sensor <i>189.20</i>     | <i>n</i> 296.80           |
| 1 pc                                        | rear bumper <i>590.20</i>               | <i>n</i> 286.90           |
| 2 pcs                                       | rear bumper retainer <i>c 98.10</i>     | <i>Bu</i> 836.70          |
| 2 pcs                                       | rear bumper lamp                        | @ 197.50                  |
| 2 pcs                                       | rear bumper bracket                     | @ 115.30                  |
| 1 pc                                        | rear end panel                          | @ 89.40                   |
| 1 pc                                        | rear end panel garnish <i>278.10</i>    | <i>m</i> 178.80           |
| 2 pcs                                       | rear tail lamp assy <i>548.40</i>       | <i>n</i> 487.50           |
| 1 pc                                        | spare tyre board                        | <i>set</i> 309.70         |
| 1 pc                                        | exhaust silencer                        | <i>sm</i> 1,297.80        |
|                                             |                                         | <i>n</i> 308.70           |
|                                             |                                         | <i>n</i> 612.50           |
|                                             | Sub-total                               | 7,383.90                  |
|                                             | Less 25%                                | 1,845.98                  |
|                                             | Sub-total                               | 5,537.93                  |
| 1 set                                       | reverse sensor                          | s.nett <i>Phon</i> 250.00 |
|                                             | Sub-total                               | 5,787.93                  |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before or after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 2

*Not Authorised*  
*LT 12mg 82950k*  
*Meaning After Paint*  
*Galaxy*

|                                                                                                               |          |     |
|---------------------------------------------------------------------------------------------------------------|----------|-----|
| Balance brought forward                                                                                       | 5,787.93 |     |
| To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas. | 800.00   | 500 |
| To check wiring system.                                                                                       | 50.00    | 20  |
| To spray painting on affected areas.                                                                          | 800.00   | 600 |
| To apply rust proofing on affected areas.                                                                     | 80.00    | 30  |
| To apply waterproof sealant on affected areas.                                                                | nn 80.00 | x   |
| To install reverse sensors                                                                                    | 60.00    | 50  |
| To carry our exhaust works                                                                                    | nn 80.00 | x   |
| Total                                                                                                         | 7,737.93 |     |