

A/Kh - Ckk

1/p



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLU 1186 M

Not Authorized
Purway Repair

Parts	(a) Cost / List Price Items	\$ <u>Finalised 2086.03</u>	7,373.68
	Plus/Less 25%	\$ <u>521.51</u>	1,843.42
	Total of Cost / List	\$ <u>1564.52</u>	5,530.26
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	5,530.26
Labour		\$ <u>1030.00</u>	3,110.00
Total		\$ <u>2594.52</u>	8,640.26

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kennoth

Company

Ckk

Survey conducted on

4/6/19

at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor

Le

Date:

4/6/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. : SLU 1186 M
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU103576306

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door	1	\$1,121.75		X
2	LH front door hinge top	1	\$78.30		X
3	LH front door hinge bottom	1	\$78.30		X
4	LH front door lock	1	\$470.33		X
5	LH front door catch	1	\$43.95		X
6	LH front door checker	1	\$130.70		X
7	LH front door weatherstrip	1	\$211.69		X
8	LHF door outer handle	1	\$391.75		✓
9	LHF door glass outer moulding	1	\$121.75		X
10	LHF door centre pillar garnish	1	\$78.50		✓
11	LH rear door	1	\$1,211.40		✓
12	LH rear door hinge top	1	\$78.34		X
13	LH rear door hinge bottom	1	\$78.34		✓
14	LH rear door lock	1	\$425.63		X
15	LH rear door catch	1	\$37.80		X
16	LH rear door checker	1	\$126.70		X
17	LH rear door weatherstrip	1	\$212.47		X
18	LH rear door trim	1	\$856.90		X
19	LHR door outer handle	1	\$98.70		✓
20	LHR door glass	1	\$458.77		X
21	LHR door glass outer moulding	1	\$107.80		✓
22	LHR power window motor	1	\$671.48		X
23	LHR power window regulator	1	\$202.49		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1878-15

Spare Parts

Vehicle No. : SLU 1186 M
Make & Model : TOYOTA PRIUS
Chassis No. : JTDKB3FU103576306

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LHR door centre pillar garnish <i>Sn</i>	1	\$79.84		<i>X</i>
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio Industrial Park 2, #01-250/01-251, Singapore 569536.
Tel : 6484 1221 Fax : 6484 7829
385 Sin Ming Drive (beside Vicom) Singapore 575718.
Tel : 6753 2112 Fax : 6451 0394
Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Spare Parts

Vehicle No. : SLU 1186 M
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU103576306

Submit By : CARMEN LIM
Year Manufacture : 2017
Engine No. :
Cost / List

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door handle adapter <i>CN/DJ</i>	1	\$197.88		✓
2		1			
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

197.88



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLU 1186 M**

Submit By : **Carmen Lim**

Make & Model : **TOYOTA PRIUS**

Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHF DOOR,LHR DOOR,LHR FENDER, LH SIDE SKIRT)	\$1,000.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHF DOOR,LHR DOOR,LHR FENDER, LH SIDE SKIRT)	\$1,000.00	500
3	To check Wiring	\$50.00	20
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	} 80
5	To remove & refit LHF door glass & LHR door glass	\$240.00	
6	To do wheel alignment <i>nn</i>	\$120.00	X
7	To remove & refit inner seat & upholstery to assist work load. <i>nn</i>	\$250.00	X
8	To tuff coat.	\$150.00	300

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.