

Cecilia

LICK

SAT

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

2

1636

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0289/2019
DATE : 08-JUN-2019

08/06/19

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : M/S LUZERNE PTE LTD
ADDRESS : 72 BENDEMEER ROAD
#02-22 LUZERNE
S(339941)
TELEPHONE NO : 65665656

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-YK2971E
VEHICLE NO : GBH9262K
MODEL CODE : MVL2RDKE26KW3JBT-D
MODEL/YEAR : NISSAN NV350 PANEL VAN SDR 2.5 SAT MY2018
ENGINE NO : YD25038191B
CHASSIS NO : JN1MC2E2620030682
MILEAGE : 1 KM
DATE IN : 08/06/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 23/05/2019

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBH9262K

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X ¹⁴
2 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	mc - X ¹⁷
3 UG14	RENEW REAR WINDSCREEN GLASS ASSY.	150.00	mc -
4 ZZ/001	REPAIR RH REAR FENDER	600.00	X ¹⁷
5 ZZ/002	S/PAINT RH REAR FENDER	800.00	X ¹⁷
6 ZZ/003	RENEW WIPER MOTOR, ARM AND COVER	120.00	/
7 ZZ/004	CHECK LIGHTING 3RD BRAKE	48.00	/
8 ZZ/005	COMPANY LOGO ON AFFECTED PORTION	1000.00	X ¹⁴
TOTAL LABOUR CHARGES		2988.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBH9262K

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	COVER-BACK WIPER <i>ms</i>	90920-3XA0A	48.00			
2	SEAL RUBBER PIV WIPER <i>? XSVL</i>	28714-CY010			6.70	
3	MOTOR-WIPER <i>? XSVL</i>	28710-3XA0A			233.20	
4	COVER-ARM, BACK <i>scr</i>	28782-1FC0A			12.40	
5	ARM ASSY-RR WDW <i>? XSVL</i>	28781-3XA0A			72.30	
6	LAMP ASSY-STOP 3RD <i>? XSVL</i>	26590-3XA0A			237.50	
7	GLASS-TAIL GATE <i>ms</i>	90300-3XA0A	837.00			
8	RUBBER-DUM <i>ms</i>	G2716-89900	60.20			
9	REAR W/SCREEN SEALANT <i>ms</i>	SEALANT - 4			80.00	
SUB TOTAL			945.20	0.00	642.10	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			189.04	0.00	0.00	
GRAND TOTAL			756.16	0.00	642.10	
OVERALL TOTAL			1398.26			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

3rd BRAKE LIGHT SEAL CASKET - ms

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBH9262K

TOTAL LABOUR CHARGES	2988.00
TOTAL SPARE PARTS CHARGES	1398.26
GRAND TOTAL	4386.26 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasm - 4p 90010068
SURVEYED DATE	:	19/07/19 @ 1100
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 2 days
LIABILITY	:	0.00
REMARKS	:	Reg after repair

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be submitted for approval
- This estimate is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer
Signature: _____
Date: _____

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0289/2019
DATE : 08-JUN-2019

209/19.

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

0/5

OWNER'S NAME : M/S LUZERNE PTE LTD
ADDRESS : 72 BENDEMEER ROAD
#02-22 LUZERNE
S(339941)
TELEPHONE NO : 65665656

PPS

20045

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-YK2971E
VEHICLE NO : GBH9262K
MODEL CODE : MVL2RDKE26KW3JBT-D
MODEL/YEAR : NISSAN NV350 PANEL VAN SDR 2.5 SAT MY2018
ENGINE NO : YD25038191B
CHASSIS NO : JN1MC2E26Z0030682
MILEAGE : 1 KM
DATE IN : 08/06/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 23/05/2019

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBH9262K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00
2	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	.00
3	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	150.00	150.00 ✓
4	ZZ/001	REPAIR RH REAR FENDER	600.00	.00
5	ZZ/002	S/PAINT RH REAR FENDER	800.00	.00
6	ZZ/003	RENEW WIPER MOTOR, ARM AND COVER	120.00	120.00 ✓
7	ZZ/004	CHECK LIGHTING 3RD BRAKE	48.00	48.00 ✓
8	ZZ/005	COMPANY LOGO ON AFFECTED PORTION	1000.00	.00
TOTAL LABOUR CHARGES			2988.00	318.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBH9262K

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	GASKET 3RD BRAKE LIGHT	26593-3XA0A			46.90 OK
2	COVER-BACK WIPER	90920-3XA0A	48.00		OK
3	SEAL RUBBER PIV WIPER	28714-CY010			6.70 X
4	MOTOR-WIPER	28710-3XA0A			233.20 X
5	COVER-ARM, BACK	28782-1FC0A			12.40 OK
6	ARM ASSY-RR WDW	28781-3XA0A			72.30 X
7	LAMP ASSY-STOP 3RD	26590-3XA0A			237.50 X
8	GLASS-TAIL GATE	90300-3XA0A	837.00		OK
9	RUBBER-DUM	G2716-89900	60.20		OK
10	REAR W/SCREEN SEALANT	SEALANT - 4			80.00 OK
SUB TOTAL			945.20	0.00	139.30
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			189.04	0.00	0.00
GRAND TOTAL			756.16	0.00	139.30
OVERALL TOTAL			895.46		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO GBH9262K

NETT ITEM 945.20
LESS 20.00%) -189.04
NETT AMOUNT 756.16

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 139.30
LESS .00%) 0.00
SPECIAL NETT AMOUNT 139.30

TOTAL LABOUR CHARGES 318.00
TOTAL SPARE PARTS CHARGES 895.46

TOTAL CHARGES 1213.46
ADD 7 % GST 84.94

GRAND TOTAL 1298.40
