

ASS. REC. BY:

REF:

CS/AGI 19010340/B3d327

Special Instruction:

Survivor: LimASSIGNMENT (Office)

From (Person):

Ivy

of

AGI

Date/Time:

10/6/2019 4:39pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDQ 73X

Insured:

SLA 3113R

at Workshop m/s

Beam Auto Pro

Tel:

62581955

of

160 2/m #01-14

Policy No:

Claim No:

C10003261/AH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/6

Person Contacted:

MichelleVehicle IN / OUT

Date/Time

Action/Instruction (☒) EstimateSDQ 73X - XSLA 3113R - X

ASSIGNMENT

From: Date: 12/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDW 73X

at Workshop m/s Team AutoPro

of 385 Sin Ming Drive.

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SDW 73X Yr Regn: 25/3/2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523i c.c 2497

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 69723 T/Radio: Insured / Std / NI / NA

Eng/No: 10407696X/52B25AF

C/No: WBAFP32050C864591

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Hankook 225/55/16

R: Michelin 225/55/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook Frt / Michelin Rear

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 7/6/19 D.O.I. 12/6/19

Survey held at Team AutoPro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/07/19	Confirmed L/S 94,850/- @ 4 days PLS see my remarks with 176. (\$ 6,520.45 Red - 57%) 43 4850/2 Team Lin 24/7/19
	MV 45,000/2 PV 35,209/2 NY 3,791/2
	RECEIVED 13 AUG 2019
	Team Lin 12/6/19

Date/Time, File Pass to?

☐ : Preli. Report

1) Typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ 4,850/- L/S)

390

390

Shirley Hiew (LKK Auto)

From: TeamAuto Pro <teamautooffice@gmail.com>
Sent: Saturday, 10 August 2019 3:31 PM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: Re: SDW 73X / DOA: 07-06-2019

Dear Shirley,

We confirmed our acceptance to your proposed COR at \$4850 / 4 working days.

Kindly advise OIC and reference number for our submission of LOD.

Thank you.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,
Adel
Team AutoPro Pte Ltd
Tel: 6258 1955
Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722
Reporting Centre: 385 Sin Ming Drive #01-02 Vicom Inspection Centre Singapore 575718

On Wed, Jul 24, 2019 at 3:51 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Adelle,

Please confirm L/S \$ 4,850.00/4 days .

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Monday, 10 June 2019 4:39 PM
To: Admin-D (LKKAuto)
Cc: SUR; Albert Hong
Subject: Claim ref:C10003261/AH || OI- SLA3113R (Brown) TP- SDQ73X || Est:0.00 || Team Autopro
Attachments: 2D.73.3113.pdf

Hi Team,

We would like to arrange TP Survey for SDQ73X. Please see below email for reference.

Kindly confirm.

Regards,

Ivy
Admin Executive, Claims

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: TeamAutoPro North <teamautopl@gmail.com>
Sent: Monday, 10 June 2019 3:39 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: 2 Days Notice: SDW 73 X (Our Ref) and SLA 3113 R (Your Ref) Dated 7th June 2019

Dear Sir/Madam,
Road Traffic Accident Involving SDW 73 X (Our Ref) and SLA 3113 R (Your Ref)
Dated 7th June 2019, Time around 06:15
@ Blk 108 Canberra Walk Deck 2A Multi storey carpark

We represent our client; Low Ai Shi, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SDW 73 X and your insured's vehicle registration number: SLA 3113 R.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

For efficiency purpose, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors, via email to the following personnel:-**

Contact Person	Alan Koh	9092 7279
	Frederick Lim	9674 6635
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,
Michelle Lim
Team AutoPro Pte Ltd
Tel: 6258 1955
Fax: 6258 1956

385 Sin Ming Drive
#01-02 Vicom Inspection Centre
Singapore 575718



Virus-free. www.avg.com

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4106J

Vehicle Details

Vehicle No.: SDW73X
Vehicle to be Exported: No
Intended Deregistration Date: 12 Jun 2019
Vehicle Make: B.M.W.
Vehicle Model: 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour: White
Manufacturing Year: 2011
Engine No.: 10407696N52B25AF
Chassis No.: WBAFP32050C864591
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$45,547.00
Original Registration Date: 25 Mar 2011
First Registration Date: 25 Mar 2011
Transfer Count: 1
Actual ARF Paid: \$45,547.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Mar 2021
PARF Rebate Amount: \$25,050.00

Intended COE Rebate Details

COE Expiry Date: 24 Mar 2021
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$57,002.00
COE Rebate Amount: \$10,159.00
Total Rebate Amount: \$35,209.00

The information contained herein is correct as at 12 Jun 2019

OK

Dep 14,990/yr

MV 45,000/2
PV 35,209/2
NV 9,791/2

TG Lim
12/6/19



BMW 5 Series 523i **\$46,800** **\$14,990 /yr** **07-Mar-2011** **2,497 cc** **93,000 km** **Luxury** **Available**

1 Owner, Low Mileage Done Only 93,000Km, 100% Loan And Balloon Scheme Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.

Faster Auto Trading

Posted: 08-Jun-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



BMW 5 Series 523i **\$49,800** **\$14,530 /yr** **26-Apr-2011** **2,497 cc** **123,000 km** **Luxury** **Available**

Come With A Free Comprehensive 120 Points Check And 6 Months Warranty From MBM. Accident Free. Most Wear And Tear Parts Replaced. Low Bank Interest Rate From 1.99% Only. In House Loan Up To 90% Of Th...

Posted: 08-Jun-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



BMW 5 Series 523i **\$54,000** **\$15,100 /yr** **02-Sep-2011** **2,497 cc** **115,000 km** **Luxury** **Available**

Full M5 Body Kit, Original Breyton Rims 20" With Warranty Card, Full PZero Tyres, Eisenman Exhaust, Front Brakes 6 Pot, 4 Aprakovic Exhaust Tips, Blistein Shock Absorbers, New Paint Metallic Grey High...

Monster Motors Pte Ltd

Posted: 07-Jun-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

PREMIUM AD

ADVERTISING



LOWEST PRICE GUARANTEE

HUAWEI Mate 20 Pro
\$189 (U.P. \$859)
\$90 2-year plan
25GB + FREE weekend data
BUY ONLINE



BMW 5 Series 523i **\$45,800** **\$14,800 /yr** **21-Jan-2011** **2,497 cc** **122,000 km** **Luxury** **Available**

Good Condition. Well Maintained. Flexible & Fast Arrangement For Loan & Insurance. Trade In Are Welcomed! Hurry Call Our Friendly Sales For More Info Or Visit Us At Our Showroom For Test Drive!

Posted: 07-Jun-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



BMW 5 Series 523i **\$53,800** **\$13,950 /yr** **14-Jul-2011** **2,497 cc** **160,000 km** **Luxury** **Available**

One Of The Best In Its Class, Remarkable Design And Ride Comfort, Smooth And Responsive Engine For Excellent Fuel Efficiency. Pristine Condition. 100% Accident Free With No Repairs Needed. STA Evaluat...

Euro Performance Asia Pte Ltd

Posted: 05-Jun-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

PREMIUM AD



BMW 5 Series 523i **-** **N.A** **29-Apr-2011** **2,497 cc** **-** **Luxury** **SOLD**

Car Done Up. No Problems. Buy With Peace Of Mind! Lowest Depreciation Of This Class! Extremely Well Maintained. Servicing Done. Tires Just Changed. Comes With Warranty For Engine And Gearbox. Super Co...

Posted: 03-Jun-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

DIRECT OWNER



BMW 5 Series 523i Highline **-** **N.A** **27-Apr-2011** **2,497 cc** **-** **Luxury** **SOLD**

Highline PML Model With Low Mileage Yet Lowest Depreciation, Beautiful White With Gray Interior! High Spec With GPS, Auto Tailgate And Parking Assist. Excellent Condition. Well Maintained. Great Condi...

Posted: 02-Jun-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



BMW 5 Series 523i **\$46,888** **\$13,830 /yr** **10-May-2011** **2,497 cc** **123,558 km** **Luxury** **Available**

Sporty White With 19" Sports Rims. Stock Condition. Well Maintained. Many Parts Had Been Replace With Receipt Proven. Need To Touch Up Paint Work. High Loan And Trade In Available For Arrangement. Cal...

Posted: 01-Jun-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

DIRECT OWNER



BMW 5 Series 523i **\$48,800** **\$15,700 /yr** **31-Mar-2011** **2,497 cc** **-** **Luxury** **Available**

Posted: 31-May-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW



BMW 5 Series 523i **\$54,800** **\$14,580 /yr** **30-Sep-2011** **2,497 cc** **110,000 km** **Luxury** **Available**

Executive Popular Luxury Sedan That Blends Perfectly For Business And Leisure. Immaculate Condition.

Posted: 31-May-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW

DIRECT OWNER

Compare



SINGAPORE POLICE FORCE

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999



T/20190607/2162

1 of 3

Report No. T/20190607/2162

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
07/06/2019 18:38

Vide Report No.:

Station Diary No.
99

Informant's Particulars

Name of Informant:
LOW WEI WEN

Address:
APT BLK 108C CANBERRA WALK #09-23 SINGAPORE
753108

ID Type / ID No.:
NRIC NO / S8506606D

Contact No.:
Home/Office: Mobile: 82003050

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Male Age: 34 Date of Birth: 10/03/1985

Type of Informant:
Driver

Race:
Chinese

Language:

Institution / School Name:

Occupation:
LOGISTICS OFFICER

Driving Licence Information:
Class: 3

Date of Expiry:

General Information of the Accident

Type of
Accident:

Non-Injury
Hit and Run

Drink
Drive:
No

Date/Time of
Accident:
07/06/2019 06:15

Type of Location:
Car Park

Location:
Along Road 1
CANBERRA LINK

At Multi-storey carpark B/108 Canberra Walk, Deck 2A, unknown lot
(unable to select Canberra Walk as Road 1)

Weather:

Road Surface:

Road Speed Limit:

Traffic Flow:
One Way

Traffic Control:
Not Controlled

Traffic Volume:

Type of Collision:
Moving Vehicle Against - Parked Vehicle

Anyone conveyed by
ambulance:
No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SDW73X	Car				Slightly Damaged	0
SLA3113R	Car					1

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE

Police Station Of Origin:
Yishun North N.P.C.
31 Yishun Central SINGAPORE 768827
Tel No. 1600-8529999



T/20190607/2162

Report No. T/20190607/2162

CONTINUATION OF REPORT

Name	LOW WEI WEN	ID No.	S8506606D
Related Vehicle	SDW73X (Car)	Contact No.	82003050
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 6/6/19 at about 2100hrs, my sister parked my vehicle, SDW73X, a white BMW, at deck 2A of Blk 108 Canberra Walk multi-storey carpark, unknown lot. Everything was last seen intact then.

I returned to my vehicle on 7/6/19 at about 0800hrs to send my child to school. I later went to work and was in my office when my colleague messaged me at about 1015hrs that my car looks like it was involved in an accident. I returned to my car and saw that there were scratches and cracks at the front right bumper and headlight area. I reviewed my CCTV footage and saw that while parked at my multi-storey carpark at Blk 108 Canberra Walk, on 7/6/19 at 0614hrs, a black Mazda 6, SLA3113R which was parked on my right, exited from his lot and the left side of his vehicle grazed the front right bumper area of my car. The driver was seen to have alighted and came to make a check on my car before quickly returning to his vehicle and driving off. A passenger was also seen looking from the front passenger seat of his car. The driver of the Mazda seems to be a male Chinese in his 50s-60s. I have seen him before and believe that he stays in my estate.

I wish to state that this is the first time such an incident occurred to me. I do not personally know the other party. I have the CCTV footage of the incident and pictures of the damages to my car. No particulars were left on my car by the driver of the Mazda.



**SINGAPORE
POLICE FORCE**



T/20190607/2162

3 of 3

Report No. T/20190607/2162

Police Station Of Origin:
Yishun North N P C
31 Yishun Central SINGAPORE 768827
Tel No. 1800-8529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you do not have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sr Staff Sgt SZE WEIJIE, WILSON

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt TAN JEOK LENG

Contact No. 65476144

Signature Of Informant

Date/Time

07/06/2019 18:38

Classification Of Case

Authentication Stamp

NP158

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	WIT ✓		
1005	992341	Frt Bumper Clips	NEC ✓		
1006	991325	Frt Bumper Bracket	?		
1007	991462	Frt Bumper Side Retainer	NEC ✓		
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor	WIT ✓		
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	?		
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp	?		
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	?		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: SDW 73X

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Bumper emblem	NEC ✓		
		RH Headlamp washer & cap	BR ✓		

No of Items: 10

APPROVER: TGLin

12/6/19

SJE :	LKK Mr Lim T-G	Vehicle Nos :	SDW 73X
Date of Survey :		Model :	BMW 523i
Date of ReSurvey:	After-Paint:	Year :	
Contacts :		Chassis No :	

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front bumper	1	\$ 1,205.00	\$ ✓ 1,205.00
2	Front bumper retainer	2	\$ 65.00	\$ ✓ 130.00
3	Front bumper reinforcement	1	\$ 814.00	\$ 814.00
4	Front bumper inner sponge	1	\$ 86.00	\$ 86.00
5	Front bumper nozzle cover	1	\$ 63.00	\$ ✓ 63.00
6	Front bumper logo	1	\$ 69.00	\$ ✓ 69.00
7	Front bumper sensor	2	\$ 383.00	\$ 766.00 766.00
8	Front bumper fog lamp	1	\$ 219.00	\$ ✓ 219.00
9	Front bumper fog lamp garnish	1	\$ 116.20	\$ ✓ 116.20
10	Headlamp Rh	1	\$ 2,552.00	\$ 2,552.00 2,552.00
11	Headlamp ballast Rh	1	\$ 1,155.00	\$ 1,155.00
12	Front fender Rh	1	\$ 1,677.90	\$ 1,677.90
Parts Sub Total :				\$ 5,060.35
5% Discount				\$ 253.02
PARTS TOTAL :				\$ 4,807.33

DDV
NECV
RX
NNX
BRV
NECV
Cut
BRV
BRV
BR
RX

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 60.00	\$ 60.00
2	Front bumper clips	1	\$ 50.00	\$ 50.00
3	Headlamp seal	1	\$ 80.00	\$ 80.00
4	Front fender sealant	1	\$ 100.00	\$ 100.00
SPECIAL NETT TOTAL :				\$ 60.00

NNX
NECV
NNA
309
NECV

Nos.	LABOUR	S\$
1	R&R distance sensor	\$ 60.00 100.00
2	R&R wire harness to facilitate repair, reconnect and check function	\$ 50.00 100.00
3	R&R front fender signal lamp	\$ 50.00 80.00
4	Headlamp adjustment and alignment	\$ 80.00
5	Panel beat	\$ 700.00 1,200.00
6	Rust proofing	\$ 60.00 100.00
7	Spray painting	\$ 600.00 1,200.00
LABOUR TOTAL :		\$ 1,240.00

✓
✓
X
X
6002
3002

Resurvey on 13/6/19
1410 hrs
Lump sum Repair
Repair days 6 4

12/7/19
Parts 4807.33
SN 60.00
Labour 1240.00
6107.33
@ 20% 1221.46
4885.86

PARTS TOTAL : \$ 8,410.45
SPECIAL NETT TOTAL : \$ 100.00
LABOUR TOTAL : \$ 2,860.00
GRAND TOTAL : \$ 11,370.45

11960.44

4/5 - 4850/2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI19010340/Bsd3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			 Date : 26-08-2019 Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 3113R	Veh. Inspected	SDW 73X	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003261/AH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	10/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 523I	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAFP32050C864591	Colour	WHITE	
Odometer	69723	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	HANKOOK	6 mm	
L/H Front Tyre	225/55 R16	HANKOOK	6 mm	
R/H Rear Tyre	225/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	225/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/06/2019	Inspection Date	12/06/2019	
Survey held at	160 SIN MING DRIVE # 01-14			
Repairer	TEAM AUTOPRO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDW 73X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED	1,205.00	1,205.00
2	FRONT BUMPER RETAINER @\$65.00	NECESSARY	130.00	130.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	814.00	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	86.00	-
1	FRONT BUMPER NOZZLE COVER	BROKEN	63.00	63.00
1	FRONT BUMPER LOGO	NECESSARY	69.00	69.00
2	FRONT BUMPER SENSOR @\$383.00	MISSING / CUT / SHORTED	766.00	398.00
1	FRONT BUMPER FOG LAMP	BROKEN	219.00	219.00
1	FRONT BUMPER FOG LAMP GARNISH	BROKEN	116.20	116.20
1	HEADLAMP RH }	BROKEN	2,552.00	2,860.15
1	HEADLAMP BALLAST RH }		1,155.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	1,677.90	-
	LESS 5% DISCOUNT		-442.66	-253.02
			8,410.44	4,807.33
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	HEADLAMP SEAL (SN)	NOT NECESSARY	80.00	-
1	FRONT FENDER SEALANT (SN)	NECESSARY	100.00	30.00
			290.00	60.00
<u>LABOUR</u>				
	R&R DISTANCE SENSOR.		100.00	60.00
	R&R WIRE HARNESS TO FACILITATE REPAIR, RECONNECT AND CHECK FUNCTION.		100.00	50.00
	R&R FRONT FENDER SIGNAL LAMP.	NOT NECESSARY	80.00	-
	HEADLAMP ADJUSTMENT AND ALIGNMENT.	NOT NECESSARY	80.00	-
	PANEL BEAT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT FENDER RH.		1,200.00	600.00
	RUST PROOFING.		100.00	30.00
	SPRAY PAINTING.		1,200.00	500.00
			2,860.00	1,240.00

Report Ref No. CS/AGI19010340/Bsd3e2



GRAND TOTAL		11,560.44	6,107.33
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,850.00

Report Ref No. CS/AGI19010340/Bsd3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.