

ASS. REC. BY:

REF:

CS/INC19010346/Tied302

Special Instruction:

Surveyor: TaufikhyASSIGNMENT (Office)From (Person): Annie Koh of INC Date/Time: 11/6/2019

Estimated Cost: _____ Bill to: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBH 4813D Insured: YP4700G Fannyat Workshop m/s Jit Keong Tel: 96794211 / 6863 4186of 28 Bencoi PlacePolicy No: _____ Claim No: MT/1047537-000

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3/6/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN OUT

Date/Time	Action/Instruction () Estimate
	<u>GBH 4813D-X</u>
	<u>YP4700G-X.</u>

(08/11/13)

ASS. REC. BY:

Taypin

REF

INC

ASSIGNMENT

From:

Date:

12/6/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBH 4813D

at Workshop m/s

Jit Keong

of 28 Bendi Place

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Sunny

Veh No:

GBH 4813D

Yr Regn:

2018, June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

c.c

2982

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

24479

T/Radio:

Insured / Std / NI / NA

Eng/No:

KDY248028455

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/75 R15

R:

145 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

12/6/19 10:30am

Survey held at

Jit Keong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/10

4/5 \$2400, 3 days, e-mail to Sunny.
(\$ 1,766.70 Red - 42%)

RECEIVED 14 OCT 2019

14/10/2019

Date/Time, File Pass to?

14/10/19

1)

Type 4

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

Report Format:

Lump Sum / I.B.I. (\$ 2,400/- 4/5)

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 11 June 2019 1:48 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto); Daniel Koh
Cc: Thio Tse Kiat; Teng Ken Leong; Susan Ting
Subject: RE: TP CASES FARMED OUT TO LKK ON 11/06/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 11 June 2019 9:27 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; Daniel Koh <daniel.koh@income.com.sg>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; Susan Ting <susan.ting@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 11/06/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA
1	Cyndie Yong	MT/1047629-002	SIG7208S	CHENG AUTO BODYWORKS	5 SOON LEE STREET #01-62 PIONEER POINT	MURUGESAN / 8666 7775		SKZ3462M	3/6/19
2	Chryllis Quah	MT/1047537-002	GBH4813D	JIT KEONG TRADING & COMPANY	28 BENOI PLACE SINGAPORE 629945	Michael / Mr Sunny / Yeoh Evone / 6863 4186 / 96794211		YP4700G	3/6/19
3	Azhari	MT/1046992-002	SFD101A	PREMIUM AUTOMOBILES PTE LTD	281 ALEXANDRA ROAD SINGAPORE 159938	Tony Foong / 6366 2323	10:00-12:00	SKZ1360L	30/5/19
4	Jared Liu	MT/1024640-002	GBF3550D	SIN SHENG ENGINEERING SERVICES	8 TUAS AVENUE 18 LEVEL 5 SINGAPORE 638892	6863 9595 / Susan		SGW2051K	19/12/19
5	Muhammad Airwan	MT/1039863-002	XD4959C	SIN SHENG ENGINEERING SERVICES	8 # TUAS AVENUE 18 LEVEL 5	Susan / 6863 9595		SJY6065Z	10/4/19

					SINGAPORE 638892				
6	Azhari	MT/1040903- 002	SKH9086X	XINYA AUTO SERVICES PTE LTD	BLK 1002 #01- 75 BUKIT MERAH LANE 3 SINGAPORE 159719	/ 62703481		SKJ6290G	19/4/19
7	Serene Lim	MT/1045961- 002	XB9555L	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	/ 63161131		SKR8444A	24/5/19

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

GBH4813D

Taufikh (LKKAuto)

Mon 14/10/2019 10:31 AM

To: 'sunny' <sunny@jitkeong.com.sg>

Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Hi Sunny,

COR I/s\$2400, 3 days.

Thank you.

Regards
Taufikh
Lkk Auto

From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]

Sent: Thursday, 10 October 2019 3:15 PM

To: 'sunny'

Subject: GBH4813D

Hi Sunny,

Can forward the after repair photo for this lorry?

Thank you.

Regards
Taufikh
Lkk Auto



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 335M

Vehicle Details

Vehicle No.: GBH4813D

Vehicle to be Exported: No

Intended Deregistration Date: 14 Oct 2019

Vehicle Make: TOYOTA

Vehicle Model: DYNA 3.0 MANUAL

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 1KD2700562

Chassis No.: KDY2318028955

Maximum Power Output: -

Open Market Value: \$32,511.00

Original Registration Date: 19 Jun 2018

First Registration Date: 19 Jun 2018

Transfer Count: 1

Actual ARF Paid: \$1,626.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 18 Jun 2028

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$17,128.00

COE Rebate Amount: \$14,863.00

Total Rebate Amount: \$14,863.00

The information contained herein is correct as at 14 Oct 2019

OK

DATE 06th June 2019

TO : NTUC INCOME INS CO-OP LTD
75 BRAS BASAH ROAD
#05-00 NTUC INCOME CENTRE
SINGAPORE 189557

TEL : 6788 1777 FAX : 6338 1500

ATT : MOTOR CLAIM DEPT.

SUBJECT : ACCIDENT ON 03/06/2019 @ 18:50hrs at North Coast Avenue (North Coast Drive)
Involving Vehicle : GBH4813D & YP4700G

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

RE: ESTIMATE QUOTATION FOR VEHICLE NO.: GBH4813D

S/N	DESCRIPTION ON PARTS	QTY	UNIT PRICE \$	AMOUNT \$
1	CORNER PANEL R/H	1 PC	\$ 270.00	\$ 270.00
2	WING MIRROR	1 PC	\$ 285.00	\$ 285.00
3	DOOR ASM R/H	1 PC	\$ 1,280.00	\$ 1,280.00
4	DOOR SIGNAL LAMP R/H	1 PC	\$ 120.00	\$ 120.00
5	DOOR HINGES TOP	1 PC	\$ 72.00	\$ 72.00
6	DOOR HINGES LOW	1 PC	\$ 86.00	\$ 86.00
	LESS DISCOUNT 10%	1 LS	\$ (211.30)	\$ (211.30)
7	FRONT HEAD LAMP R/H	1 PC	\$ 685.00	\$ 685.00
8	LABOUR TO REMOVE, REPLACE DOOR GLASS, DOOR BOARD, DOOR LOCK WEATHER STRIP, DOOR GUIDE INNER / OUTER, WING MIRROR	1 PC	\$ 280.00	\$ 280.00
9	LTA SIDE MARK	1 PC	\$ 30.00	\$ 30.00
10	COMPANY LOGO	1 SET	\$ 220.00	\$ 220.00
11	WORKMANSHIP CHARGE REMOVE, DAMAGE PARTS, REPLACE TO THE SAME AND RE-ALIGN DOOR	1 PC	\$ 450.00	\$ 450.00
12	TOUCH-UP PAINT TO ALL AFFECTED PARTS	1 JOB	\$ 700.00	\$ 700.00
Sub Total :				\$ 4,166.70
GST 7%				\$ 291.67
Total				\$ 4,458.37

Note:

The above estimate does not include any hidden damage parts that is / are not visible at the time of inspection.
We will advise you accordingly.

Remark : Vehicle to be view at No. 28 Benoi Place, Singapore 629945

[Signature]
4/6/19

Tan Kah 97495749
"up"
12/6/19 01020
Lumpsum
Resurvey after repair.
sure lkkanto.com
03 days

Yours Faithfully,

JIT KEONG TRADING CO. PTE. LTD.

SUNNY YEOH (Hp: 9662 1626)

MICHAEL YEOH (Hp: 9679 4211)

cut
cur
bt
cut
ry 2640
25% 1980
cut
80
150 net
350
400
1010
1980
1010
2990
1/5 2400
3 days #



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19010346/T1sd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 15-10-2019



ATTN: CHRYLLIS QUAH

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 4700G	Veh. Inspected	GBH 4813D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1047537-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	11/06/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KDY2318028955	Colour	WHITE
Odometer	24979 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm
L/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	145 R13	BRIDGESTONE	6 mm
L/H Rear Tyre	145 R13	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/06/2019	Inspect Date / Time	12/06/2019 (10:30 AM)
Survey held at	JIT KEONG TRADING CO 28 BENOI PLACE SINGAPORE 629945 (WAREHOUSE)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 4813D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	CORNER PANEL R/H	CUT	270.00	270.00
1	WING MIRROR	CRACKED	285.00	285.00
1	DOOR ASM R/H	BENT	1,280.00	1,280.00
1	DOOR SIGNAL LAMP R/H	CUT	120.00	120.00
1	DOOR HINGES TOP	TO REPAIR SEE LABOUR	72.00	-
1	DOOR HINGES LOW	TO REPAIR SEE LABOUR	86.00	-
	LESS 10% DISCOUNT		-211.30	-
	LESS 25% DISCOUNT		-	-488.75
			1,901.70	1,466.25
1	FRONT HEAD LAMP R/H	CUT	685.00	685.00
	LESS 25% DISCOUNT		-	-171.25
			685.00	513.75
	<u>SPECIAL NETT ITEMS</u>			
1	SET COMPANY LOGO (SN)	NECESSARY	220.00	150.00
1	LTA SIDE MARK (SN)	NECESSARY	30.00	30.00
			250.00	180.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE, REPLACE DOOR GLASS, DOOR BOARD, DOOR LOCK WEATHER STRIP, DOOR GUIDE INNER/OUTER, WING MIRROR.		280.00	80.00
	WORKMANSHIP CHARGE REMOVE, DAMAGE PARTS, REPLACE TO THE SAME AND RE-ALIGN DOOR. INCLUSIVE OF THE REPAIR OF DOOR HINGES TOP AND DOOR HINGES LOW.		450.00	350.00
	TOUCH-UP PAINT TO ALL AFFECTED PARTS.		700.00	400.00
			1,430.00	830.00
	GRAND TOTAL		4,266.70	2,990.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,400.00
--	--	--	----------

Report Ref No. CS/INC19010346/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.