

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0733/2019/DY/TF
Date : 10-Jun-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ye Yansi Esther
Address : 62A Strathmore Ave
#04-46
Singapore 142062
Telephone : (HP) +65 98028476
Type of Claim : Own Damage Claim
Policy No. : 1800025878
Vehicle No : **SLX 529 Z**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Mar-18
Engine No : CHZ 654583
Chassis No. : WAUZZZ8V3J1046464
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 04-Jun-19
Place of Accident : Intersection of Marymount Lane-

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 0529 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 /	
2	To remove front fittings, dismantle and renew front bumper and damaged attachments. Renew bonnet, hinges, striker and locks. Re-align both front fender and bonnet. Re-organise front crash management components. Reinstall all parts removed. \$50	\$ 1,800.00 1100	
3	To respray front bumper, bonnet and both front fenders. \$00	\$ 2,800.00 2000	
4	To carry out diagnostic check	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$ 5,152.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 0529 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER X R	\$ 1,830.00	
2	FRONT BUMPER FIXING PARTS X	\$ 170.00	
3	FOAM FILLER PIECE X	\$ 172.00	
4	RIVET X	\$ 30.00	
5	FRONT REINFORCEMENT BAR X	\$ 660.00	
6	FRONT BUMPER GRILLE - CENTER X	\$ 146.00	
7	FRONT BUMPER COVER TRIM - LH / RH X	\$ 296.00	
8	FRONT BUMPER GUIDE SECTION - LH / RH X	\$ 70.00	
9	RADIATOR GRILLE / BR	\$ 1,301.00	
10	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 174.00	
11	BONNET / DD	\$ 2,898.00	
12	BONNET ATTACHMENT PARTS ?	\$ 149.00	
13	BONNET EDGE PROTECTION / hel	\$ 25.00	
14	BONNET CATCH - TOP ?	\$ 81.00	
15	BONNET STRIKER X	2 \$ 200.00	
16	BONNET SOUND ABSORBER X	\$ 201.00	
17	BOWDEN CABLE COVER X	\$ 9.00	
18	BOWDEN CABLE X	\$ 53.00	
19	BONNET LOCK X	2 TBC	
20	BONNET CATCH - BOTTOM X	\$ 58.00	
SUB - TOTAL SPARE PARTS CHARGES		\$ 8,523.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 0529 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	BONNET HINGE - LH / RH X	\$ 112.00	
22	FRONT AIR GUIDE - CENTER ?	\$ 53.00	
23	FRONT NO. PLATE / DD	S/N \$ 40.00	
24	SUNDRIES ?	\$ 400.00	
TOTAL SPARE PARTS CHARGES		: \$ 9,128.00	
TOTAL LABOUR CHARGES		: \$ 5,152.00	
GRAND TOTAL		: \$ 14,280.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

11/6/19, 10.15 am
Steve (LKK)

Surveyed Date

:

OD - Author

Authorised Date

:

Excess - ?

Excess Cost

:

Liability

:

6 days

Remarks

:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9825 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant