

ASS. REC. BY:

REF: CS/CTI 9010372/V9d3

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Cheng Boon Sen

of CTI

Date/Time: 12.6.19 10.44am

Estimated Cost:

Bill to:

OD: TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 321E

Insured: SLC 4447K

at Workshop m/s M/S Automobile

Tel: 97864483

of 1 Eki Bukit Mv 6 # 02-11

Policy No: DMP CSN 30 34828000

Claim No: SMI 9D 2025 05102

Sum Insured:

Excess:

Make of Veh:

D.O.A. 6.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12.6.19 11.30am

Person Contacted: Mr Lim

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
| | <u>SMG 321E -x</u> |
| | <u>SLC 4447K -x</u> |
| | |
| | |
| | |
| | |
| | |

ASSIGNMENT

From: Date: 12/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMG 322.E

at Workshop m/s Automobile Hub

of 1 Kaki Blk Aves # 02-11

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

75'

PAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

9

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

1 up 27A68046

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Prel. Report

1) 10/6/19

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

65A

Survey Fee:

Transportation:

\$ + RTS, \$

Photos

Others

TOTAL

220

RECEIVED 13 JUN 2019

17/6/19 4/5 # 6500 confirmed with AH Xiong. (Red 8/17979.05, 73.6)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 12 Jun 2019 | | 12 Jun 2019 10:44 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|------------------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | | | | | | | | | |
| Main Claimant: | OCEAN CONTINENTAL PTE LTD, Co. Reg. No.: 201435336C | | | | | | | | |
| Vehicle Reg. No.: | SMG322E | Date of Loss: | 06/06/2019 14:00 - :59 | | | | | | |
| Claim Type: | TP / SNM19D202505C02 | Policy/Cover Note No.: | DMPCSN30398218000 | | | | | | |
| Vehicle Reg. No. (Insured): | SLC4447K | Policy No. (Claimant): | DMPCSN3039821901 | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | Automobile Hub Enterprise () 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen] | | | | | | | | |
| Claimant's Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/06/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

500+ dealers competed to buy my car!

Sell ur Car for More Cash

Highest Price or Get \$100 Free

Get Paid Now, Handover Later

SELL YOUR CAR

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2015 Toyota Estima 2.4 Aeras Premium Moonroof.



Cheapest 2015, Low Mileage,
Grab Before Gone.
Direct Owner StarAd

PRIME MOTOR & LEASING

IOHONG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.








Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

bmw 320

Advanced Search Submit

| | Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|---|----------------------------|--------------|-----------|--------------|-------------|----------|------------|----------|-----------|
| Search Selection | bmw 320 | | Any | Any | 2013 | Any | Any | Any | Available |
|  | BMW 3 Series | 320i Sport | \$81,800 | \$14,360 /yr | 20-Aug-2013 | 1,997 cc | 68,000 km | Luxury | Available |
| Low Interest Rate, Immaculate Condition, Well Kept And Maintained By Single Owner With Low Mileage Clocked, Always Sheltered Park, Trade In And Loan Available,Special Interest Rate Promotion 1.98%, Hu... | | | | | | | | | |
| Lay Auto Pte Ltd | | | | | | | | | |
| Posted: 07-Jun-2019 Tags: 2013 BMW 320i, 2013 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW | | | | | | | | | |
|  | BMW 3 Series | 320i Luxury | \$108,800 | \$20,610 /yr | 30-Aug-2013 | 1,997 cc | 136,330 km | Luxury | Available |
| 1 Owner, Black With Tanned Leather Interior, Wider LCI Screen With GPS, Keyless Entry/Start, Bi-Xenon Auto Headlights, Regularly Maintain By Ex Owner, Asking Cheapest The The Market, Very Safe Buy Wit... | | | | | | | | | |
| Posted: 07-Jun-2019 Tags: 2013 BMW 320i, 2013 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW | | | | | | | | | |
|  | BMW 3 Series | 320i | \$69,800 | \$13,410 /yr | 28-Mar-2013 | 1,997 cc | 125,000 km | Luxury | Available |
| 1.98% Interest Rate! Cheapest In The Market, Easy High Loan Approval, PML Unit, Fully Agent Maintained, Well Taken Care By 1 Careful Owner, Last Servicing At PML Done Just Recently, Accident Free Cond... | | | | | | | | | |
| Heritage Auto Enterprise Pte Ltd | | | | | | | | | |
| Posted: 01-Jun-2019 Tags: 2013 BMW 320i, 2013 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW | | | | | | | | | |
|  | BMW 3 Series | 320i Sport | \$66,800 | \$13,680 /yr | 30-Jan-2013 | 1,997 cc | 126,366 km | Luxury | Available |
| Well Maintained With 1 Careful Owner Only! Excellent Driving Condition! STA Welcome! Flexible In-House Loan Scheme Available! By Appointment! Contact/SMS Our Appointed Sales Person Directly For Enquir... | | | | | | | | | |
| Posted: 30-May-2019 Tags: 2013 BMW 320i, 2013 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW | | | | | | | | | |
|  | H11/H16/H8 50W 4 LED White | | | | | | | | |
| Wide-range voltage(12V-24V), constant current control, anti-interference circuit design. | | | | | | | | | |
| Find out more! | | | | | | | | | |
|  | BMW 3 Series | 320i Sunroof | \$79,800 | \$15,810 /yr | 05-Apr-2013 | 1,997 cc | 115,000 km | Luxury | Available |
| No Car Dealers Or Agents Please. 100% Accident-Free. View To Believe. Rare BMW F30 With Original Sun Roof. WhatsApp/SMS To Arrange For Viewing. Viewing Strictly By Appointment Only. | | | | | | | | | |
| Posted: 26-May-2019 Tags: 2013 BMW 320i, 2013 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW | | | | | | | | | |
|  | BMW 3 Series | 320i | \$70,000 | \$14,470 /yr | 28-Feb-2013 | 1,997 cc | - | Luxury | Available |
| PML Unit With Service Records. Well Taken Care Of Car That Is Regularly Serviced. Wear And Tear Parts Replaced. Enquire With A Peace Of Mind - Price Is Slightly Negotiable. | | | | | | | | | |
| Posted: 18-May-2019 Tags: 2013 BMW 320i, 2013 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW | | | | | | | | | |

Compare

Save this search criteria, to get email alerts whenever a match is found.

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

| | |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 1542B |

Vehicle Details

| | |
|-------------------------------|-------------------------------------|
| Vehicle No.: | SMG322E |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 12 Jun 2019 |
| Vehicle Make: | B.M.W. |
| Vehicle Model: | 320i GT 5DR ABS HID DSC NAV M SPORT |
| Primary Colour: | Black |
| Manufacturing Year: | 2013 |
| Engine No.: | B3260593N20B20B |
| Chassis No.: | WBA3X12060D372461 |
| Maximum Power Output: | 135.0 kW (181 bhp) |
| Open Market Value: | \$44,913.00 |
| Original Registration Date: | 30 Sep 2013 |
| First Registration Date: | 30 Sep 2013 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$49,879.00 24939 |

Intended PARF Rebate Details

| | |
|-------------------------------|-------------|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 29 Sep 2023 |
| PARF Rebate Amount: | \$34,915.00 |

Intended COE Rebate Details

| | |
|-----------------------------|--------------------------|
| COE Expiry Date: | 29 Sep 2023 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 10 |
| QP Paid: | \$77,100.00 |
| COE Rebate Amount: | \$33,131.00 |
| Total Rebate Amount: | \$68,046.00 |

The information contained herein is correct as at 12 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------------|
| Date Of Report | 06/06/2019 15:56 |
| Date Of Accident | 06/06/2019 14:05 |
| Exact Location Of Accident | SOUTH BUONA VISTA ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SMG322E |
| Insured/Policyholder | |
| Name Of Registered Owner | MARK LEE VI LOONG |
| NRIC No | S7211542B |
| Email Address | VILOONG@YAHOO.COM |
| Mobile Phone No | (LOCAL) +65-96815280 |
| Alternative Phone No | OTHERS-96815280 |

Vehicle Particulars

| | |
|--|---------------------------|
| Manufacturer | BMW |
| Model | 320I-2.0 GRAN TURISMO (A) |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5104741607 |
| Cover Note Number | DRIVO CLASSIC |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | MARK LEE VI LOONG |
| NRIC No | S7211542B |
| Date Of Birth | 02/04/1972 |
| Occupation | INDOOR |
| Date Of Driving Pass | 15/12/1997 |
| Driving Experience | 21 YEARS AND 5 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96815280 |
| Fax Number | |
| Contact Number | OTHERS-96815280 |
| Email Address | VILOONG@YAHOO.COM |

| | |
|---|---------------------------|
| Address | 466 UPPER EAST COAST ROAD |
| Postcode | 466512 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

I WAS WAITING TO TURN RIGHT DUE TO HEAVY TRAFFIC WHEN VEHICLE B CAME AND HIT INTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|----------------|
| Vehicle Registration Number | SLC4447K |
| Vehicle Make/Model/Colour | TOYOTA SILVER |
| Details Of Properties | FRONT PORTION |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | KHOO CHEE MENG |
| NRIC/Passport Number | S7688478A |
| Contact Number | 96746839 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | 1 |

Sketch Plan Pg. 2

SKETCH PLAN

SOUTH BUONA VISTA ROAD

Vehicle A: SMG322E Vehicle B: SLC4447K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS WAITING TO TURN RIGHT DUE TO HEAVY TRAFFIC WHEN VEHICLE B CAME AND HIT INTO THE REAR PORTION OF MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


6/6/2019 16:01
Policyholder's Signature
Date & Time:

6/6/2019 16:01
Driver's Signature (if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: 3292753

Repair Estimate

Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Make/Model: BMW 320i GT
Engine/Chassis No.: WBA3X12060D372461
Date of accident:
Damaged area: O/S Rear

Date: 07/06/2019
Claim Type: TP
VRN: SMG322E



Not Authorized
1/5 6500
5.00%
12/6/19
Take to the repair

| List items | | | | |
|---------------|-------------------------------------|-----|-------------|--------------|
| S/N | Parts description | QTY | UNIT PRICE | AMOUNT |
| 1 | Tailgate | 1 | \$ 2,325.00 | \$ 2,325.00 |
| 2 | Tailgate lock | 1 | \$ 411.00 | \$ 411.00 |
| 3 | Tailgate lock striker | 1 | \$ 93.00 | \$ 93.00 |
| 4 | Tailgate weatherstrip | 1 | \$ 275.00 | \$ 275.00 |
| 5 | Tailgate inner trim board | 1 | \$ 498.00 | \$ 498.00 |
| 6 | Tailgate "BMW" emblem | 1 | \$ 95.00 | \$ 95.00 |
| 7 | Tailgate "320i" emblem | 1 | \$ 75.00 | \$ 75.00 |
| 8 | Tailgate "GT" emblem | 1 | \$ 67.00 | \$ 67.00 |
| 9 | Tailgate lamp o/s | 1 | \$ 790.00 | \$ 790.00 |
| 10 | Rear bumper upper | 1 | \$ 2,306.00 | \$ 2,306.00 |
| 11 | Rear bumper lower | 1 | \$ 850.00 | \$ 850.00 |
| 12 | Rear bumper tow hook cover | 1 | \$ 49.00 | \$ 49.00 |
| 13 | Rear bumper reflector o/s | 1 | \$ 167.00 | \$ 167.00 |
| 14 | Rear bumper lower cowl | 1 | \$ 335.00 | \$ 335.00 |
| 15 | Rear bumper side retainer | 2 | \$ 178.00 | \$ 356.00 |
| 16 | Rear bumper reinforcement | 1 | \$ 688.00 | \$ 688.00 |
| 17 | Rear bumper inner top support beam | 1 | \$ 632.00 | \$ 632.00 |
| 18 | Rear bumper inner side support beam | 1 | \$ 465.00 | \$ 465.00 |
| 19 | Rear bumper inner beam lock clasp | 1 | \$ 61.00 | \$ 61.00 |
| 20 | Tail lamp o/s | 1 | \$ 1,388.00 | \$ 1,388.00 |
| 21 | Tail lamp inner seal o/s | 1 | \$ 31.00 | \$ 31.00 |
| 22 | End panel | 1 | \$ 917.00 | \$ 917.00 |
| 23 | End panel top garnish | 1 | \$ 295.00 | \$ 295.00 |
| 24 | Rear fender o/s | 1 | \$ 1,921.00 | \$ 1,921.00 |
| 25 | Rear fender inner cowl o/s | 1 | \$ 508.00 | \$ 508.00 |
| 26 | Rear side air vent o/s | 1 | \$ 97.00 | \$ 97.00 |
| 27 | Rear bumper reinforcement bracket | 2 | \$ 107.00 | \$ 214.00 |
| 28 | Tailgate windscreen moulding | 1 | \$ 346.00 | \$ 346.00 |
| Subtotal | | | | \$ 16,255.00 |
| List discount | | | | 5.00% |
| Total | | | | \$ 15,442.25 |

6208.82
5%
5898.37

Repair Estimate

| Special nett items | | | | | |
|--------------------|---|-----|-------------|--------|----------|
| No. | Parts description | QTY | UNIT PRICE | AMOUNT | |
| 1 | Rear bumper sensor 313 shw | 4 | \$ 674.00 | \$ | 2,696.00 |
| 2 | Rear bumper sensor holder 2.0 nu | 4 | \$ 124.00 | \$ | 496.00 |
| 3 | Rear bumper sensor wire harness 17 | 1 | \$ 1,475.00 | \$ | 1,475.00 |
| 4 | Tailgate inner trim board clips 17 | 12 | \$ 7.50 | \$ | 90.00 |
| 5 | Rear bumper clips nu | 10 | \$ 7.50 | \$ | 75.00 |
| 6 | Rear bumper lower cowlings clips nu | 8 | \$ 7.50 | \$ | 60.00 |
| 7 | End panel sealant nu | 1 | \$ 120.00 | \$ | 120.00 |
| 8 | End panel top garnish clips 17 | 6 | \$ 7.50 | \$ | 45.00 |
| 9 | Rear fender inner cowlings o/s clips 17 | 8 | \$ 7.50 | \$ | 60.00 |
| 10 | Tailgate windscreen sealant 17 | 1 | \$ 120.00 | \$ | 120.00 |
| 11 | Sundries 17 | 1 | \$ 50.00 | \$ | 50.00 |
| Total | | | | \$ | 5,287.00 |

17C
17C
X
50
50
50
X
X
X
X

| Labour | | | |
|--------------|---|-----------|--------------|
| No. | Description | Work unit | Amount |
| 1 | To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts. | 8 | \$ 1,600.00 |
| 2 | To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings. | 0.25 | \$ 50.00 |
| 3 | To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage. | 0.5 | \$ 11 100.00 |
| 4 | To remove and refit o/s rear fender glass to facilitate repair work. | 0.75 | \$ 11 150.00 |
| 5 | To remove and refit rear windscreen to facilitate repair work. | 0.75 | \$ 17 150.00 |
| 6 | Supply spray paint material and necessary items to respray tailgate, rear bumper, end panel, o/s rear fender and other affected area / panel. | 8 | \$ 1,600.00 |
| 7 | To rust proof all affected portions after repair. | 0.5 | \$ 100.00 |
| Total labour | | | \$ 3,750.00 |

800
20
X
X
X
900
50

| | |
|----------------------|--------------|
| Estimate Grand Total | \$ 24,479.25 |
|----------------------|--------------|

Insurance Company
Policy No. 123456789
Insured Name: John Doe
Address: 123 Main Street, Singapore
Phone: 9123 4567
Email: john.doe@example.com
Vehicle: 2018 Toyota Camry
Engine No. 1234567890
Chassis No. 9876543210
Insured by: John Doe
Insured for: 12 months
Insured from: 01/01/2023
Insured to: 31/12/2023
Insured by: John Doe
Insured for: 12 months
Insured from: 01/01/2023
Insured to: 31/12/2023

P - 5896.37
S.N - 483.00
17C - 1770
8151.37
6521.10

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010372/UQD3N2
Date: 20/06/2019

REFERENCE

| | | | | | |
|-----------------------|---|----------------------|-------------------|-----------|-----------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMPCSN30398218000 | | |
| Claimant Vehicle No : | SMG322E | Insured Vehicle No : | SLC4447K | | |
| Date of Loss: | 06/06/2019 | Nature of Claim: | TP | Claim No: | SNM19D202505C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | | |
|-----------------------------|------------------------------|--|-------------|-------------------|
| Reg No: | SMG322E | | Engine No: | B3260593N20B20B |
| Make & Model: | BMW 320I, 2.0 (A) | | Chassis No: | WBA3X12060D372461 |
| Reg. Date: | 30/09/2013 (Man. Year: 2013) | | Odometer: | 48830 km |
| Colour: | Black | | | |
| Engine Capacity: | 1997 cc | | | |
| Market Value/New Car Price: | N/A | | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 255/45 R18 | Rear Tyre Size: | 255/45 R18 |
| Front Left Side: | Pirelli 6 mm | Rear Left Side: | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|-----------------|------------------|--------------|
| Parts | 20,729.25 | 6,381.38 | 14,347.87 | 69.22 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,750.00 | 1,770.00 | 1,980.00 | 52.80 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 24,479.25 | 8,151.38 | 16,327.87 | 66.70 |
| Approved Total (Overridden) (\$\$) | | 6,500.00 | | |
| Nett Amount (\$\$) | 24,479.25 | 6,500.00 | 17,979.25 | 73.45 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 12/06/2019 | |
| Date Inspected: | 12/06/2019 Inspected At: | Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|--|
| Reference | | |
| Part Source: | (Last Synchronised: 20 Jun 2019) | |
| Parts: | N/A | BMW 320i 2.0 (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMG322E) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Repair | 2,325.00 FL | *- FL |
| 2 | 1 | | *TAILGATE LOCK | Not Necessary | 411.00 FL | *- FL |
| 3 | 1 | | *TAILGATE LOCK STRIKER | Not Necessary | 93.00 FL | *- FL |
| 4 | 1 | | *TAILGATE WEATHERSTRIP | Not Necessary | 275.00 FL | *- FL |
| 5 | 1 | | *TAILGATE INNER TRIM BOARD | Not Necessary | 498.00 FL | *- FL |
| 6 | 1 | | *TAILGATE BMW EMBLEM | Not Necessary | 95.00 FL | *- FL |
| 7 | 1 | | *TAILGATE 320i EMBLEM | Necessary | 75.00 FL | *75.00 FL |
| 8 | 1 | | *TAILGATE GT EMBLEM | Necessary | 67.00 FL | *67.00 FL |
| 9 | 1 | | *TAILGATE LAMP O/S | Not Necessary | 790.00 FL | *- FL |
| 10 | 1 | | *REAR BUMPER UPPER | Distorted | 2,306.00 FL | *1,615.32 FL |
| 11 | 1 | | *REAR BUMPER LOWER | Distorted | 850.00 FL | *850.00 FL |
| 12 | 1 | | *REAR BUMPER TOW HOOK COVER | Not Necessary | 49.00 FL | *- FL |
| 13 | 1 | | *REAR BUMPER REFLECTOR O/S | Cracked | 167.00 FL | *65.00 FL |
| 14 | 1 | | *REAR BUMPER LOWER COWLING | No Such Parts | 335.00 FL | *- FL |
| 15 | 1 | | *REAR BUMPER SIDE RETAINER | O/s Cracked | 358.00 FL | *178.00 FL |
| 16 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 688.00 FL | *688.00 FL |
| 17 | 1 | | *REAR BUMPER INNER TOP SUPPORT BEAM | Cracked | 632.00 FL | *245.00 FL |
| 18 | 1 | | *REAR BUMPER INNER SIDE SUPPORT BEAM | Cracked | 465.00 FL | *366.00 FL |
| 19 | 1 | | *REAR BUMPER INNER BEAM LOCK CLASP | Not Necessary | 61.00 FL | *- FL |
| 20 | 1 | | *TAILLAMP O/S | Cracked | 1,388.00 FL | *1,045.50 FL |
| 21 | 1 | | *TAILLAMP INNER SEAL O/S | Not Necessary | 31.00 FL | *- FL |
| 22 | 1 | | *END PANEL | Dented / Bent | 917.00 FL | *917.00 FL |
| 23 | 1 | | *END PANEL TOP GARNISH | Not Necessary | 295.00 FL | *- FL |
| 24 | 1 | | *REAR FENDER O/S | Repair | 1,921.00 FL | *- FL |
| 25 | 1 | | *REAR FENDER INNER COWLING O/S | Not Necessary | 508.00 FL | *- FL |
| 26 | 1 | | *REAR SIDE AIR VENT O/S | Twisted | 97.00 FL | *97.00 FL |
| 27 | 2 | | *REAR BUMPER REINFORCEMENT BRACKET | Not Necessary | 214.00 FL | *- FL |
| 28 | 1 | | *TAILGATE WINDSCREEN MOULDING | Not Necessary | 346.00 FL | *- FL |
| 29 | 4 | | *REAR BUMPER SENSOR | Shorted | 2,696.00 FS | *313.00 FS |
| 30 | 4 | | *REAR BUMPER SENSOR HOLDER | Necessary | 496.00 FS | *20.00 FS |
| 31 | 1 | | *REAR BUMPER SENSOR WIRE HARNESS | Not Necessary | 1,475.00 FS | *- FS |
| 32 | 12 | | *TAILGATE INNER TRIM BOARD CLIPS | Not Necessary | 90.00 FS | *- FS |
| 33 | 10 | | *REAR BUMPER CLIPS | Necessary | 75.00 FS | *50.00 FS |
| 34 | 8 | | *REAR BUMPER LOWER COWLING CLIPS | Necessary | 60.00 FS | *50.00 FS |
| 35 | 1 | | *END PANEL SEALANT | Necessary | 120.00 FS | *50.00 FS |
| 36 | 6 | | *END PANEL TOP GARNISH CLIPS | Not Necessary | 45.00 FS | *- FS |
| 37 | 8 | | *REAR FENDER INNER COWLING O/S CLIPS | Not Necessary | 60.00 FS | *- FS |
| 38 | 1 | | *TAILGATE WINDSCREEN SEALANT | Not Necessary | 120.00 FS | *- FS |
| 39 | 1 | | *SUNDRIES | Not Necessary | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 21,542.00 | 6,691.82 |
| - List Item Discount on L Items 5.00/5.00% (\$\$) | 812.75 | 310.44 |
| Total Parts (\$\$) | 20,729.25 | 6,381.38 |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|-------------|-----------|------------|--------|
| Report was unsubmitted during this print-out. | | | | | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. | New | 1,600.00 | 800.00 |
| 2 | TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS. | New | 50.00 | 20.00 |
| 3 | TO REMOVE, REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE, CHECK AND RE-ADJUST CLOSE GAP, ALIGNMENT AND WATER SEEPAGE. | New | 100.00 | 0.00 |
| 4 | TO REMOVE AND REFIT O/S REAR FENDER GLASS TO FACILITATE REPAIR WORK. | New | 150.00 | 0.00 |
| 5 | TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK. | New | 150.00 | 0.00 |
| 6 | SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY TAILGATE, REAR BUMPER, END PANEL, O/S REAR FENDER AND OTHER AFFECTED AREA / PANEL. | New | 1,600.00 | 900.00 |
| 7 | TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR. | New | 100.00 | 50.00 |
| Gross Labour Cost (S\$) | | | 3,750.00 | 1,770.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >