

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 367B**AAD1906-063***Not Notified*
1/1/19

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 367B

VF1ABL15AUC282736

RENAULT

LATITUDE

6.6.19

AIG

17/5/2016

		PART		LIST
1	1	BUMPER COVER REAR	\$	1,108.46
2	1	BUMPER LOWER REAR	\$	768.84
3	1	BUMPER BRACKET CTR REAR	\$	113.47
4	1	BUMPER BRACKET SIDE RH REAR	\$	135.97
5	1	BUMPER RETAINER RH REAR	\$	44.99
6	1	BUMPER REFLECTOR RH	\$	43.61
7	1	BUMPER BRACKET SIDE LH REAR	\$	135.97
8	1	BUMPER RETAINER LH REAR	\$	44.99
9	1	BUMPER REFLECTOR LH	\$	43.61
10	1	BUMPER BEAM REAR	\$	777.52
11	1	BUMPER BEAM BRACKET LH REAR	\$	225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$	225.95
13	1	OUTER PANEL REAR (End Panel)	\$	1,471.77
14	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56
15	1	TAILLAMP RH	\$	552.55
16	1	TAILLAMP PANEL RH	\$	986.70
17	1	TAILLAMP LH	\$	552.55
18	1	TAILLAMP PANEL LH	\$	986.70
19	1	BOOT REAR	\$	2,872.68
20	1	BOOT FINISHER	\$	470.06
21	1	BOOT WHEATERSTRIP	\$	323.05
22	1	BOOT REFLECTOR LAMP LH	\$	493.35
23	1	BOOT REFLECTOR LAMP RH	\$	493.35
24	1	BOOT BADGE 'RENAULT'	\$	225.36
25	1	BOOT BADGE	\$	225.36
26	1	BOOT STRUT LH	\$	276.08
27	1	BOOT STRUT RH	\$	276.08
28	1	BOOT HINGE LH	\$	367.84
29	1	BOOT HINGE RH	\$	367.84
30	1	BOOT INNER TRIM	\$	586.45

Xerox

Trans-cab Auto Services Pte Ltd**AAD1906-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 367B

31	1	BOOT SWITCH	\$	168.13	} X
32	1	BOOT LOCK	\$	202.67	
33	1	BOOT LOCK CATCH	\$	74.40	
34	1	EXHAUST REAR	\$	7,489.05	
35	1	EXHAUST CAP REAR	\$	230.49	
TOTAL			\$	23,766.42	
10%			\$	2,376.64	
			\$	21,389.78	

Special Nett

1	1SET	PARKING AID	\$	700.00	} X
2	1SET	REAR BUMPER CLIP	\$	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	
10	1	BOOT STICKER "Trans-cab"	\$	30.00	
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	1	EXHAUST MOUNTING REAR	\$	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	80.00	
14	1	WINDSCREEN MOULDING	\$	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
16	1	BOOT INNER TRIM CLIP	\$	45.00	
17	1SET	BOOT FINISHER CLIP	\$	24.20	
18	1	TAILLAMP CLIP LH	\$	5.00	
19	1	TAILLAMP CLIP RH	\$	5.00	
TOTAL			\$	1,384.02	

TOTAL PARTS \$ 22,773.80**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1906-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 367B

To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	X
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	2201
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00	X
TOTAL	\$	11,510.00	

Over All Total \$ 34,283.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resume before after work
- To follow repaired part
- Particulars subject
- Transparency on "fair price" basis
- No additional cost
- Sub work
- is subject to approval from LKK Auto Consultants and Company

Authorized Repairer

15 DAYS
1 day