

Trans-cab Auto Services Pte Ltd

AAD1906-089

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

Not Authorized
1/1/15 B

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC 5935J
VF1ABL15AUC281660
RENAULT
LATITUDE
10.6.19
III
26/6/2015

		PART		LIST	
1	DOOR PANEL REAR LH		\$	<i>Rn</i> 2,844.66	✓
1	DOOR GUIDE REAR LH		\$	<i>Sn</i> 176.82	}
1	DOOR HINGE UPPER LH		\$	<i>N</i> 274.50	
1	DOOR HINGE LOWER LH		\$	<i>N</i> 300.55	
1	DOOR CHECK REAR LH/RH L70Y		\$	<i>Sn</i> 203.06	
1	DOOR LOCK REAR LH		\$	<i>N</i> 908.75	
1	DOOR HANDLE OUTER REAR LH		\$	<i>Sn</i> 126.49	
1	DOOR HANDLE CAP REAR LH		\$	<i>Sn</i> 35.52	
1	DOOR HANDLE SEAL REAR LH		\$	<i>Sn</i> 7.89	
1	DOOR HANDLE COVER REAR LH		\$	<i>Sn</i> 13.22	
1	DOOR HANDLE MODULE REAR LH		\$	<i>Sn</i> 133.60	
1	DOOR REGULATOR REAR LH		\$	1,135.10	?
1	DOOR REGULATOR MOTOR REAR LH		\$	893.75	?
1	DOOR REGULATOR NUT REAR L70Y		\$	<i>Sn</i> 12.43	}
1	DOOR REGULATOR MOTOR SCREW REAR L70Y		\$	<i>Sn</i> 6.31	
1	DOOR FINISHER REAR LH		\$	<i>Sn</i> 423.10	
1	DOOR MOULDING REAR LH		\$	<i>Sn</i> 176.82	
1	DOOR MOULDING CLIP L70Y		\$	<i>N</i> 5.92	
1	DOOR MOULDING SCREW L70Y		\$	<i>Sn</i> 6.91	
1	DOOR CASING REAR LH		\$	<i>Sn</i> 1,509.06	
1	DOOR WATER SHIELD REAR LH		\$	<i>Sn</i> 30.39	
1	DOOR CASING CLIP		\$	<i>N</i> 12.63	
1	DOOR CASING LIGHT L70Y		\$	<i>N</i> 48.74	
1	DOOR FINISHER INNER REAR LH		\$	<i>Sn</i> 323.44	}
1	DOOR FINISHER BRACKET INNER REAR LH		\$	<i>N</i> 46.97	
1	DOOR FINISHER BRACKET INNER REAR LH		\$	<i>N</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH		\$	<i>N</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH		\$	<i>N</i> 20.33	
1	DOOR GRAB HANDLE REAR LH		\$	<i>Sn</i> 210.96	
1	DOOR BLIND REAR LH		\$	<i>Sn</i> 741.80	

Trans-cab Auto Services Pte Ltd

AAD1906-089

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

1	DOOR WHEATHESTRIIP REAR LH	\$	S 410.66	X	
1	DOOR SEAL REAR LH	\$	S 162.02	X	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	S 229.31	X	
1	DOOR WAIST SEAL OUTER REAR LH	\$	S 334.69	X	
1	DOOR WAIST SEAL INNER REAR LH	\$	S 115.64	X	
1	DOOR PANEL FRT LH	\$	B 2,844.66		
1	DOOR HINGE UPPER LH	\$	N 261.28	} X	
1	DOOR HINGE LOWER LH	\$	N 300.55		
1	DOOR CHECK FRT LH	\$	S 194.77		
1	DOOR LOCK FRT LH	\$	N 908.75		
1	DOOR CATCH FRT LH	\$	N 131.23		
1	DOOR HANDLE OUTER FRT LH	\$	S 477.76		
1	DOOR HANDLE COVER FRT LH	\$	S 13.22		
1	DOOR HANDLE MODULE FRT LH	\$	S 133.60		
1	DOOR REGULATOR FRT LH	\$	505.19		?
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46		?
1	DOOR REGULATOR GUIDE FRT LH	\$	S 120.97	} X	
1	DOOR MOULDING FRONT LH	\$	S 176.82		
1	DOOR FINISHER INNER FRONT LH	\$	S 323.44		
1	DOOR FINISHER FRONT LH	\$	S 423.10		
1	DOOR CASING FRONT LH	\$	S 1,509.06		
1	DOOR GRAB HANDLE FRONT LH	\$	S 210.96		
1	DOOR BLIND FRONT LH	\$	S 741.80		
1	DOOR WHEATHESTRIIP FRONT LH	\$	S 410.66		
1	DOOR SEAL FRONT LH	\$	S 162.02		
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	S 229.31		
1	DOOR WAIST SEAL OUTER FRONT LH	\$	S 334.69	} X	
1	DOOR WAIST SEAL INNER FRONT LH	\$	S 115.64		
1	ROCKER PANEL INNER GARNISH LH	\$	S 466.51		
1	ROCKER PANEL INNER LH	\$	N 1,024.79		
1	ROCKER PANEL OUTER LH	\$	N 1,184.99		
1	ROCKER PANEL CENTER LH	\$	B 990.25		
1	DOOR MIRROR ASSY LH	\$	S 1,483.40		
1	DOOR MIRROR GLASS LH	\$	S 148.20		
1	DOOR MIRROR BACK COVER LH	\$	S 218.46		
1	DOOR HARNESS WIRE LH	\$	S 2,670.00		
1	FENDER PANEL REAR LH	\$	N 3,299.13	} X	
1	FENDER PANEL INNER TRIM REAR LH	\$	S 671.45		

Trans-cab Auto Services Pte Ltd

AAD1906-089

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

1	WHEELARCH REAR LH	\$	<i>Sn</i>	543.47	X
1	TAILLAMP LH	\$	<i>Sn</i>	552.55	X
1	TAILLAMP PANEL LH	\$	<i>n</i>	986.70	X
1	BUMPER COVER REAR	\$	<i>Bu</i>	1,108.46	✓
1	BUMPER LOWER REAR	\$	<i>Sn</i>	768.84	} X
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i>	113.47	
1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i>	135.97	
1	BUMPER RETAINER LH REAR	\$	<i>Sn</i>	44.99	
1	BUMPER REFLECTOR LH	\$	<i>Sn</i>	43.61	
1	BUMPER BEAM REAR	\$	<i>n</i>	777.52	
1	BUMPER BEAM BRACKET LH REAR	\$	<i>n</i>	225.95	
TOTAL		\$		40,707.35	
10%		\$		4,070.73	
		\$		36,636.61	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>nn</i>	100.00	<i>basn</i>
1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>nn</i>	80.00	<i>basn</i>
1	FRONT DOOR STICKER 'Classic'	\$	<i>nn</i>	80.00	X
1	DOOR CHECK BOLT	\$	<i>Sn</i>	22.69	} X
1	DOOR GUIDE SCREW	\$	<i>Sn</i>	10.85	
1	DOOR HINGE BOLT	\$	<i>Sn</i>	10.85	
1	DOOR HINGE NUT LH	\$	<i>Sn</i>	14.60	
1	DOOR CHECK BOLT	\$	<i>Sn</i>	22.69	
1	DOOR CHECK NUT	\$	<i>Sn</i>	3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>Sn</i>	6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>Sn</i>	10.06	
1	REAR LEFT TYRE	\$	<i>Sn</i>	300.00	
1	REAR LEFT TYRE RIM	\$	<i>Sn</i>	380.00	
1	FRONT LEFT TYRE	\$	<i>Sn</i>	300.00	
1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i>	30.50	
1	FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00	
1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00	
1	FRONT LEFT TYRE RIM	\$	<i>Sn</i>	380.00	
2	REAR WINDSCREEN SEALANT	\$	<i>nn</i>	80.00	
1	REAR WINDSCREEN MOULDING	\$	<i>nn</i>	120.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	
1	TAILLAMP CLIP LH	\$	<i>nn</i>	5.00	

Trans-cab Auto Services Pte Ltd

AAD1906-089

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

1SET	PARKING AID	\$	<i>pn</i> 700.00 X
1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 ✓
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 X
TOTAL		\$	3,037.13
TOTAL PARTS		\$	39,673.74

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00 <i>8001</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
Putty and spray painting of the affected portion.	\$	7,500.00 <i>11001</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 <i>601</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1906-089

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00	<i>601</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To rust-proofing of the affected areas.	\$	170.00	<i>901</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of Rear Bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
TOTAL	\$	18,730.00	
Over All Total	\$	58,403.74	

LUMP SUM (REPAIR DAY)***25* DAYS***6 days*

<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--