

SERVICE ESTIMATE

98775 - C00001 SL: SERVICE SALES - PC

Mr Quek Kok Leong Joseph
6 Pasir Ris Link
#01-20

Singapore 518161

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Quek Kok Leong Jo

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1
Inv.date. : 28/05/2019
WIP No. . : 16730
Veh.In/Out:
*Tel.No. . : Mobile: 91711097
Reg.No. . : SMM9918X
Reg.date . : 11/10/2018
Mileage .. : 0
Chassis No: YV1FS40LDJ2462992

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SENSOR, ETC	0	2400.00	0		2,400.00 S	800
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR LOWER SPOILER, ETC	0	2100.00	0		2,100.00 S	1400
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	480.00	0		480.00 S	
	BUMPER COVER REAR S6	1.0 EA	1428.70			1,428.70 S	
	TOW COVER REAR S60 1	1.0 EA	73.90			73.90 S	
	BUMPER SPOILER REAR	1.0 EA	486.40			486.40 S	
	PROTECTING PLATE REAR	1.0 EA	178.10			178.10 S	
	BUMPER BRACKET CTR R	1.0 EA	88.70			88.70 S	
	BUMPER BRACKET LHR S	1.0 EA	54.30			54.30 S	
	BUMPER BRACKET RHR S	1.0 EA	54.30			54.30 S	
	BUMPER BRACKET LHR S	1.0 EA	54.30			54.30 S	
	BUMPER BRACKET RHR S	1.0 EA	54.30			54.30 S	

SERVICE ESTIMATE

98775 - C00001 SL: SERVICE SALES - PC

Mr Quek Kok Leong Joseph
6 Pasir Ris Link
#01-20

Singapore 518161

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Quek Kok Leong Jo

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 28/05/2019
WIP No. . : 16730
Veh.In/Out:
*Tel.No. . : Mobile: 91711097
Reg.No. . : SMM9918X
Reg.date. : 11/10/2018
Mileage . : 0
Chassis No: YV1FS40LDJ2462992

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER RAIL (BEAM) R ?	1.0 EA	1277.20			1,277.20	S
	BLIND RIVET 4.0*21 P X	10.0 EA	3.00			30.00	S
	BUMPER CLIP 8x8,5 X	10.0 EA	5.40			54.00	S
	BUMPER INSTALLING MT X	1.0 EA	83.40			83.40	S
	ADHESIVE TUBE CHEMIC X	2.0 EA	151.60			303.20	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Pasul
Hp 90010068
3 days
17/07/19 @ 1120
Resy before paint

		Gross Total.	9,200.80
Labour Total	4,980.00	Net.....	9,200.80
Parts Total	4,220.80	GST @ 7.0%	644.06
Package Total	0.00	Total.....	9,844.85
		Paid.....	0.00
		Please Pay..	9,844.85

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated