

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

08/06/2019

Owner: ONG ZHI JIAN

ESTIMATE TO REPAIR HONDA CIVIC 1.8 - SLC785K

1pc	front bumper
10pcs	front bumper clip @\$5.00
1pc	front bumpe RH side retainer
1pc	front bumper RH fog lamp
1pc	front bumper RH fog lamp side garnish
1pc	front RH headlamp
1pc	front RH headlamp lower beam

less 20%

myjms	\$	638.00	✓
na	\$	50.00	✓
sn	\$	48.50	X
.	\$	355.50	?
sn	\$	58.50	X
	\$	903.20	?
	\$	32.50	X
		\$	2,086.20
		\$	417.24
		\$	1,668.96

wiring
spray painting
labour charges
Total

\$	60.00	10d
\$	600.00	200d
\$	600.00	200d
\$	2,928.96	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: