

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 40T

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

PART

- | | | |
|----|---|---------------------------------|
| 1 | 1 | BUMPER COVER REAR |
| 2 | 1 | BUMPER LOWER REAR |
| 3 | 1 | BUMPER BRACKET CTR REAR |
| 4 | 1 | BUMPER BRACKET SIDE RH REAR |
| 5 | 1 | BUMPER RETAINER RH REAR |
| 6 | 1 | BUMPER REFLECTOR RH |
| 7 | 1 | BUMPER BRACKET SIDE LH REAR |
| 8 | 1 | BUMPER RETAINER LH REAR |
| 9 | 1 | BUMPER REFLECTOR LH |
| 10 | 1 | BUMPER BEAM REAR |
| 11 | 1 | BUMPER BEAM BRACKET LH REAR |
| 12 | 1 | BUMPER BEAM BRACKET RH REAR |
| 13 | 1 | BOOT REAR |
| 14 | 1 | BOOT FINISHER |
| 15 | 1 | BOOT WHEATERSTRIP |
| 16 | 1 | BOOT REFLECTOR LAMP LH |
| 17 | 1 | BOOT REFLECTOR LAMP RH |
| 18 | 1 | BOOT BADGE 'RENAULT' |
| 19 | 1 | BOOT BADGE |
| 20 | 1 | BOOT STRUT LH |
| 21 | 1 | BOOT STRUT RH |
| 22 | 1 | BOOT HINGE LH |
| 23 | 1 | BOOT HINGE RH |
| 24 | 1 | BOOT INNER TRIM |
| 25 | 1 | BOOT SWITCH |
| 26 | 1 | BOOT LOCK |
| 27 | 1 | BOOT LOCK CATCH |
| 28 | 2 | LICENCE PLATE LAMP |
| 29 | 2 | BOOT RUBBER PLUG |
| 30 | 1 | FENDER PANEL INNER TRIM REAR LH |

AAD1906-071

Not Authored
C/Sing &

SHD 40T

VF1ABL15AUC281533

RENAULT

LATITUDE

8.6.19

AIG

23/3/2015

LIST

\$	<i>By</i>	1,108.46	✓
\$	<i>By</i>	768.84	✓
\$	<i>By</i>	113.47	X
\$	<i>By</i>	135.97	X
\$	<i>By</i>	44.99	X
\$	<i>By</i>	43.61	X
\$	<i>By</i>	135.97	X
\$	<i>By</i>	44.99	X
\$	<i>By</i>	43.61	X
\$	<i>By</i>	777.52	✓
\$		225.95	?
\$		225.95	?
\$	<i>By</i>	2,872.68	✓
\$	<i>By</i>	470.06	X
\$	<i>By</i>	323.05	<i>50% by</i>
\$	<i>By</i>	493.35	X
\$	<i>By</i>	493.35	X
\$	<i>By</i>	225.36	—
\$	<i>By</i>	225.36	—
\$	<i>By</i>	276.08	} X
\$	<i>By</i>	276.08	
\$	<i>By</i>	367.84	
\$	<i>By</i>	367.84	
\$	<i>By</i>	586.45	
\$	<i>By</i>	168.13	
\$	<i>By</i>	202.67	
\$	<i>By</i>	74.40	
\$	<i>By</i>	50.52	
\$	<i>By</i>	221.81	
\$	<i>By</i>	671.45	

Trans-cab Auto Services Pte Ltd**AAD1906-071**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 40T

31	1	FENDER PANEL REAR LH	\$	N	3,299.13	}	X
32	1	WHEELARCH REAR LH	\$	Sn	543.47		
33	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45		
34	1	FENDER PANEL REAR RH	\$	N	3,299.13		
35	1	WHEELARCH REAR RH	\$	Sn	543.47		
36	1	TAILLAMP RH	\$	Sn	552.55		
37	1	TAILLAMP PANEL RH	\$	N	986.70		
38	1	TAILLAMP LH	\$	Sn	552.55		
39	1	TAILLAMP PANEL LH	\$	N	986.70		
40	1	OUTER PANEL REAR (End Panel)	\$	Sn	1,471.77		
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	Mj 0.1	404.56	}	X
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88		
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21		
44	1	EXHAUST REAR	\$	N	7,489.05		
45	1	EXHAUST CAP REAR	\$	N	230.49		
46	1	FUEL FLAP	\$	Sn	343.57		
47	1	BUMPER COVER FRT	\$	N	1,259.42		
48	1	BUMPER SPOILER FRT	\$	Sn	181.75		
49	1	BUMPER ABSORBER FRT	\$	Sn	394.68		
50	1	BUMPER RETAINER FRT LH	\$	Sn	151.41		
51	1	BUMPER SUPPORT FRT	\$	Sn	123.88		
52	1	BUMPER RETAINER FRT RH	\$	Sn	150.77		
53	1	BUMPER SUPPORT FRT	\$	Sn	123.88		
54	1	BUMPER UNDERTRAY FRT	\$	Sn	472.83		
55	1	BUMPER GRILLE LOWER FRT	\$	Sn	266.80		
56	1	BUMPER FOG LAMP GRILLE LH	\$	Sn	207.21		
57	1	BUMPER FOG LAMP GRILLE RH	\$	Sn	207.21		
58	1	BUMPER BEAM FRT	\$	N	914.08		
59	1	TOW COVER FRT	\$	Sn	28.61		
60	1	RADIATOR GRILLE	\$	Sn	1,707.78		
61	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sn	225.36		
62	1	RADIATOR GRILLE FRAME	\$	Sn	1,353.75		
63	1	FRAME FULL SUPPORT PANEL	\$	Sn	615.90		
64	1	FRAME FULL SUPPORT BRACKET	\$	N	89.79		
65	1	FRONT BRACE PANEL	\$	N	177.22		
66	1	HORN	\$	Sn	314.17		
67	1	HORN BRACKET	\$	N	40.45		
68	1	HEADLAMP LH	\$	Sn	1,184.43		

Trans-cab Auto Services Pte Ltd**AAD1906-071**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 40T

69	1	HEADLAMP RH	\$	Sn	1,184.43	}	X	
70	1	HEADLAMP PANEL FRT LH	\$	N	152.15			
71	1	HEADLAMP PANEL FRT RH	\$	N	152.15			
72	1	BONNET	\$	N	1,941.63			
73	1	BONNET INSULATOR	\$	Sn	405.73			
74	1	BONNET STRUT LH	\$	Sn	88.61			
75	1	BONNET STRUT RH	\$	Sn	88.61			
76	1	BONNET HINGE LH	\$	N	348.31			
77	1	BONNET HINGE RH	\$	N	348.31			
78	1	BONNET LOCK	\$	N	305.48			
79	1	BONNET CABLE	\$	Sn	119.19			
80	1	BONNET CABLE COVER	\$	Sn	161.03			
81	1	BONNET SEAL OUTER	\$	Sn	92.36			
82	1	BONNET SEAL INNER	\$	Sn	157.28			
83	1	FENDER PANEL FRT LH	\$	N	783.83			
84	1	WHEELARCH FRT LH	\$	Sn	278.84			
85	1	FENDER BRACKET LOWER LH	\$	Sn	15.79			
86	1	FENDER INSULATOR LH	\$	Sn	130.84			
87	1	FENDER INSULATOR RH	\$	Sn	130.84			
88	1	FENDER PANEL FRT RH	\$	N	783.83			
89	1	WHEELARCH FRT RH	\$	Sn	278.84			
90	1	FENDER BRACKET LOWER RH	\$	Sn	15.79			
91	1	WIPER RESERVOIR	\$	Sn	348.25			
92	1	WIPER RESERVOIR NECK	\$	Sn	136.11			
93	1	WIPER RESERVOIR MOTOR	\$	Sn	270.06			
94	1	AIR CLEANER LOWER	\$	Sn	271.26			
95	1	AIR CLEANER HOSE	\$	Sn	76.14			
96	1	BASE BATTERY TRAY	\$	Sn	363.40			
97	1	AIR CLEANER BOX	\$	Sn	464.20			
TOTAL			\$		56,297.19			
10%			\$		5,629.72			
			\$		50,667.47			

Special Nett

1	1SET	PARKING AID	\$	Shan	700.00	400.00
2	1SET	REAR BUMPER CLIP	\$	N	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	N	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	N	10.00	X

Trans-cab Auto Services Pte Ltd

AAD1906-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 40T

5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT INNER TRIM CLIP	\$	na	45.00	
13	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
14	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
15	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
16	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	
17	1 TAILLAMP CLIP RH	\$	na	5.00	
18	1 TAILLAMP CLIP LH	\$	na	5.00	
19	2 REAR WINDSCREEN SEALANT	\$	na	80.00	
20	1 WINDSCREEN MOULDING	\$	na	100.00	
21	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
22	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	
23	1 SPARE TYRE	\$	Sn	330.00	
24	1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	
25	1SET BUMPER CLIP FRT	\$	na	66.00	
26	1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
27	1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
28	1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
29	1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
30	1 TOW COVER FRT	\$	na	14.50	
31	1SET RADIATOR GRILLE SCREW	\$	na	16.00	
32	1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
33	1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
34	2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
35	2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
36	1 Windscreen moulding	\$	na	100.00	
37	1 FRONT WINDSCREEN SEALANT	\$	na	253.80	
38	1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
39	1SET Front licence plate with holder	\$	na	80.00	2 as n
40	1 WHEELARCH CLIP FRT LH	\$	na	30.50	X
41	1 WHEELARCH CLIP FRT RH	\$	na	30.50	X
42	2 BONNET STRUT L70Y	\$	na	88.61	X

Trans-cab Auto Services Pte Ltd

AAD1906-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 40T

43	6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	}
44	1	REAR BUMPER ADVERTISEMENT STICKER	\$	nn	300.00	
45	1	REAR BOOT ADVERTISEMENT STICKER	\$	nn	300.00	
46	1	FRONT LH FENDER ADVERTISEMENT STICKER	\$	nn	300.00	
47	1	FRONT RH FENDER ADVERTISEMENT STICKER	\$	nn	300.00	
48	1	REAR RH FENDER ADVERTISEMENT STICKER	\$	nn	300.00	
49	1	REAR LH FENDER ADVERTISEMENT STICKER	\$	nn	300.00	
TOTAL			\$		5,038.23	

TOTAL PARTS \$ 55,705.70**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601

Trans-cab Auto Services Pte Ltd**AAD1906-071**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 40T

To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To Transfer Of Rear Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 340.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	~ 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To Transfer Of Front Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 340.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	~ 180.00	X
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	~ 180.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 180.00	X

Trans-cab Auto Services Pte Ltd**AAD1906-071**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 40T

To transfer of front windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X**TOTAL \$ 17,210.00****Over All Total \$ 72,915.70****Repair Days (PART BY PART)**~~20 DAYS~~*5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: