

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9981D**AAD1906-095***Not Notarised**11 Lmp & ?**Boole Valve ?*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB 9981D

VF1ABL15AUC273530

RENAULT

LATITUDE

10.6.19

AXA

30/9/2013

PART		LIST	
1	DOOR PANEL REAR RH	\$	<i>Rs</i> 2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	<i>Rs</i> 176.82 X
1	DOOR HINGE UPPER RH	\$	<i>Rs</i> 274.50 X
1	DOOR HINGE LOWER RH	\$	<i>Rs</i> 300.55 ✓
1	DOOR CHECK REAR RH	\$	<i>Rs</i> 203.06 X
1	DOOR LOCK REAR RH	\$	908.75 ?
1	DOOR HANDLE OUTER REAR RH	\$	<i>Rs</i> 126.49 X
1	DOOR HANDLE CAP REAR RH	\$	<i>Rs</i> 35.52 X
1	DOOR HANDLE SEAL REAR RH	\$	<i>Rs</i> 7.89 X
1	DOOR HANDLE COVER REAR RH	\$	<i>Rs</i> 13.22 ✓
1	DOOR HANDLE MODULE REAR RH	\$	<i>Rs</i> 133.60 X
1	DOOR REGULATOR REAR RH	\$	<i>Rs</i> 1,135.10 ✓
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>Rs</i> 893.75 —
1	DOOR REGULATOR NUT REAR RH	\$	<i>Rs</i> 12.43 X
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Rs</i> 6.31 X
1	DOOR FINISHER REAR RH	\$	423.10 ?
1	DOOR MOULDING REAR RH	\$	<i>Rs</i> 176.82 X
1	DOOR MOULDING CLIP L70Y	\$	<i>Rs</i> 5.92 X
1	DOOR MOULDING SCREW L70Y	\$	<i>Rs</i> 6.91 X
1	DOOR CASING REAR RH	\$	1,509.06 ?
1	DOOR WATER SHIELD REAR RH	\$	<i>Rs</i> 30.39
1	DOOR CASING CLIP	\$	<i>Rs</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Rs</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>Rs</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>Rs</i> 46.97 X
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>Rs</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>Rs</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>Rs</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>Rs</i> 210.96
1	DOOR BLIND REAR RH	\$	<i>Rs</i> 741.80

Trans-cab Auto Services Pte Ltd**AAD1906-095**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9981D

1	DOOR WHEATHESTRIIP REAR RH	\$	410.66	50 in
1	DOOR SEAL REAR RH	\$	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	115.64	
1	ROCKER PANEL INNER GARNISH RH	\$	466.51	
1	ROCKER PANEL INNER RH	\$	1,024.79	
1	ROCKER PANEL OUTER RH	\$	1,184.99	
1	ROCKER PANEL CENTER RH	\$	990.25	
1	FENDER PANEL REAR RH	\$	3,299.13	
1	FENDER PANEL INNER TRIM REAR RH	\$	671.45	X
1	WHEELARCH REAR RH	\$	543.47	X
1	WHEEL HOUSING PANEL REAR RH	\$	4,682.09	X
1	CHASSIS PANEL REAR RH	\$	3,766.43	X
1	BUMPER COVER REAR	\$	1,108.46	
1	BUMPER LOWER REAR	\$	768.84	X
1	BUMPER BRACKET CTR REAR	\$	113.47	X
1	BUMPER BRACKET SIDE RH REAR	\$	135.97	
1	BUMPER RETAINER RH REAR	\$	44.99	
1	BUMPER REFLECTOR RH	\$	43.61	
1	BUMPER BEAM REAR	\$	777.52	
1	BUMPER BEAM BRACKET RH REAR	\$	225.95	
1	TAILLAMP RH	\$	552.55	
1	TAILLAMP PANEL RH	\$	986.70	
1	EXHAUST REAR	\$	7,489.05	
1	EXHAUST CAP REAR	\$	230.49	
1	KNUCKLE ARM REAR RH L70Y	\$	736.67	
1	BRAKE DISC REAR L70Y	\$	525.91	X
1	WHEEL HUB NUT L70Y	\$	51.11	X
1	WHEEL HUB CAP L70Y	\$	57.82	X
1	ABS SENSOR REAR RH L70Y	\$	255.75	X
1	REAR AXLE L70Y	\$	4,167.03	?
1	AXLE ARM RH L70Y	\$	117.22	?
1	LOWER ARM REAR RH L70Y	\$	905.99	
1	ABSORBER REAR	\$	389.75	?
1	STABILIZER BAR REAR RH	\$	604.65	?
1	BRAKE CALIPER REAR RH	\$	1,300.67	X
1	DOOR PANEL FRT RH	\$	2,844.66	X

Trans-cab Auto Services Pte Ltd

AAD1906-095

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9981D

TOTAL	\$	52,986.64
10%	\$	5,298.66

\$	47,687.98
-----------	------------------

Special Nett

1	REAR DOOR ADVERTISEMENT STICKER	\$	na	300.00	}
1	REAR BUMPER ADVERTISEMENT STICKER	\$	na	300.00	
1	REAR BOOT ADVERTISEMENT STICKER	\$	na	300.00	
1	REAR FENDER ADVERTISEMENT STICKER	\$	na	300.00	
1	FRONT DOOR ADVERTISEMENT STICKER	\$	na	300.00	
1	FENDER INNER TRIM CLIP RH	\$	na	28.00	
1	TAILLAMP CLIP RH	\$	na	5.00	}
1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
2	REAR WINDSCREEN SEALANT	\$	na	80.00	40ea
1	WINDSCREEN MOULDING	\$	na	100.00	—
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	30ea
1	REAR RIGHT TYRE	\$	@ WD	300.00	802ea
1	REAR RIGHT TYRE RIM	\$	na	380.00	—
1SET	PARKING AID	\$	na	700.00	X
1SET	REAR BUMPER CLIP	\$	na	66.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	}
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	
1SET	BUMPER RETAINER CLIP RH RR	\$	na	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	
1	EXHAUST MOUNTING REAR	\$	na	17.82	
1	DOOR CHECK BOLT	\$	na	22.69	}
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	}
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
TOTAL	\$	3,564.45			

TOTAL PARTS	\$	51,252.43
--------------------	-----------	------------------

Trans-cab Auto Services Pte Ltd**AAD1906-095**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9981D**LABOUR**

To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	1001
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	nn X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	380.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	121
Putty and spray painting of the affected portion.	\$	7,500.00	881
To rust-proofing of the affected areas.	\$	170.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	601
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	nn X
To reinstall rear bumper parking sensor.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	nn X

Trans-cab Auto Services Pte Ltd**AAD1906-095**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9981D

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00 X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00 1801
Towing Fees	\$	150.00 501
To transfer of Front door fittings, attachment and perform water seepage test.	\$	na 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00 X
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To remove and replace corporate sticker	\$	na 330.00 X
TOTAL	\$	20,310.00
Over All Total	\$	71,562.43

LUMP SUM (REPAIR DAY)**25 DAYS**

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: