

Surveyor

REF:

CSI/SFF19010374/Ktd332

Special Instruction:

LS \$1970.00

ASSIGNMENT (Office)

From (Person): Harizal Farhan of SFF

Date/Time: 11/6/2019

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: VAC

Workshop: Trans-cab

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SHB 9777C

Insured: G13C 56172

at Workshop m/s Trans-cab

Tel:

of No. 2 Ang Mo Kio Street 63.

Policy No:

Claim No: AEMD 105 009 2016 205

Sum Insured:

Excess:

Make of Veh:

D.O.A. 5/12/2016

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time:

Confirmed with

Final Fig

days (Red \$ / %; Original 3 days)

Date/Time: 11/6/2019

Submit Final Fig

1950/-

02 days

(Red \$ 70 / 1 %; Original 3 days)

Date/Time

Action/Instruction

SHB 9777C - X

SHB 56172 - X

Repair Range \$1000 - \$2000/-

weekend - 0
Repair days - 2
Total: 2 days

Do Not Finalise

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 17 JUN 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

200

1) Date/Time File Pass to

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Tuesday, 11 June 2019 11:50 AM
To: Admin-D (LKKAuto); assignments
Cc: Frankie THAY (SPF); Olivia Lau (LKKAuto)
Subject: Post Survey for SHB9777C
Attachments: VICOM 2016-205.pdf

Our ref: AEMD/105/009/2016/205

Hi,

Kindly do a paper survey on SHB9777C.

Third party claim for cost of repairs is \$2,642.75.

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 / FAX: (65) 6478 4850



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------|
| Date Of Report | 05/12/2016 17:12 |
| Date Of Accident | 05/12/2016 12:00 |
| Exact Location Of Accident | CGH Basement car park |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------------|
| Vehicle Registration Number | SHB9777C |
| Insured/Policyholder | |
| Name Of Registered Owner | TRANS-CAB SERVICES PTE LTD |
| Co Reg No | 200303878K |
| Email Address | claims@transcab.com.sg |
| Mobile Phone No | |
| Alternative Phone No | Office-62876666 |

Vehicle Particulars

| | |
|--|------------------------|
| Manufacturer | RENAULT |
| Model | LATITUDE-2.0 D dCi (A) |
| Exact Purpose for which vehicle was being used at time of accident | Hire and Reward |
| Are you claiming under your own insurance policy for repair to your vehicle? | No |
| If No, Please state action to be taken | Third Party |
| Vehicle Category | Taxi |

Insurance Company

| | |
|---------------------------|---------------------------------|
| Name of Insurance Company | AXA Insurance Singapore Pte Ltd |
| Type Of Coverage | Third Party |
| Fleet Policy | Yes |
| Policy Number | VPX/P1680520 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | HAN CHYN CHOUR |
| NRIC No | S1384481Z |
| Date Of Birth | 22/11/1959 |
| Occupation | Outdoor |
| Date Of Driving Pass | 27/11/1999 |
| Driving Experience | 17 Years And 0 Months |
| Gender | Male |
| Mobile Number | (Local) +65-96328190 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|---------------------------------------|
| Address | BLK 424 TAMPINES STREET 41 #11-192 |
| Postcode | 520424 |
| Was driver an employee of the Insured's Company | No |
| If No, Relationship of the Driver with the Insured | Other - Hirer |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-----------------------|
| Type Of Accident | Damaged whilst parked |
| Weather Conditions | Clear |
| Road Surface | Dry |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | No |
| Was any body injured in the Accident? | No |
| Was any other material or property damaged? | Yes |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | No |
| Number of Passengers (Including Driver) | 0 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | No |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | No |
| If Yes, against whom? | |

Circumstances of Accident

On 05.12.2016 at about 1200hrs, I park my taxi at Changi General Hospital Basemen 2 car park. When I return to my taxi, I notice a damaged on the rear portion and there's a letter with the name and contact number of Mr CHEONG BENEDICT. I did try to call him and he inform me that he hit onto my park taxi.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-----------------|
| Vehicle Registration Number | GBC5617Z |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Name of Driver | CHEONG BENEDICT |
| NRIC/Passport Number | |
| Contact Number | 9325 3572 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Details of Witness

| | |
|---------------|--|
| Name | |
| Phone Number | |
| Email Address | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Handwritten sketch of a vehicle accident scene. It shows a car labeled 'HIL' (likely a Hilux) in the center, with arrows indicating movement or impact. The sketch is drawn on a grid background.

Describe Circumstances of the Accident

PLS REFER TO GLA REPORT

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

SPF ACCIDENT CLAIMS SECTION
Automotive Engg & Mgmt Div
Police Logistics Department
No.1 Mount Pleasant Road
BLK 8 Old Police Academy -S(298333)



VICOM LTD
395 Sin Ming Drive Singapore 575718

Mobile: 655 6458 4565
Facsimile: 655 6458 1040

www.vicom.com.sg
Company Registration No: 197000000

SURVEY REPORT

| GENERAL INFORMATION | | | |
|---------------------|--------------|---------------|------------------------|
| VAC Ref. No. | : 500991 | Claim No. | : AEMD/105/009/2016/GB |
| Accident Date | : 05/12/2016 | Claim Type | : THIRD PARTY |
| Assignment Date | : 20/12/2016 | Policy No. | : |
| Survey Date | : 20/12/2016 | Finalised Dt. | : 31/03/2017 |
| Survey Report Date | : 26/05/2017 | | |

| VEHICLE PARTICULARS | | | |
|---------------------|--------------|--------------|---------------------|
| Vehicle No. | : SHB9777C | Chassis No. | : VF1ABL15AUC273101 |
| Registration Date | : 31/07/2013 | Engine No. | : M9R8839C000255 |
| Make | : RENAULT | Engine Cap. | : 1995 CC |
| Model | : LATITUDE | Transmission | : AUTOMATIC |
| | | Colour | : RED/WHITE |

| CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY) | | | |
|--|---------------|--------------|---------------|
| Foot Brake | : SERVICEABLE | Steering | : SERVICEABLE |
| Hand Brake | : SERVICEABLE | Modification | : NONE |
| Mileage | : 435007KM | | |

| TYRES | SIZE | MAKE | BALANCE (mm) |
|----------|------------|-----------|--------------|
| FRONT RH | 215/60 R15 | LING LONG | 8 |
| FRONT LH | 215/60 R15 | LING LONG | 8 |
| REAR RH | 215/60 R15 | LING LONG | 7 |
| REAR LH | 215/60 R15 | LING LONG | 7 |

| SURVEY CONDUCTED AT | |
|---|--|
| TRANS-CAB AUTO SERVICES PTE LTD No2 Ang Mo Kio Street 63 Singapore 569111 | |

| REMARKS |
|--|
| [1]Workshop Estimate : S\$ 22,386.17 |
| [2]Our Adjustment : S\$ 1,970.00 |
| [3]Repair Period : 03 days |
| [4]We have not authorised repairs. This survey was carried out on without prejudice basis. |

SURVEY REPORT

Annex A: Adjustment on Spare Parts

| # | Qty | Vehicle Parts Description | Condition | Workshop Estimate (S\$) | VAC Adjustment (S\$) |
|-----------|-----|-----------------------------------|-------------------|-------------------------|----------------------|
| 1 | 1 | Bumper Cover Rear | Deformed | 852.66 | 852.66 |
| 2 | 1 | Bumper Lower Rear | Garzed | 591.41 | 591.41 |
| 3 | 1 | Bumper Bracket Ctr Rear | Reuse | 87.29 | 0.00 |
| 4 | 1 | Bumper Retainer Rh Rear | Reuse | 34.61 | 0.00 |
| 5 | 1 | Bumper Retainer Lh Rear | Reuse | 34.61 | 0.00 |
| 6 | 1 | Bumper Reflector Rh | Reuse | 33.55 | 0.00 |
| 7 | 1 | Bumper Reflector Lh | Cracked | 33.55 | 33.55 |
| 8 | 1 | Bumper Beam Rear | Reuse | 598.09 | 0.00 |
| 9 | 1 | Bumper Beam Bracket Lh Rear | Reuse | 173.81 | 0.00 |
| 10 | 1 | Bumper Beam Bracket Rh Rear | Reuse | 173.81 | 0.00 |
| 11 | 1 | Boot Rear | No Visible Damage | 2209.75 | 0.00 |
| 12 | 1 | Boot Finisher Moulding | Reuse | 429.90 | 0.00 |
| 13 | 1 | Boot Weatherstrip | Reuse | 248.50 | 0.00 |
| 14 | 1 | Boot Reflector Lamp Rh | Reuse | 379.50 | 0.00 |
| 15 | 1 | Boot Reflector Lamp Lh | Reuse | 379.50 | 0.00 |
| 16 | 1 | Boot Badge 'Renault' | Reuse | 173.35 | 0.00 |
| 17 | 1 | Boot Badge | Reuse | 173.35 | 0.00 |
| 18 | 1 | Taillamp Rh | Reuse | 425.04 | 0.00 |
| 19 | 1 | Taillamp Lh | Reuse | 425.04 | 0.00 |
| 20 | 1 | Outer Panel Rear (End Panel) | No Visible Damage | 1132.13 | 0.00 |
| 21 | 1 | Outer Panel Rear (End Panel) Trim | Reuse | 311.20 | 0.00 |
| 22 | 1 | Exhaust Rear | Reuse | 5760.00 | 0.00 |
| 23 | 1 | Exhaust Cap Rear | Reuse | 177.30 | 0.00 |
| | | | Subtotal | : 14837.95 | 1477.62 |
| Less 10 % | | | | 1483.80 | 147.76 |
| | | | TOTAL | : 13354.15 | 1329.86 |

SPECIAL NETT ITEM

| | | | | | |
|----|---|------------------------------------|---------------|--------|--------|
| 1 | 1 | Parking Aid | Malfunctioned | 600.00 | 300.00 |
| 2 | 1 | Rear Bumper Clip | Cracked | 66.00 | 20.00 |
| 3 | 1 | Bumper Bracket Ctr Clip | Reuse | 33.00 | 0.00 |
| 4 | 1 | Bumper Retainer Rh Clip Rr | Reuse | 20.00 | 0.00 |
| 5 | 1 | Bumper Retainer Lh Clip Rr | Reuse | 20.00 | 0.00 |
| 6 | 1 | Bumper Lower Rear Clip | Reuse | 66.00 | 0.00 |
| 7 | 1 | Exhaust Mounting Rear | Reuse | 17.82 | 0.00 |
| 8 | 1 | Boot Finisher Clip | Reuse | 24.20 | 0.00 |
| 9 | 1 | Bootsticker 'Trans-Cab' | Not Necessary | 30.00 | 0.00 |
| 10 | 1 | Bootsticker '6555-3333' | Not Necessary | 30.00 | 0.00 |
| 11 | 1 | Boot Inner Trim Clip | Reuse | 45.00 | 0.00 |
| 12 | 1 | Fender Advertisement Sticker Rr Lh | Necessary | 300.00 | 150.00 |
| 13 | 1 | Fender Advertisement Stickerr Rh | Necessary | 300.00 | 150.00 |

| | | | | | |
|--------------|---|------------------------------|---------------|----------------|---------------|
| 14 | 1 | Boot Advertisement Sticker | Not Necessary | 300.00 | 0.00 |
| 15 | 1 | Bumper Advertisement Sticker | Necessary | 200.00 | 100.00 |
| TOTAL | | | | 2052.02 | 720.00 |

TOTAL FOR SPARE PARTS : 15406.17 2049.86

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

| # | Job Description | Workshop Estimate (S\$) | VAC Adjustment (S\$) |
|--|---|-------------------------|----------------------|
| 1 | Putty and spray painting of the affected portion | 3000.00 | 200.00 |
| 2 | Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | 2800.00 | 200.00 |
| 3 | To remove and replace corporate sticker | 330.00 | 0.00 |
| 4 | To rust-proofing of the affected area | 170.00 | 0.00 |
| 5 | To reinstall rear bumper parking sensor | 170.00 | 20.00 |
| 6 | To transfer of bootlid fittings, attachments and perform water seepage test | 170.00 | 0.00 |
| 7 | To drop rear exhaust box, renew the same, to repair and realign center exhaust pipe | 170.00 | 0.00 |
| 8 | To transfer of rear end panel fittings, attachment and perform water seepage test | 170.00 | 0.00 |
| TOTAL FOR LABOUR AND SPRAY PAINTING | | 6980.00 | 420.00 |

Summary

| Description | Workshop Estimate (S\$) | VAC Adjustment (S\$) |
|--|-------------------------|----------------------|
| TOTAL FOR SPARE PARTS | 15406.17 | 2049.86 |
| TOTAL FOR LABOUR AND SPRAY PAINTING | 6980.00 | 420.00 |
| TOTAL REPAIR COST | 22386.17 | 2469.86 |

VICOM LTD**SURVEY REPORT****Annex C: Conclusion****ASSESSOR'S REPORT**

At the place of inspection, we saw this vehicle sustained rear portion damage.

The damages seen during our survey were rear bumper assy and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Trans-Cab Auto Services Pte Ltd estimated a repair cost of S\$22,386.17. We adjusted it to S\$2,469.86.

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$1,970.00.

The repairs would require a period of 03 working days.



Tommie Lim
for VICOM Ltd



Your Ref: AEMD/105/009/2016/205

Date: 27th June 2019

Our Ref: CS1/SPF19010394/Ktd3s2

M/s Automotive Engineering & MGT Division
Accident Claim Section (Singapore Police Force)
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333

Attn: Hafizul Farhan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SHB 9777C INSURED VEHICLE: GBC 5617Z ACCIDENT DATE: 05/12/2016**

We thank you for your instruction on 11/06/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHB 9777C from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SHB 9777C.
- c) Colour damaged vehicle photographs of SHB 9777C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|---------------------|
| Registration Number | : SHB 9777C |
| Make & Model | : Renault Latitude |
| Year of Registration | : 2013 |
| Chassis Number | : VF1ABL15AUC273101 |
| Engine Capacity | : 1995 cc |

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9777C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-----------------------------------|-------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | BUMPER COVER REAR | DEFORMED | 852.66 | 852.66 |
| 1 | BUMPER LOWER REAR | GRAZED | 591.41 | 591.41 |
| 1 | BUMPER BRACKET CTR REAR | REUSE | 87.29 | - |
| 1 | BUMPER RETAINER RH REAR | REUSE | 34.61 | - |
| 1 | BUMPER RETANER LH REAR | REUSE | 34.61 | - |
| 1 | BUMPER REFLECTOR RH | REUSE | 33.55 | - |
| 1 | BUMPER REFLECTOR LH | CRACKED | 33.55 | 33.55 |
| 1 | BUMPER BEAM REAR | REUSE | 598.09 | - |
| 1 | BUMPER BEAM BRACKET LH REAR | REUSE | 173.81 | - |
| 1 | BUMPER BEAM BRACKET RH REAR | REUSE | 173.81 | - |
| 1 | BOOT REAR | NO VISIBLE DAMAGE | 2,209.75 | - |
| 1 | BOOT FINISHER MOULDING | REUSE | 429.90 | - |
| 1 | BOOT WEATHERSTRIP | REUSE | 248.50 | - |
| 1 | BOOT REFLECTOR LAMP RH | REUSE | 379.50 | - |
| 1 | BOOT REFLECTOR LAMP LH | REUSE | 379.50 | - |
| 1 | BOOT BADGE 'RENAULT' | REUSE | 173.35 | - |
| 1 | BOOT BADGE | REUSE | 173.35 | - |
| 1 | TAILLAMP RH | REUSE | 425.04 | - |
| 1 | TAILLAMP LH | REUSE | 425.04 | - |
| 1 | OUTER PANEL REAR (END PANEL) | NO VISIBLE DAMAGE | 1,132.13 | - |
| 1 | OUTER PANEL REAR (END PANEL) TRIM | REUSE | 311.20 | - |
| 1 | EXHAUST REAR | REUSE | 5,760.00 | - |
| 1 | EXHAUST CAP REAR | REUSE | 177.30 | - |
| | LESS 10% DISCOUNT | | -1,483.80 | -147.77 |
| | | | 13,354.15 | 1,329.85 |
| SPECIAL NETT ITEMS | | | | |
| 1 | PARKING AID (SN) | MALFUNCTIONED | 600.00 | 300.00 |
| 1 | REAR BUMPER CLIP (SN) | CRACKED | 66.00 | 20.00 |
| 1 | BUMPER BRACKET CTR CLIP (SN) | REUSE | 33.00 | - |
| 1 | BUMPER RETAINER RH CLIP RR (SN) | REUSE | 20.00 | - |
| 1 | BUMPER RETAINER LH CLIP RR (SN) | REUSE | 20.00 | - |
| 1 | BUMPER LOWER REAR CLIP (SN) | REUSE | 66.00 | - |

Report Ref No. CS1/SPF19010394/Ktd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| 1 | EXHAUST MOUNTING REAR (SN) | REUSE | 17.82 | - |
| 1 | BOOT FINISHER CLIP (SN) | REUSE | 24.20 | - |
| 1 | BOOTSTICKER 'TRANS-CAB' (SN) | NOT NECESSARY | 30.00 | - |
| 1 | BOOTSTICKER '6555-3333' (SN) | NOT NECESSARY | 30.00 | - |
| 1 | BOOT INNER TRIM CLIP (SN) | REUSE | 45.00 | - |
| 1 | FENDER ADVERTISEMENT STCKER RR LH (SN) | NECESSARY | 300.00 | 150.00 |
| 1 | FENDER ADVERTISEMENT STCKER RR RH (SN) | NECESSARY | 300.00 | 150.00 |
| 1 | BOOT ADVERTISEMENT STCKER (SN) | NOT NECESSARY | 300.00 | - |
| 1 | BUMPER ADVERTISEMENT STCKER (SN) | NECESSARY | 200.00 | 100.00 |
| | | | 2,052.02 | 720.00 |
| | LABOUR | | | |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 3,000.00 | 200.00 |
| | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. | | 2,800.00 | 200.00 |
| | TO REMOVE AND REPLACE CORPORATE STICKER. | NOT NECESSARY | 330.00 | - |
| | TO RUST-PROOFING OF THE AFFECTED AREA. | NOT NECESSARY | 170.00 | - |
| | TO REINSTALL REAR BUMPER PARKING SENSOR. | | 170.00 | 20.00 |
| | TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTER EXHAUST PIPE. | NOT NECESSARY | 170.00 | - |
| | TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | | | 6,980.00 | 420.00 |
| | GRAND TOTAL | | 22,386.17 | 2,469.85 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,950.00 |

Report Ref No. CS1/SPF19010394/Ktd3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 - \$2,000.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.