

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

11-Jun-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6084 H

1 pc	Rear bumper	✓	\$	696.00
1 pc	Rear bumper lower cover	X	\$	206.00
2 pcs	Rear bumper side bracket o/s @ \$29.00	X	\$	29.00
1 pc	Rear bumper o/s reflector	✓	\$	46.00
1 pc	Rear o/s wheel cover	X repair	\$	116.00
1 pc	Rear bumper reflector o/s @ \$46.00	X	\$	46.00
	<i>rear o/s fender X repair</i>		\$	1,139.00
	Less 10%		\$	113.90
			\$	1,025.10

S/NETT

1 set	Rear bumper clips	✓	\$	48.00
1 pc	Rear o/s fender sticker	✓	\$	60.00

Sundry	\$	50.00 20
To send and check for rear o/s wheel alignment	\$	80.00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, etc	\$	400.00 200
To putty and spray painting on rear bumper, rear o/s fender, rear o/s wheel cover	\$	600.00 410
To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
	\$	2,563.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

- Parts and labour charges are subject to change.
- Third party survey is on a 24 hrs basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be approved and is subject to final approval from insurance company.

Acknowledged by Repairer
Signature:
Date:

Kahli 11/6/19

12/6/19 17.56

2 Rs

US

After Repair, US