

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0722/2019/NK
Date : 06-Jun-19 ✓

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lam Pek Ying
Address : 3 Psir Ris View
Singapore 518586
Telephone : HP +65 91899940
Type of Claim : Own Damage Claims
Policy No. : 2100468761-03
Vehicle No : **SLC 8775 L** ✓
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : 27-05-2016
Engine No : CZC540605
Chassis No : WAUZZZ8V5G1089776
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 02-Jun-19
Place of Accident : 414 Pasir Ris (MSC)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLC 8775 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,400.00 750	
3	To respray front bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,852.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 8775 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>del</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING SETS <i>new</i>	\$ 170.00	X
3	FRONT COVER TRIM RH <i>new</i>	\$ 148.00	X
4	CLOSING ELEMENTS CNETRE LOWER <i>new</i>	\$ 148.00	X
5	FRONT BUMPER PULL STRAP LOWER <i>3 holes</i>	\$ 187.00	X
6	FRONT BUMPER GUIDE SECTION RH	\$ 35.00	X
7	AIR GUIDE GRILLE - BLACK RH <i>at</i>	\$ 99.00	✓
8	RADIATOR GRILLE <i>at</i>	\$ 637.00	✓
9	RADIATOR GRILLE COVER <i>new ?</i>	\$ 89.00	?
10	FRONT REINFORCEMENT <i>new</i>	\$ 660.00	X
11	FOAM PIECE <i>new</i>	\$ 125.00	X
12	REINFORCEMENT COVER <i>new</i>	\$ 51.00	X
13	SIGN " CAUTION " <i>3 new</i>	\$ 13.00	X
14	AIR CONDITIONER STICKER	\$ 7.00	✓
15	SIGNAL HORN <i>new</i>	\$ 182.00	X
16	HEADLIGHT RH <i>at</i>	\$ 1,825.00	✓
17	LIFT CYLINDER RH <i>?</i>	\$ 181.00	?
18	RADIATOR AIR GUIDE RH <i>new</i>	\$ 22.00	X
19	RADIATOR AIR GUIDE UPPER CENTRE <i>new</i>	\$ 11.00	X
20	RADIATOR SEAL <i>the new</i>	\$ 8.00	X
SUB SPARE PARTS		\$ 6,428.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 8775 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT NO PLATE <i>Bent.</i>	S/N \$ 40.00 ✓	
22	SUNDRIES ?	\$ 300.00 ?	
TOTAL SPARE PARTS		: \$ 6,768.00	
TOTAL LABOUR CHARGES		\$ 2,852.00	
GRAND TOTAL		\$ 9,620.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *12/06/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorised Repairs, 03 Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant