

TRANS-CAB AUTO SERVICES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO 6287 6666 FAX NO 6366 8862

CO/GST REG NO 201019626G

SHD 5702J - AXA

ROEL

14h2

Not Authenticated

Book Value??

Proposed L1 Sing \$ 26,000

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 5702J - ROEL

JTDGJ20W205002783*

TOYOTA

WISH 2.0 BI-FUEL

24.01.2014

AXA

PART

LIST

1	1	Front Bumper	\$	585.36	✓
2	1	Front Bumper Lower Absorber	\$	130.00	✓
3	1	Front Bumper Reinforcement	\$	318.11	✓
4	1	Front Bumper Side Support LH	\$	76.20	✓
5	1	Front Bumper Side Support RH	\$	76.20	✓
6	1	Front Bumper Retainer RH	\$	102.00	✓
7	1	Front Bumper Retainer LH	\$	102.00	✓
8	1	Front Bumper Bracket RH	\$	108.00	✓
9	1	Front Bumper Bracket LH	\$	108.00	✓
10	1	Front Bumper Centre Grille	\$	139.92	✓
11	1	Front Bumper Lower Grille	\$	129.36	✓
12	1	Front Bumper Fog Lamp RH	\$	208.00	✓
13	1	Front Bumper Fog Lamp Outer Chrome RH	\$	190.00	✓
14	1	Front Bumper Fog Lamp Grille RH	\$	150.00	✓
15	1	Front Bumper Fog Lamp LH	\$	208.00	✓
16	1	Front Bumper Fog Lamp Outer Chrome LH	\$	190.00	✓
17	1	Front Bumper Fog Lamp Grille LH	\$	150.00	✓
18	1	Front Bumper Fog Lamp Protector Grille	\$	100.00	✓
19	1	Front Headlamp RH	\$	672.00	✓
20	1	Headlamp RH inner panel	\$	732.00	✓
21	1	Front Headlamp LH	\$	672.00	✓
22	1	Headlamp LH inner panel	\$	732.00	✓
23	1	Front Support Panel Assy	\$	1,222.32	✓
24	1	Front Brace Panel	\$	95.49	✓
25	1	Horn unit	\$	125.00	✓
26	1	Horn high pitch / low pitch	\$	150.00	✓
27	1	Bonnet	\$	1,019.16	✓
28	1	Bonnet Under Weatherstrip Seal	\$	71.99	✓
29	1	Bonnet Hinge RH	\$	81.60	✓
30	1	Bonnet Hinge LH	\$	81.60	✓
31	1	Bonnet Moulding	\$	194.36	✓
32	1	Bonnet Lock	\$	90.02	✓
33	1	Bonnet Centre TOYOTA Logo Badge	\$	115.44	✓

TRANS-CAB AUTO SERVICES PTE LTD

ROEL

NO 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO 201019626G

SHD 5702J - AXA

34	1	Bonnet Insulator	\$	524.06	✓
35	1	Bonnet Damper Stay	\$	239.05	✓
36	1	Front Fender RH	\$	837.60	✓
37	1	Front Fender Liner RH	\$	369.14	✓
38	1	Front Fender Indicator Lamp RH	\$	95.80	✓
39	1	Front Fender Inner Wheel House Panel RH	\$	714.86	X
40	1	Front Fender LH	\$	369.14	✓
41	1	Front Fender Liner LH	\$	369.14	✓
42	1	Front Fender Indicator Lamp LH	\$	95.80	✓
43	1	Front Fender Inner Wheel House Panel LH	\$	714.86	✓
44	1	Room View Mirror	\$	200.04	✓
45	1	Front Windscreen	\$	1,406.64	✓
46	1	Front Windscreen Moulding	\$	86.40	✓
47	1	Radiator Assembly	\$	2,268.24	✓
48	1	Radiator Grille	\$	462.48	✓
49	1	Radiator Fan Blade	\$	223.95	✓
50	1	Aircon Fan Blade	\$	223.95	✓
51	1	Radiator Cowling	\$	221.73	✓
52	1	Radiator Fan Motor	\$	372.76	✓
53	1	Aircon Fan Motor	\$	372.76	✓
54	1	Radiator Expansion Tank	\$	180.76	✓
55	1	Radiator Y - Pipe	\$	98.50	X
56	1	Aircon Condenser	\$	1,375.50	✓
57	1	Aircon hose - condenser to compressor	\$	389.51	✓
58	1	Aircon hose - compressor to evaporator	\$	521.93	X
59	1	Aircon hose - condenser to evaporator	\$	216.00	X
60	1	Aircon compressor - pump	\$	3,200.00	X
61	1	Aircon compressor bracket	\$	120.76	✓
62	1	Windscreen Washer Tank - Filler Neck	\$	166.00	✓
63	1	Windscreen Washer Tank	\$	266.86	✓
64	1	Windscreen Washer Tank Motor	\$	1,554.00	✓
65	1	Front Door RH	\$	88.44	✓
66	1	Fuse Box Top (Cover)	\$	84.24	✓
67	1	Fuse Box Lower	\$	254.04	✓
68	1	Fuse Box Centre	\$	238.32	X
69	1	Fuse Box Centre Cover	\$	250.60	✓
70	1	Engine Cover (Top)	\$	1,500.08	✓
71	1	Intake Manifold	\$	1,036.44	X
72	1	Air Cleaner Assembly	\$	101.57	✓
73	1	Air-Cleaner Intake Duct	\$	199.42	✓
74	1	Air-cleaner intake hose	\$	558.00	X
75	1	Front shock absorber assy LH	\$		

TRANS-CAB AUTO SERVICES PTE LTD

ROEL

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 5702J - AXA

76	1	Front shock absorber top mounting LH	\$	Sn	159.16	X
77	1	Front shock absorber assy RH	\$	Sn	558.00	X
78	1	Front shock absorber top mounting RH	\$	Sn	159.16	X
79	1	Front lower arm RH	\$	Sn	620.57	X
80	1	Front lower arm LH	\$	Sn	620.57	X
81	1	Front knuckle arm RH	\$	Sn	490.74	X
82	1	Front knuckle arm LH	\$	Sn	490.74	X
83	1	Steering rack & pinion assy	\$	R	3,167.33	X
84	1	Steering rack end	\$	Sn	246.50	X
85	1	Steering rack & pinion bushing	\$	Sn	30.00	X
86	1	Bracket-strg rack no 1 (s10/12)	\$	Sn	55.14	X
87	1	Bracket-strg rack no 2 (s10/12)	\$	Sn	37.42	X
88	1	Steering tie-rod end	\$	Sn	127.44	X
89	1	Steering wheel air bag	\$	Sn	2,480.52	X
90	1	Steering Wheel air bag sensor	\$	Sn	522.72	X
91	1	Steering Wheel air bag control unit	\$	Sn	522.60	X
92	1	Power steering pump	\$	Sn	5,664.96	X
93	1	Power steering belt	\$	Sn	251.33	X
94	1	Power steering reservoir tank	\$	Sn	394.62	X
95	1	Power steering inlet / outlet pipe	\$	Sn	518.04	X
96	1	Power steering pump pulley	\$	Sn	235.68	X
97	1	Power steering hose - pressure	\$	Sn	361.68	X
98	1	Power steering hose - non pressure	\$	Sn	494.28	X
99	1	Front chassis member/frame	\$	Sn	1,550.70	X
100	1	Dash Board	\$	Sn	869.76	X
101	1	Dash Board air bag	\$	Sn	3,342.72	X
102	1	Dash Board air bag sensor	\$	Sn	323.76	X
103	1	Dash Board air bag control unit	\$	Sn	654.96	X
104	1	Engine splash cover RH	\$	Sn	178.20	X
105	1	Engine splash cover LH	\$	Sn	178.20	X
106	1	ECU assy	\$	Sn	4,584.24	X
107	1	ABS pump	\$	Sn	5,679.60	X
108	1	ABS pump pipe	\$	Sn	82.08	X
109	1	Alternator assembly	\$	R	2,657.64	X
110	1	Gear box cross member	\$	Sn	1,454.28	X
111	1	Gear box cross member Center	\$	Sn	539.76	X
112	1	Gear box mountingRR	\$	Sn	349.68	X
113	1	Gear box mounting FRT	\$	Sn	189.60	X
114	1	Engine mounting side LH	\$	Sn	209.58	X
115	1	Engine mounting RH	\$	Sn	254.28	X
116	1	Front Seat Belt RH	\$	Sn	862.20	X
117	1	Front safety belt cover garnish RH	\$	Sn	253.68	X

TRANS-CAB AUTO SERVICES PTE LTD

ROEL

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 5702J - AXA

118	1	Front Seat Belt tension RH	\$
119	1	Front Seat Belt LH	\$
120	1	Front safety belt cover garnish LH	\$
121	1	Front Seat Belt tension LH	\$
122	1	Battery	\$
123	1	Battery tray	\$
124	1	Battery fastener bracket	\$

Sn	126.01	X
Ta	862.20	—
Da	253.68	—
Sn	126.01	X
Da	240.00	120.00
Da	63.48	—
R	37.26	X

TOTAL	\$	75,828.26
25%	\$	18,957.07
	\$	56,871.19

Specical Nett

1 Set	Front Bumper Fastener Clip	\$
1	CNG Sticker	\$
1 Set	Front Fender Liner Clip LH	\$
1 Set	Front Fender Liner Clip RH	\$
2	Bonnet Stopper	\$
1 Set	Bonnet Under Weatherstrip Seal Clips	\$
1 Set	Bonnet Insulator Clip	\$
1 Set	Bonnet Damper Stay Clip	\$
1 Set	Horn High pitch / Low Pitch	\$
1 Set	Front Wiper Garnish / Wiper Grille Clips	\$
1 Set	Front Wiper Clip	\$
1 Set	Radiator Grille Clip	\$
2 Can	Radiator Coolant	\$
2	Radiator Top Bracket Mounting	\$
2	Radiator Lower Mounting Bushing	\$
1	Front Licence Plate	\$
1	Front Door Sticker 'Trans-Cab'	\$
1	Front Side Rocker Panel Garnish Clips	\$
1	Front Windscreen Sealant	\$
1	Front Windscreen Inner Sponge Seal	\$
1	Roof Lining Clips	\$
1	Front ERP Bracket	\$
1	Front ERP Unit	\$
2	ERP Sticker	\$
1	Battery	\$
1	Air Filter	\$
1 Set	Engine splash cover clip RH	\$
1 Set	Engine splash cover clip LH	\$

Da	40.00	—
Da	15.00	—
Da	30.00	—
Da	30.00	—
Da	9.60	—
Da	21.60	—
Da	42.00	—
Da	10.00	X
Da	100.00	X
Da	18.50	—
Da	10.68	—
Da	18.00	—
Da	40.00	20.00
Da	33.84	—
Sn	18.43	X
Da	50.00	15.00
Da	60.00	X
Da	18.00	X
Da	80.00	40.00
Da	60.00	30.00
Da	25.00	X
Da	50.00	X
Da	200.00	X
Da	10.00	—
Da	240.00	X
Sn	36.00	X
Da	12.00	X
Da	12.00	X

TRANS-CAB AUTO SERVICES PTE LTD

ROEL

NO 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO. 6287 6666 FAX NO 6366 8862

CO/GST REG NO. 201019626G

SHD 5702J - AXA

1	Front Fender Advertisement Sticker LH	\$	250.00	250.00
1	Front Fender Advertisement Sticker RH	\$	250.00	250.00

TOTAL \$ 1,790.65

TOTAL PARTS \$ 58,661.85

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	8,400.00	2400
To Check Electrical Lighting Concerned.	\$	100.00	300
To Rust-Proofing Of The Affected Areas.	\$	200.00	180
Putty And Spray Painting Of The Affected Portion.	\$	8,100.00	1400
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other. To Enable Repair.	\$	350.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	2500
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	2000
To remove and renew engine and gear box mounting.	\$	380.00	3000
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	
To lift-up engine with gear box and refit.	\$	440.00	
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO 6287 6666 FAX NO 6366 8862

CO/GST REG NO 201019626G

SHD 5702J - AXA

To check ABS brake efficiency, final checking and testing.	\$	380.00	380
To remove and refit ABS pump relay to enable repair.	\$	380.00	380
To remove and refit air bag system and reset.	\$	480.00	480
To Remove And Replace Corporate Sticker	\$	150.00	60
Towing Fees.	\$	100.00	50
To Check Steering Geometry And Computer Wheel Alignment.	\$	200.00	60
To Transfer Of Tire, Rim And On Wheel Balancing.	\$	150.00	X
To Vacuum, Replace, Refix And Recharge Air Condenser	\$	350.00	100
To Replace, Refix And Top Up Coolant For Radiator	\$	150.00	50
To Dismantle And Refit Aircon Assy And Attachment, Vacuum And Charge-In-Gas.	\$	350.00	X
To remove and replace corporate sticker	\$	330.00	X
To Remove, Replace And Refit Front W/ Screen Glass To Facilitate Bodywork Repair.	\$	150.00	120

TOTAL \$ 22,720.00**Over All Total \$ 81,381.84****Total Repair Days****30 DAYS**

18 days